



EXAMPLES OF DEGRADATION OF JACK ARCH BEAMS DUE TO WATER INGRESS FROM PARK LEVEL ABOVE - Please see Structural engineers report for description of required remedial works.

NOTE:  
REFER TO PLOWMAN CRAVEN SURVEY DRAWINGS:  
1.5532-013E-03 - North Elevation of Listed Arches

FOR DETAIL OF ARCHES REFER TO:  
KMH HERITAGE STATEMENT & ALAN BAXTER CONDITION SURVEY



Do not scale this drawing  
Do not derive dimensions from digital media

Rev	Date	Revision Notes	Drawn by	Checked	Rev	Date	Revision Notes	Drawn by	Checked	Rev	Date	Revision Notes	Drawn by	Checked	Drawing status:	Job No:	Drawing No:	Rev:
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	PLANNING FOR APPROVAL	3465	BGY-FBA-00-XX-DR-A-00_10-7D03	P1
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	Job Title:	© Drawing & Design Copyright of:		
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	The Goodsyards	FAULKNERBROWNS ARCHITECTS		
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	Drawing Title:	PLOT 7D - EXISTING SECTIONS SHEET 3		
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	Date:	Scale:	Drawn By:	Checked By:
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	April 19	1:50@A1	JK	TL