



REMEDIAL ACTION REQUIRED TO HALT DEGRADATION OF JACK ARCH AND VAULT STRUCTURE DUE TO WATER INGRESS - Please see Structural Engineers information for description of works.

NOTE:
REFER TO PLOWMAN CRAVEN SURVEY DRAWINGS:
15532-010T-01 (A) - 3D Street Survey
15532-010T-02 (B) - 3D Site Topo
15532-010T-03 (A) - Boundary Drawing
15532-010W-02 (A) - Railway Cutting
15532-013E-03 - North Elevation of Listed Arches
15532-013E-08 - South Elevation of London Road
15532-013T-01 (B) - Planimetric Survey
W15532-010SM - 3D Arch Survey

FOR DETAIL OF ARCHES REFER TO:
KMH HERITAGE STATEMENT & ALAN BAXTER CONDITION SURVEY
0m 0.5 1 2 3 4 5m
Do not scale this drawing
Do not derive dimensions from digital media

Rev	Date	Revision Notes	Drawn by	Checked	Rev	Date	Revision Notes	Drawn by	Checked	Rev	Date	Revision Notes	Drawn by	Checked	Drawing Status:	Job No:	Drawing No:	Rev:
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	PLANNING	3465	BGY-FBA-07-XX-DR-A-00_10-7C03	P1
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	FOR LISTED BUILDING CONSENT	—	—	—
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	Job Title:	—	—	—
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	The Goodyard	—	—	—
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	Drawing Title:	—	—	—
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	PLOT 7C - EXISTING SECTIONS	—	—	—
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	SHEET 3	—	—	—
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	Date:	Scale:	Drawn By:	Checked By:
—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	April 19	1:50@A1	JK	TL