
Appendix 18.1

Drawings of the Baseline Condition and Development Scenario

4th Floor, Holborn Tower
137-144 High Holborn
London WC1V 6PL
T: +44(0)20 7148 6290
E: info@eb7.co.uk
W: eb7.co.uk



Key:

Existing

Proposed

NORTH

Sources of information

See Sources of Information in Appendix 1

Project	Stag Brewery SW14 7ET London		
Title	Existing Condition Plan View		
Drawn	AD	Checked	--
Date	09/04/2020	Project	2201
Rel no.	15	Prefix	DS01
Page no.	01		

eb7 © copyright 2020

4th Floor, Holborn Tower
137-144 High Holborn
London WC1V 6PL
T: +44(0)20 7148 6290
E: info@eb7.co.uk
W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1



Key:

Existing

Proposed

Notes:
All heights and dimensions are in AOD

Project	Stag Brewery SW14 7ET London
Title	Existing Condition 3D View

Drawn	AD	Checked	--
Date	09/04/2020	Project	2201
Rel no.	15	Prefix	DS01
Page no.	02		

eb7 © copyright 2020

4th Floor, Holborn Tower
137-144 High Holborn
London WC1V 6PL
T: +44(0)20 7148 6290
E: info@eb7.co.uk
W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1




Key:

- Existing
- Proposed

NORTH

Project	Stag Brewery SW14 7ET London		
Title	Proposed Development Plan View		
Drawn	AD	Checked	--
Date	09/04/2020	Project	2201
Rel no.	15	Prefix	DS01
Page no.	03		

eb7 © copyright 2020



4th Floor, Holborn Tower
137-144 High Holborn
London WC1V 6PL
T: +44(0)20 7148 6290
E: info@eb7.co.uk
W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

Key:

- Existing
- Proposed


Notes:
All heights and dimensions are in AOD


Project	Stag Brewery SW14 7ET London
Title	Proposed Development 3D View

Drawn	AD	Checked	--
Date	09/04/2020	Project	2201
Rel no.	Prefix	Page no.	
15	DS01		04

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London
Title	Butler House Window Map
Drawn	AA
Checked	--
Date	29/01/2018
Rel no.	07
Drawing no.	2201-WM01


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Butler House Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM02		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





eb7 © copyright 2020

Sources of information


See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Boatrace House Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM03		





eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	Rann House Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM04		

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	2 to 6 Williams Lane Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM15		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	2 to 6 Williams Lane Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM16		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	8-10 Williams Lane Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM16		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	12 to 20 Williams Lane Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM17		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	15 to 21 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM18		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Reid Court Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM19		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1


EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Churchil Court Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM20		

eb7 © copyright 2020





eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Churchil Court Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM20		

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Jolly Gardeners Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM21		

eb7 © copyright 2020





eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	The Tapestry Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM22		

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



eb7 © copyright 2020


EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	The Tapestry Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM23		

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	The Tapestry Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM24		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-10 Cromwell Place Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM25		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-10 Cromwell Place Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM26		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1


EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-10 Cromwell Place Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM27		

eb7 © copyright 2020





eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	1-10 Cromwell Place Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM28		

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	22 Cromwell Place Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM29		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	3-9 Waldeck Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM30		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	3-9 Waldeck Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM31		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	3-9 Waldeck Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM32		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	3-9 Waldeck Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM33		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	2-10 Waldeck Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM34		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1




EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	2-10 Waldeck Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM35		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1


EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	2-10 Waldeck Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM36		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	2-10 Waldeck Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM37		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	51a-55 Lower Richmond Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM38		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	51a-55 Lower Richmond Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM39		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	61-63 Lower Richmond Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM40		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	61-63 Lower Richmond Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM41		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	67 Lower Richmond Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM42		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	67 Lower Richmond Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM43		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project: The Stag Brewery, SW14 7ET, London

Title: 67 Lower Richmond Road
Window Map

Drawn: AP | Checked: --


Date: 04/10/2019 | Rel no.: 13

Drawing no.: 2201-WM44

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	17-18 Lamgdon Place Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM45		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	1-3 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM46		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-3 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM47		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	4-5 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM48		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	4-5 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM49		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1






EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	11-13 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM50		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1


EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	11-13 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM51		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1


EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	23-29 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM52		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project: The Stag Brewery
SW14 7ET
London

Title: 23-29 Watney Road
Window Map

Drawn: AP | Checked: --

Date: 04/10/2019 | Rel no.: 13


Drawing no.: 2201-WM53


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1






EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	31-37 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM54		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1




EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	39-45 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM55		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	47-49 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM56		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	51-53 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM57		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1






EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	55-57 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM58		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1




EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	59-61 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM59		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey


Project	The Stag Brewery SW14 7ET London		
Title	63-65 Watney Road Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM60		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	22-26 Williams Lane Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM61		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Combe House Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM62		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Combe House Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM63		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-5 Varsity Row Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM64		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-5 Varsity Row Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM65		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-5 Varsity Row Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM66		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-5 Varsity Row Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM67		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-5 Varsity Row Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM68		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	6-7 Varsity Row Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM69		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM70		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM71		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM72		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM73		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM74		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM75		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project
The Stag Brewery
SW14 7ET
London

Title
Parliament Mews
Window Map

Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13

Drawing no.
2201-WM76

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM77		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM78		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM79		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM80		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project: The Stag Brewery, SW14 7ET, London

Title: Parliament Mews Window Map

Drawn: AP | Checked: --

Date: 04/10/2019 | Rel no.: 13

Drawing no.: 2201-WM81

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM82		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Parliament Mews Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM83		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk



Sources of information

See Sources of Information in Appendix 1



EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Aynescombe Cottage Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM84		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Aynescombe Cottage Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM85		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Aynescombe Cottage Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM86		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1






EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Aynescombe Cottage Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM87		

eb7 © copyright 2020





Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London
Title	Asplin Cottage Window Map
Drawn	AP
Checked	--
Date	04/10/2019
Rel no.	13
Drawing no.	2201-WM88


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Asplin Cottage Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM89		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd


Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	Tudor Lodge Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM90		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk





Sources of information

See Sources of Information in Appendix 1


EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-2 Thames Bank Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM91		

eb7 © copyright 2020





Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	1-2 Thames Bank Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM92		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	The Ship Thames Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM93		

eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	The Ship Thames Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM94		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	The Ship Thames Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM95		


eb7 © copyright 2020

Studio 1B, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1





EB7 Ltd

Site Photographs
Ordnance Survey

Project	The Stag Brewery SW14 7ET London		
Title	The Ship Thames Window Map		
Drawn	AP	Checked	--
Date	04/10/2019	Rel no.	13
Drawing no.	2201-WM96		

eb7 © copyright 2020

Sources of Information

Cloud 10 Limited

Measured Survey (laser scan)

APR SERVICES

Topographical Survey.pdf
Received 22/09/2016

Squire and Partners

Phase2

18125-SQP-ZZ-ZZ-M3-A-0001_rkl - 3D View - EXPORT FOR CONSULTANTS.dwg
Received 12/09/2019

191015_18125-SQP-ZZ-ZZ-M3-A-0001.dwg
Received: 15/10/2019

Detailed

18125-SQP-B12-ZZ-M3-A-0001.rvt
Received: 04/11/2019

191030_18125-SQP-B08-ZZ-M3-A-0001.rvt
Received: 31/10/2019

18125-SQP-B05-ZZ-M3-A-0001.rvt
18125-SQP-B06-ZZ-M3-A-0001.rvt
18125-SQP-B010-ZZ-M3-A-0001.rvt
Received: 15/10/2019

18125_C645_B01_P_00_001_A - BUILDING 01 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B01_P_01_001_A - BUILDING 01 - PROPOSED FIRST FLOOR PLAN.dwg
18125_C645_B01_P_02_001_A - BUILDING 01 - PROPOSED SECOND FLOOR PLAN.dwg
18125_C645_B01_P_03_001_A - BUILDING 01 - PROPOSED THIRD FLOOR PLAN.dwg
18125_C645_B01_P_B1_001_A - BUILDING 01 - PROPOSED LEVEL BASEMENT 1 PLAN.dwg
18125_C645_B01_P_B2_001_A - BUILDING 01 - PROPOSED LEVEL BASEMENT 2 PLAN.dwg
18125_C645_B01_P_RF_001_A - BUILDING 01 - PROPOSED ROOF PLAN.dwg
18125_C645_B04_P_01_001_A - BUILDING 04 - PROPOSED FIRST FLOOR PLAN.dwg
18125_C645_B04_P_02_001_A - BUILDING 04 - PROPOSED SECOND FLOOR PLAN.dwg
18125_C645_B04_P_03_001_A - BUILDING 04 - PROPOSED THRID FLOOR PLAN.dwg
18125_C645_B04_P_04_001_A - BUILDING 04 - PROPOSED FOURTH FLOOR PLAN.dwg
18125_C645_B04_P_05_001_A - BUILDING 04 - PROPOSED FIFTH FLOOR PLAN.dwg
18125_C645_B04_P_06_001_A - BUILDING 04 - PROPOSED SIXTH FLOOR PLAN.dwg
18125_C645_B04_P_07_001_A - BUILDING 04 - PROPOSED SEVENTH FLOOR PLAN.dwg
18125_C645_B04_P_RF_001_A - BUILDING 04 - PROPOSED ROOF PLAN.dwg
18125_C645_B07_P_00_001_A - BUILDING 07 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B07_P_07_001_A - BUILDING 07 - PROPOSED SEVENTH FLOOR PLAN.dwg
18125_C645_B07_P_08_001_A - BUILDING 07 - PROPOSED EIGHTH FLOOR PLAN.dwg
18125_C645_B07_P_09_001_A - BUILDING 07 - PROPOSED NINTH FLOOR PLAN.dwg
18125_C645_B07_P_RF_001_A - BUILDING 07 - PROPOSED ROOF PLAN.dwg

18125_C645_B07_P_TY1_001_A - BUILDING 07 - PROPOSED TYPICAL FLOOR 1 (SECOND TO FIFTH LEVELS).dwg
18125_C645_B07_P_TY2_001_A - BUILDING 07 - PROPOSED TYPICAL FLOOR 2 (FIRST AND SIXTH LEVELS).dwg
18125_C645_B08_P_00_001_A - BUILDING 08 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B08_P_07_001_A - BUILDING 08 - PROPOSED SEVENTH FLOOR PLAN.dwg
18125_C645_B08_P_08_001_A - BUILDING 08 - PROPOSED EIGHTH FLOOR PLAN.dwg
18125_C645_B08_P_RF_001_A - BUILDING 08 - PROPOSED ROOF FLOOR PLAN.dwg
18125_C645_B09_P_00_001_A - BUILDING 09 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B09_P_04_001_A - BUILDING 09 - PROPOSED FOURTH FLOOR PLAN.dwg
18125_C645_B09_P_RF_001_A - BLUILDING 09 - PROPOSED ROOF PLAN.dwg
18125_C645_B09_P_TY_001_A - BUILDING 09 - PROPOSED TYPICAL FLOOR PLAN (FIRST TO THIRD LEVELS).dwg
18125_C645_B10_P_00_001_A - BUILDING 10 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B10_P_05_001_A - BUILDING 10 - PROPOSED FIFTH FLOOR PLAN.dwg
18125_C645_B10_P_RF_001_A - BUILDING 10 - PROPOSED ROOF PLAN.dwg
18125_C645_B10_P_TY_001_A - BUILDING 10 - PROPOSED TYPICAL FLOOR PLAN (FIRST TO FOURTH LEVELS).dwg
18125_C645_B11_P_00_001_A - BUILDING 11 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B11_P_07_001_A - BUILDING 11 - PROPOSED SEVENTH FLOOR PLAN.dwg
18125_C645_B11_P_08_001_A - BUILDING 11 - PROPOSED EIGHTH FLOOR PLAN.dwg
18125_C645_B11_P_RF_001_A - BUILDING 11 - PROPOSED ROOF PLAN.dwg
18125_C645_B11_P_TY1_001_A - BUILDING 11 - PROPOSED TYPICAL FLOOR 1 (SECOND TO FIFTH LEVELS).dwg
18125_C645_B11_P_TY2_001_A - BUILDING 11 - PROPOSED TYPICAL FLOOR 2 (FIRST AND SIXTH LEVELS).dwg
18125_C645_B12_P_00_001_A - BUILDING 12 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B12_P_05_001_A - BUILDING 12 - PROPOSED FIFTH FLOOR PLAN.dwg
18125_C645_B12_P_06_001_A - BUILDING 12 - PROPOSED SIXTH FLOOR PLAN.dwg
18125_C645_B12_P_07_001_A - BUILDING 12 - PROPOSED SEVENTH FLOOR PLAN.dwg
18125_C645_B12_P_RF_001_A - BUILDING 12 - PROPOSED ROOF PLAN.dwg
18125_C645_B12_P_TY_001_A - BUILDING 12 - PROPOSED TYPICAL FLOOR PLAN (FIRST TO FOURTH LEVELS).dwg
18125_C645_B01_E_E_001_A - BUILDING 01 - PROPOSED EAST ELEVATION.dwg
18125_C645_B01_E_N_001_A - BUILDING 01 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B01_E_S_001_A - BUILDING 01 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B01_E_W_001_A - BUILDING 01 - PROPOSED WEST ELEVATION.dwg
18125_C645_B04_E_E_001_A - BUILDING 04 - PROPOSED EAST ELEVATION.dwg
18125_C645_B04_E_N_001_A - BUILDING 04 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B04_E_S_001_A - BUILDING 04 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B04_E_W_002_A - BUILDING 04 - PROPOSED WEST ELEVATION.dwg
18125_C645_B05_E_H_001_A - BUILDING 05 - PROPOSEDBOTTLEWORKS ELEVATIONS.dwg
18125_C645_B05_E_S_001_A - BUILDING 05 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B05_E_Z_001_A - BUILDING 05 - PROPOSED EAST & NORTH ELEVATIONS.dwg
18125_C645_B05_E_Z_002_A - BUILDING 05 - PROPOSED NORTH & WEST ELEVATIONS.dwg
18125_C645_B07_E_E_001_A - BUILDING 07 - PROPOSED EAST ELEVATION.dwg
18125_C645_B07_E_N_001_A - BUILDING 07 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B07_E_S_001_A - BUILDING 07 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B07_E_W_001_A - BUILDING 07 - PROPOSED WEST ELEVATION.dwg
18125_C645_B08_E_E_001_A - BUILDING 08 - PROPOSED EAST ELEVATION.dwg
18125_C645_B08_E_N_001_A - BUILDING 08 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B08_E_S_001_A - BUILDING 08 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B08_E_W_001_A - BUILDING 08 - PROPOSED WEST ELEVATION 1.dwg
18125_C645_B08_E_W_002_A - BUILDING 08 - PROPOSED WEST ELEVATION 2.dwg
18125_C645_B09_E_E_001_A - BUILDING 09 - PROPOSED EAST ELEVATION.dwg
18125_C645_B09_E_N_001_A - BUILDING 09 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B09_E_S_001_A - BUILDING 09 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B09_E_W_001_A - BUILDING 09 - PROPOSED WEST ELEVATION.dwg
18125_C645_B10_E_E_001_A - BUILDING 10 - PROPOSED EAST ELEVATION.dwg

18125_C645_B10_E_N_001_A - BUILDING 10 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B10_E_S_001_A - BUILDING 10 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B10_E_W_001_A - BUILDING 10 - PROPOSED WEST ELEVATION.dwg
18125_C645_B11_E_E_001_A - BUILDING 11 - PROPOSED EAST ELEVATION.dwg
18125_C645_B11_E_N_001_A - BUILDING 11 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B11_E_S_001_A - BUILDING 11 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B11_E_W_001_A - BUILDING 11 - PROPOSED WEST ELEVATION.dwg
18125_C645_B12_E_E_001_A - BUILDING 12 - PROPOSED EAST ELEVATION.dwg
18125_C645_B12_E_N_001_A - BUILDING 12 - PROPOSED NORTH ELEVATION 01.dwg
18125_C645_B12_E_N_002_A - BUILDING 12 - PROPOSED NORTH ELEVATION 02.dwg
18125_C645_B12_E_S_002_A - BUILDING 12 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B12_E_W_001_A - BUILDING 12 - PROPOSED WEST ELEVATION.dwg
18125_C645_MP_P_00_001_A - PROPOSED MASTERPLAN GROUND FLOOR LEVEL.dwg
Received: 21/10/2019

18125_G200_B08_E_E_001_B.dwg
18125_G200_B08_P_TY2_001_-.dwg
18125_G200_B08_P_TY_002_B.dwg

School
190919_16019-SQP-P3-ZZ-M3-A-0001-School – Mirrored.dwg
Received: 29/10/2019

18125-SQP-ZZ-ZZ-M3-A-0001.dwg
18125_C645_B02_P_00_001_B - BUILDING 02 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B02_P_07_001_B - BUILDING 02 - PROPOSED SEVENTH FLOOR PLAN.dwg
18125_C645_B02_P_08_001_B - BUILDING 02 - PROPOSED EIGHTH FLOOR PLAN.dwg
18125_C645_B02_P_09_001_B - BUILDING 02 - PROPOSED NINTH FLOOR PLAN.dwg
18125_C645_B02_P_RF_001_B - BUILDING 02 - PROPOSED ROOF PLAN.dwg
18125_C645_B02_P_TY1_001_B - BUILDING 02 - PROPOSED TYPICAL FLOOR 1 (SECOND TO FIFTH LEVELS).dwg
18125_C645_B02_P_TY2_001_B - BUILDING 02 - PROPOSED TYPICAL FLOOR 2 (FIRST AND SIXTH LEVELS).dwg
18125_C645_B03_P_00_001_B - BUILDING 03 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B03_P_05_001_B - BUILDING 03 - PROPOSED FIFTH FLOOR PLAN.dwg
18125_C645_B03_P_06_001_B - BUILDING 03 - PROPOSED SIXTH FLOOR PLAN.dwg
18125_C645_B03_P_07_001_B - BUILDING 03 - PROPOSED SEVENTH FLOOR PLAN.dwg
18125_C645_B03_P_RF_001_B - BUILDING 03 - PROPOSED ROOF PLAN.dwg
18125_C645_B03_P_TY_001_B - BUILDING 03 - PROPOSED TYPICAL FLOOR (FIRST TO FOURTH LEVELS).dwg
18125_C645_B04_P_00_001_B - BUILDING 04 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B06_P_00_001_B - BUILDING 06 - PROPOSED GROUND FLOOR PLAN.dwg
18125_C645_B06_P_01_001_B - BUILDING 06 - PROPOSED FIRST FLOOR PLAN.dwg
18125_C645_B06_P_04_001_B - BUILDING 06 - PROPOSED FOURTH FLOOR PLAN.dwg
18125_C645_B06_P_RF_001_B - BUILDING 06 - PROPOSED ROOF PLAN.dwg
18125_C645_B06_P_TY_001_B - BUILDING 06 - PROPOSED TYPICAL FLOOR PLAN (SECOND TO THIRD LEVELS).dwg
18125_C645_B02_E_E_001_B - BUILDING 02 - PROPOSED EAST ELEVATION.dwg
18125_C645_B02_E_N_001_B - BUILDING 02 - PROPOSED NORTH ELEVATION 1.dwg
18125_C645_B02_E_N_002_B - BUILDING 02 - PROPOSED NORTH ELEVATION 2.dwg
18125_C645_B02_E_S_001_B - BUILDING 02 - PROPOSED SOUTH ELEVATION.dwg
18125_C645_B02_E_W_001_B - BUILDING 02 - PROPOSED WEST ELEVATION 1.dwg
18125_C645_B02_E_W_002_B - BUILDING 02 - PROPOSED WEST ELEVATION 2.dwg
18125_C645_B03_E_E_001_B - BUILDING 03 - PROPOSED EAST ELEVATION.dwg
18125_C645_B03_E_N_001_B - BUILDING 03 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B03_E_S_001_B - BUILDING 03 - PROPOSED SOUTH ELEVATION.dwg

18125_C645_B03_E_W_001_B - BUILDING 03 - PROPOSED WEST ELEVATION.dwg18125_C645_B06_E_E_001_B - BUILDING 06 - PROPOSED EAST ELEVATION.dwg
18125_C645_B06_E_N_001_B - BUILDING 06 - PROPOSED NORTH ELEVATION.dwg
18125_C645_B06_E_S_001_B - BUILDING 06 - PROPOSED SOUTH ELEVATION 01.dwg
18125_C645_B06_E_S_002_B - BUILDING 06 - PROPOSED SOUTH ELEVATION 02.dwg
18125_C645_B06_E_W_001_B - BUILDING 06 - PROPOSED WEST ELEVATION.dwg
Received 27/03/2020

Appendix 18.2

Detailed Results of the Daylight (VSC, NSC and ADF) and Sunlight (APSH) Analysis

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Butler House																								
Ground	R1	W01	Bedroom	32.0	31.1	0.9	2.7						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		10.9	7.3	3.6	33.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.2		0.1									
		W03-L		8.3	5.4	2.9	34.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						144.7	129.5	127.2	2.4	1.8	0.2	0.91	0.2	0.77	0.1	15.0						
Ground	R2	W04-L	LKD	10.9	9.8	1.1	9.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.1		0.1									
		W05-L		15.7	14.6	1.1	7.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.2		0.2									
		W06-L		25.7	24.5	1.2	4.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.1		1.0									
		W07-L		36.1	26.7	9.4	26.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						304.1	303.2	298.4	4.7	1.6	2.2	3.69	1.7	3.16	0.5	14.4						
Ground	R4	W09-L	LKD	35.4	25.0	10.4	29.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											1.8		1.4									
		W10-L		21.5	18.3	3.2	14.7						0.0		0.0				15	0	14	0	0.9	0.0
		W10-U											0.8		0.7									
		W11-L		12.4	9.5	2.9	23.7						0.0		0.0				5	0	4	0	0.8	0.0
		W11-U											0.1		0.1									
		W12-L		8.0	5.2	2.8	35.3						0.0		0.0				4	0		0	0.8	0.0
		W12-U											0.1		0.1									
		W13		2.7	1.0	1.8	63.9	382.6	379.2	358.2	21.1	5.6	0.1	3.04	0.1	2.43	0.6	20.0	2	0	1	0	0.5	0.0
Ground	R5	W14-L	Bedroom	5.4	1.8	3.6	66.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											0.2		0.1									
		W15-L		8.0	3.7	4.4	54.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.2		0.1									
		W16		23.8	21.7	2.1	9.0	135.1	110.6	70.7	39.9	36.1	0.4	0.75	0.3	0.55	0.2	27.3	33	11	32	11	1.0	1.0
Ground	R6	W17	Bedroom	12.4	12.4	0.0	0.0						0.2		0.2				20	2	20	2	1.0	1.0
		W18		12.2	11.8	0.3	2.6	103.9	30.2	30.2	0.0	0.0	0.2	0.40	0.2	0.40	0.0	0.6	1	0	1	0	1.0	0.0
First	R1	W01	Bedroom	33.6	32.9	0.6	1.8						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		4.4	2.6	1.8	39.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						139.4	136.2	133.7	2.6	1.9	0.3	0.69	0.2	0.62	0.1	10.2						
First	R2	W03-L	Bedroom	6.8	6.0	0.8	11.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						105.1	83.7	83.2	0.4	0.5	0.4	0.41	0.4	0.39	0.0	6.4						
First	R3	W04-L	LKD	14.1	13.2	0.9	6.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.2		0.2									
		W05-L		18.2	17.2	1.0	5.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.2		0.2									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W06-L		28.9	27.8	1.0	3.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.2		1.2									
		W07-L		37.5	28.4	9.1	24.3						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											2.2		1.7									
		W08		38.1	28.7	9.4	24.7	290.5	290.2	290.0	0.2	0.1	0.3	4.48	0.3	3.85	0.6	13.9	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W09	LKD	38.1	28.1	9.9	26.1						0.3		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10-L		37.2	26.8	10.4	28.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U											2.2		1.7									
		W11-L		24.2	21.0	3.2	13.2						0.1		0.1				14	1	13	1	0.9	1.0
		W11-U											1.0		0.9									
		W12-L		14.3	11.3	3.0	20.9						0.0		0.0				9	2	8	2	0.9	1.0
		W12-U											0.2		0.2									
		W13-L		9.7	6.8	2.9	29.7						0.0		0.0				8	2	7	2	0.9	1.0
		W13-U						290.5	284.8	284.7	0.0	0.0	0.1	4.22	0.1	3.43	0.8	18.8						
First	R5	W14-L	Bedroom	3.5	1.5	2.0	58.2						0.0		0.0				2	0	1	0	0.5	0.0
		W14-U						105.2	50.5	46.7	3.9	7.6	0.3	0.29	0.2	0.18	0.1	38.6						
First	R6	W15-L	Bedroom	4.3	1.1	3.3	75.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.3		0.1									
		W16		26.7	24.9	1.8	6.9	125.2	99.9	83.2	16.7	16.7	0.4	0.64	0.3	0.48	0.2	25.8	35	11	34	11	1.0	1.0
First	R7	W17	LKD	20.7	20.5	0.2	0.9						0.1		0.1				32	12	32	12	1.0	1.0
		W18		21.1	19.6	1.4	6.8						0.1		0.1				15		15		1.0	1.0
		W19		27.8	26.5	1.3	4.8	302.0	250.2	216.2	33.9	13.6	0.2	0.46	0.2	0.45	0.0	2.0	39	15	39	15	1.0	1.0
Second	R1	W01	Bedroom	36.5	36.0	0.5	1.5						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		22.0	20.2	1.8	8.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						139.4	138.9	138.9	0.0	0.0	0.7	1.11	0.6	1.07	0.0	3.6						
Second	R2	W03-L	Bedroom	31.3	30.7	0.6	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						105.1	101.0	101.0	0.0	0.0	1.1	1.08	1.1	1.07	0.0	1.4						
Second	R3	W04-L	LKD	35.5	34.8	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.4		0.4									
		W05-L		35.9	35.1	0.8	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.4		0.4									
		W06-L		36.3	35.5	0.8	2.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.5		1.4									
		W07-L		38.4	30.3	8.1	21.1						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											2.2		1.8									
		W08		38.9	30.7	8.2	21.2	290.5	290.2	290.0	0.2	0.1	0.3	5.21	0.3	4.65	0.6	10.8	N/F	N/F	N/F	N/F	N/F	N/F
Second	R4	W09	LKD	38.9	30.2	8.8	22.5						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W10-L		38.4	28.9	9.5	24.7						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U											2.2		1.8									
		W11-L		31.1	28.2	2.9	9.4						0.1		0.1				39	8	38	8	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W11-U											1.2		1.1									
		W12-L		30.5	27.8	2.7	8.9						0.0		0.0				39	8	38	8	1.0	1.0
		W12-U											0.3		0.3									
		W13-L		29.9	27.3	2.6	8.7						0.0		0.0				35	6	34	6	1.0	1.0
		W13-U						290.5	284.8	284.8	0.0	0.0	0.3	4.84	0.3	4.12	0.7	15.0						
Second	R5	W14-L	Bedroom	24.8	22.4	2.4	9.5						0.0		0.0				19	1	18	1	0.9	1.0
		W14-U						105.2	77.1	77.1	0.0	0.0	0.9	0.91	0.9	0.86	0.1	5.7						
Second	R6	W15-L	Bedroom	21.5	16.4	5.1	23.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.7		0.6									
		W16		30.1	28.2	2.0	6.5	125.2	100.5	100.5	0.0	0.0	0.4	1.07	0.4	0.95	0.1	11.5	42	13	42	13	1.0	1.0
Second	R7	W17	LKD	23.4	23.2	0.2	0.8						0.1		0.1				39	12	39	12	1.0	1.0
		W18		23.5	22.2	1.3	5.3						0.1		0.1				17		17		1.0	1.0
		W19		30.2	29.0	1.2	3.9						0.2		0.2				40	15	40	15	1.0	1.0
		W20-L		38.8	38.8	0.0	0.0						0.1		0.1				83	28	83	28	1.0	1.0
		W20-U											0.7		0.7									
		W21-L		38.9	38.9	0.0	0.0						0.1		0.1				83	28	83	28	1.0	1.0
		W21-U											0.6		0.6									
		W22-L		38.9	38.9	0.0	0.0						0.0		0.0				83	28	83	28	1.0	1.0
		W22-U											0.5		0.5									
		W23-L		39.0	39.0	0.0	0.0						0.1		0.1				83	28	83	28	1.0	1.0
		W23-U						302.0	301.2	301.2	0.0	0.0	0.7	3.17	0.7	3.16	0.0	0.3						
Third	R1	W01-L	Living Room	29.1	28.6	0.6	1.9						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											2.7		2.7									
		W02-L		21.6	19.8	1.8	8.2						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						251.5	251.5	251.5	0.0	0.0	2.9	6.05	2.3	5.42	0.6	10.4						
Third	R2	W03-L	Living Room	22.2	16.6	5.6	25.3						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											2.8		2.1									
		W04-L		24.2	22.1	2.1	8.7						0.2		0.2				32	9	31	9	1.0	1.0
		W04-U						251.5	251.5	251.5	0.0	0.0	2.3	5.53	2.2	4.71	0.8	14.8						
Boatrace House																								
First	R1	W01-L	LKD	0.8	0.8	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.1		0.1									
		W02-L		1.2	1.2	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.1		0.1									
		W03-L		33.6	33.6	0.0	0.1						0.0		0.0				82	24	82	24	1.0	1.0
		W03-U											0.4		0.4									
		W04-L		33.4	33.4	0.0	0.1						0.0		0.0				81	23	81	23	1.0	1.0
		W04-U											0.4		0.4									
		W05-L		33.2	33.2	0.0	0.1						0.0		0.0				81	23	81	23	1.0	1.0
		W05-U						500.2	455.5	455.5	0.0	0.0	0.4	1.47	0.4	1.47	0.0	0.0						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R2	W06-L	Bedroom	32.0	32.0	0.0	0.1						0.0		0.0				72	22	72	22	1.0	1.0
		W06-U						165.8	110.9	110.9	0.0	0.0	0.6	0.61	0.6	0.61	0.0	0.0						
First	R3	W07-L	Bedroom	32.3	32.3	0.0	0.1						0.0		0.0				79	23	79	23	1.0	1.0
		W07-U						158.8	111.7	111.7	0.0	0.0	0.6	0.58	0.6	0.58	0.0	0.0						
First	R4	W08	Bedroom	31.6	31.6	0.0	0.1						0.8		0.8				78	25	78	25	1.0	1.0
		W09		31.6	31.6	0.0	0.0	145.3	144.3	144.3	0.0	0.0	0.8	1.58	0.8	1.58	0.0	0.0	81	25	81	25	1.0	1.0
First	R5	W10	LKD	31.6	31.6	0.0	0.1						0.6		0.6				78	24	78	24	1.0	1.0
		W11		31.6	31.6	0.0	0.0						0.6		0.6				79	23	79	23	1.0	1.0
		W12		31.6	31.6	0.0	0.1						0.5		0.5				77	24	77	24	1.0	1.0
		W13		31.7	31.7	0.0	0.0	227.2	226.0	226.0	0.0	0.0	0.5	2.20	0.5	2.20	0.0	0.0	80	24	80	24	1.0	1.0
First	R6	W14	Bedroom	31.7	31.7	0.0	0.2						0.5		0.5				79	25	79	25	1.0	1.0
		W15		31.8	31.7	0.0	0.0						0.5		0.5				81	25	81	25	1.0	1.0
		W16		36.4	23.8	12.6	34.6						0.8		0.6				N/F	N/F	N/F	N/F	N/F	N/F
		W17		14.2	7.5	6.7	47.2	197.4	187.9	165.0	22.8	12.2	0.1	1.90	0.1	1.64	0.3	13.4	16	0	8	0	0.5	0.0
First	R7	W18-L	Bedroom	32.9	15.6	17.3	52.5						0.1		0.1				49	14	33	12	0.7	0.9
		W18-U						164.8	157.2	100.3	56.9	36.2	1.4	1.55	0.8	0.90	0.6	41.9						
First	R8	W19-L	LKD	33.0	14.3	18.7	56.7						0.1		0.0				47	13	25	9	0.5	0.7
		W19-U						449.7	429.7	46.3	383.3	89.2	0.6	0.65	0.3	0.36	0.3	45.4						
First	R9	W20-L	Bedroom	33.3	14.9	18.5	55.4						0.1		0.1				47	14	22	8	0.5	0.6
		W20-U						228.5	224.7	91.6	133.1	59.2	1.0	1.15	0.6	0.64	0.5	44.3						
First	R10	W21-L	Bedroom	33.8	17.2	16.6	49.1						0.1		0.1				48	14	23	8	0.5	0.6
		W21-U						184.9	129.2	84.0	45.2	35.0	1.3	1.38	0.8	0.84	0.5	39.4						
First	R11	W22-L	LKD	36.6	21.0	15.6	42.6						0.0		0.0				44	13	19	7	0.4	0.5
		W22-U											0.5		0.3									
		W23-L		38.8	38.4	0.5	1.2						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W23-U						367.4	322.7	226.9	95.8	29.7	0.8	1.45	0.8	1.26	0.2	13.2						
Second	R1	W01	Bedroom	29.8	29.8	0.0	0.0						1.0		1.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		33.6	33.6	0.0	0.1						0.1		0.1				84	28	84	28	1.0	1.0
		W02-U						253.6	251.8	251.8	0.0	0.0	1.0	2.05	1.0	2.05	0.0	0.0						
Second	R2	W03-L	Bedroom	34.2	34.1	0.0	0.1						0.1		0.1				84	28	84	28	1.0	1.0
		W03-U						242.1	236.1	236.1	0.0	0.0	1.1	1.17	1.1	1.17	0.0	0.0						
Second	R4	W05-L	Bedroom	34.4	34.2	0.2	0.5						0.2		0.2				86	29	86	29	1.0	1.0
		W05-U						134.9	132.8	132.8	0.0	0.0	1.7	1.89	1.7	1.89	0.0	0.1						
Second	R5	W06-L	LKD	34.8	34.4	0.4	1.0						0.1		0.1				86	29	82	27	1.0	0.9
		W06-U											0.9		0.9									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W07-L		33.7	19.3	14.4	42.6						0.1		0.1				49	15	35	13	0.7	0.9
		W07-U						348.2	347.1	336.2	11.0	3.2	0.8	1.79	0.5	1.50	0.3	16.1						
Second	R6	W08-L	Bedroom	33.8	17.9	15.8	46.9						0.1		0.1				46	13	28	9	0.6	0.7
		W08-U						233.4	219.7	46.2	173.5	79.0	1.0	1.10	0.6	0.70	0.4	36.7						
Second	R7	W09-L	Bedroom	33.4	17.7	15.7	47.0						0.1		0.1				45	13	24	7	0.5	0.5
		W09-U						185.3	181.3	80.4	100.9	55.7	1.1	1.20	0.7	0.76	0.4	36.8						
Second	R8	W10-L	Bedroom	33.8	19.6	14.2	41.9						0.1		0.1				46	14	23	8	0.5	0.6
		W10-U						167.4	119.0	86.7	32.3	27.2	1.3	1.39	0.8	0.93	0.5	33.0						
Second	R9	W11-L	LKD	38.4	38.0	0.4	1.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.8		0.8									
		W12-L		38.7	38.2	0.5	1.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						367.5	300.2	300.2	0.0	0.0	0.8	1.71	0.8	1.69	0.0	0.9						
Third	R1	W01	Bedroom	26.4	26.4	0.0	0.0						0.8		0.8				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		32.4	32.4	0.0	0.1						0.1		0.1				79	30	79	30	1.0	1.0
		W02-U						257.0	254.8	254.8	0.0	0.0	0.9	1.77	0.9	1.77	0.0	0.0						
Third	R2	W03-L	Bedroom	32.1	32.1	0.0	0.1						0.1		0.1				77	30	77	30	1.0	1.0
		W03-U						221.8	218.1	218.1	0.0	0.0	1.0	1.13	1.0	1.13	0.0	0.0						
Third	R4	W05-L	Bedroom	31.6	31.5	0.1	0.3						0.1		0.1				76	29	76	29	1.0	1.0
		W05-U						157.6	138.4	138.4	0.0	0.0	1.2	1.37	1.2	1.36	0.0	0.1						
Third	R5	W06-L	LKD	31.6	31.4	0.2	0.7						0.1		0.1				77	29	75	27	1.0	0.9
		W06-U											0.7		0.7									
		W07-L		33.0	22.6	10.4	31.5						0.1		0.1				40	13	29	11	0.7	0.8
		W07-U						347.6	346.5	335.0	11.5	3.3	0.8	1.67	0.6	1.46	0.2	12.7						
Third	R6	W08-L	Bedroom	33.0	21.2	11.8	35.8						0.1		0.1				39	12	26	10	0.7	0.8
		W08-U						186.0	179.7	81.8	98.0	54.5	1.2	1.34	0.9	0.96	0.4	28.0						
Third	R7	W09-L	Bedroom	32.0	20.1	11.9	37.3						0.1		0.1				39	12	23	8	0.6	0.7
		W09-U						178.1	169.6	99.9	69.7	41.1	1.1	1.24	0.8	0.88	0.4	29.1						
Third	R8	W10-L	Bedroom	32.1	21.2	10.9	34.0						0.1		0.1				39	12	21	6	0.5	0.5
		W10-U						171.7	123.1	102.9	20.3	16.5	1.2	1.32	0.9	0.96	0.4	26.8						
Third	R9	W11-L	LKD	33.7	33.2	0.4	1.2						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.7		0.6									
		W12-L		33.5	33.1	0.3	1.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						367.2	299.8	299.7	0.0	0.0	0.6	1.42	0.6	1.41	0.0	0.7						
Fourth	R1	W01-L	Bedroom	25.8	21.9	3.9	15.1						0.1		0.1				26	2	21	1	0.8	0.5
		W01-U						311.0	291.7	198.4	93.3	32.0	0.8	0.87	0.7	0.78	0.1	9.8						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Fourth	R2	W02-L	Bedroom	25.6	21.2	4.5	17.4						0.1		0.1				28	2	21	0	0.8	0.0
		W02-U						214.5	195.4	195.2	0.3	0.1	1.1	1.19	1.0	1.06	0.1	11.1						
Fourth	R3	W03-L	LKD	38.8	38.8	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						730.8	713.9	713.9	0.0	0.0	1.6	1.75	1.6	1.74	0.0	0.3						
Rann House																								
Ground	R3	W03	Bedroom	36.5	28.6	7.8	21.5	129.1	128.4	115.2	13.2	10.3	2.3	2.34	1.9	1.91	0.4	18.2	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W04	Living Room	9.9	6.0	4.0	39.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		17.0	14.0	3.0	17.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.0		0.0									
		W06-L		12.2	6.2	6.0	49.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						175.8	173.4	160.4	13.1	7.5	0.7	0.89	0.5	0.60	0.3	33.4						
Ground	R5	W07	Living Room	33.7	28.0	5.7	16.8						1.8		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W08		3.0	3.0	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		6.0	6.0	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						157.9	156.5	146.0	10.4	6.7	0.0	1.90	0.0	1.66	0.2	12.7						
Ground	R6	W10-L	Bedroom	11.6	7.2	4.5	38.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						107.3	103.2	103.2	0.0	0.0	1.0	1.04	0.8	0.76	0.3	26.6						
Ground	R8	W22-L	Bedroom	11.1	7.7	3.4	30.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W22-U						107.3	104.4	95.1	9.4	9.0	1.0	1.01	0.8	0.80	0.2	20.9						
Ground	R9	W23	Living Room	3.6	1.4	2.1	60.0						0.1		0.0				2	0	0	0	0.0	0.0
		W24-L		6.2	4.5	1.7	26.8						0.0		0.0				2	0	0	0	0.0	0.0
		W24-U											0.0		0.0									
		W25		35.0	31.0	4.0	11.5	157.9	151.9	151.5	0.4	0.3	1.9	1.97	1.7	1.75	0.2	11.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R10	W26	Living Room	34.6	31.1	3.5	10.1						1.9		1.7				N/F	N/F	N/F	N/F	N/F	N/F
		W27		3.2	3.2	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W28-L		6.2	6.2	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W28-U						157.9	147.7	147.7	0.0	0.0	0.0	1.94	0.0	1.79	0.2	8.2						
Ground	R11	W29-L	Bedroom	10.1	7.7	2.4	23.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W29-U						107.3	100.5	100.5	0.0	0.0	0.9	0.95	0.8	0.80	0.1	15.5						
Ground	R13	W41-L	Bedroom	9.5	7.8	1.7	17.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W41-U						107.3	101.4	101.3	0.1	0.1	0.9	0.91	0.8	0.81	0.1	10.9						
Ground	R14	W42	Living Room	3.7	1.7	1.9	52.5						0.1		0.1				2	0	1	0	0.5	0.0
		W43-L		6.1	4.8	1.3	21.5						0.0		0.0				2	0	0	0	0.0	0.0
		W43-U											0.0		0.0									
		W44		30.9	28.8	2.1	6.9	157.9	141.2	140.9	0.3	0.2	1.7	1.78	1.6	1.66	0.1	6.6	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R15	W45-L	Living Room	8.9	8.1	0.7	8.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W45-U											0.6		0.6									
		W46		7.5	6.1	1.5	19.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W47-L		15.6	14.2	1.3	8.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W47-U						175.8	136.5	131.0	5.5	4.1	0.0	0.73	0.0	0.69	0.0	5.5						
Ground	R16	W48	Bedroom	31.8	30.3	1.5	4.7	129.1	127.8	127.8	0.0	0.0	2.1	2.09	2.0	2.01	0.1	3.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W03	Bedroom	37.4	30.4	7.1	18.9	129.1	128.4	126.4	2.0	1.6	2.4	2.40	2.0	2.00	0.4	16.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W04	Living Room	10.7	7.1	3.6	33.5						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		14.6	14.1	0.5	3.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.0		0.0									
		W06		13.0	7.5	5.5	42.3	175.8	172.4	162.9	9.6	5.6	0.8	0.97	0.6	0.70	0.3	27.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R5	W07	Living Room	34.6	29.5	5.1	14.7						1.9		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W08		3.4	3.4	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		5.0	5.0	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						157.9	156.5	150.8	5.7	3.6	0.0	1.95	0.0	1.73	0.2	11.4						
First	R6	W10	Bedroom	12.4	8.4	4.0	32.2	107.3	104.2	104.2	0.0	0.0	1.1	1.15	0.9	0.91	0.2	21.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R8	W12	Bedroom	12.0	9.0	3.1	25.6	107.3	104.4	101.2	3.1	3.0	1.1	1.12	0.9	0.94	0.2	16.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R9	W13	Living Room	3.9	1.8	2.1	53.2						0.1		0.1				2	0	1	0	0.5	0.0
		W14-L		5.0	4.8	0.2	4.0						0.0		0.0				2	0	2	0	1.0	0.0
		W14-U											0.0		0.0									
		W15		36.1	32.5	3.6	10.0	157.9	156.7	156.4	0.3	0.2	1.9	2.03	1.8	1.83	0.2	9.9	N/F	N/F	N/F	N/F	N/F	N/F
First	R10	W16	Living Room	35.8	32.6	3.2	8.8						1.9		1.8				N/F	N/F	N/F	N/F	N/F	N/F
		W17		3.6	3.6	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W18-L		5.0	5.0	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						157.9	156.7	156.7	0.0	0.0	0.0	2.01	0.0	1.86	0.2	7.5						
First	R11	W19	Bedroom	11.2	9.1	2.2	19.1	107.3	104.3	104.3	0.0	0.0	1.1	1.07	0.9	0.95	0.1	11.9	N/F	N/F	N/F	N/F	N/F	N/F
First	R13	W21	Bedroom	10.8	9.3	1.5	13.9	107.3	104.5	104.5	0.0	0.0	1.0	1.04	1.0	0.96	0.1	8.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R14	W22	Living Room	3.9	2.1	1.8	46.6						0.1		0.1				2	0	1	0	0.5	0.0
		W23-L		5.0	4.9	0.1	2.0						0.0		0.0				2	0	2	0	1.0	0.0
		W23-U											0.0		0.0									
		W24		32.4	30.4	2.0	6.0	157.9	156.6	156.4	0.2	0.1	1.8	1.85	1.7	1.74	0.1	5.9	N/F	N/F	N/F	N/F	N/F	N/F
First	R15	W25	Living Room	10.3	9.6	0.7	6.7						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W26		8.6	7.3	1.4	15.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W27-L		14.4	14.2	0.2	1.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W27-U						175.8	158.7	158.3	0.3	0.2	0.0	0.83	0.0	0.80	0.0	4.3						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R16	W28	Bedroom	33.7	32.3	1.4	4.1	129.1	128.2	128.2	0.0	0.0	2.2	2.19	2.1	2.11	0.1	3.5	N/F	N/F	N/F	N/F	N/F	N/F
Second	R3	W03	Bedroom	38.0	32.0	6.0	15.8	129.1	128.4	128.4	0.0	0.0	2.4	2.44	2.1	2.09	0.3	14.3	N/F	N/F	N/F	N/F	N/F	N/F
Second	R4	W04	Living Room	11.1	8.2	2.9	26.0						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		14.2	14.1	0.0	0.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.0		0.0									
		W06		13.4	8.8	4.7	34.7	175.8	172.5	167.7	4.8	2.8	0.8	0.99	0.6	0.77	0.2	21.8	N/F	N/F	N/F	N/F	N/F	N/F
Second	R5	W07	Living Room	35.1	30.8	4.3	12.3						1.9		1.7				N/F	N/F	N/F	N/F	N/F	N/F
		W08		3.7	3.7	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		4.9	4.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						157.9	156.6	155.4	1.2	0.8	0.0	1.97	0.0	1.78	0.2	9.7						
Second	R6	W10	Bedroom	13.0	9.6	3.4	26.2	107.3	104.2	104.2	0.0	0.0	1.2	1.18	1.0	0.98	0.2	16.9	N/F	N/F	N/F	N/F	N/F	N/F
Second	R8	W12	Bedroom	12.7	10.1	2.6	20.7	107.3	104.4	104.3	0.1	0.1	1.2	1.16	1.0	1.01	0.2	13.1	N/F	N/F	N/F	N/F	N/F	N/F
Second	R9	W13	Living Room	4.0	2.2	1.8	45.7						0.1		0.1				2	0	1	0	0.5	0.0
		W14-L		4.9	4.9	0.0	0.0						0.0		0.0				2	0	2	0	1.0	0.0
		W14-U											0.0		0.0									
		W15		36.9	33.8	3.1	8.4	157.9	156.7	156.7	0.0	0.0	2.0	2.07	1.8	1.90	0.2	8.5	N/F	N/F	N/F	N/F	N/F	N/F
Second	R10	W16	Living Room	36.7	34.0	2.7	7.4						2.0		1.8				N/F	N/F	N/F	N/F	N/F	N/F
		W17		3.9	3.9	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W18-L		4.9	4.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						157.9	156.8	156.8	0.0	0.0	0.0	2.06	0.0	1.93	0.1	6.5						
Second	R11	W19	Bedroom	12.1	10.3	1.8	15.2	107.3	104.3	104.3	0.0	0.0	1.1	1.13	1.0	1.02	0.1	9.3	N/F	N/F	N/F	N/F	N/F	N/F
Second	R13	W21	Bedroom	11.8	10.5	1.3	10.8	107.3	104.6	104.5	0.0	0.0	1.1	1.11	1.0	1.04	0.1	6.1	N/F	N/F	N/F	N/F	N/F	N/F
Second	R14	W22	Living Room	4.0	2.4	1.6	40.7						0.1		0.1				2	0	1	0	0.5	0.0
		W23-L		4.9	4.9	0.0	0.0						0.0		0.0				2	0	2	0	1.0	0.0
		W23-U											0.0		0.0									
		W24		33.6	31.9	1.7	5.1	157.9	156.6	156.5	0.2	0.1	1.8	1.90	1.7	1.81	0.1	5.2	N/F	N/F	N/F	N/F	N/F	N/F
Second	R15	W25	Living Room	11.5	10.9	0.6	5.2						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W26		9.7	8.5	1.2	12.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W27-L		14.2	14.1	0.0	0.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W27-U						175.8	172.3	172.3	0.0	0.0	0.0	0.89	0.0	0.86	0.0	3.3						
Second	R16	W28	Bedroom	35.5	34.2	1.3	3.6	129.1	128.3	128.3	0.0	0.0	2.3	2.29	2.2	2.22	0.1	3.2	N/F	N/F	N/F	N/F	N/F	N/F
Third	R3	W03	Bedroom	38.0	33.2	4.9	12.8	129.1	128.4	128.4	0.0	0.0	2.5	2.46	2.2	2.17	0.3	11.9	N/F	N/F	N/F	N/F	N/F	N/F
Third	R4	W04	Living Room	11.5	9.2	2.3	19.7						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W05-L		13.4	13.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.0		0.0									
		W06-L		13.8	10.0	3.8	27.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						175.8	173.0	173.0	0.0	0.0	0.8	0.98	0.7	0.82	0.2	17.0						
Third	R5	W07	Living Room	33.9	30.4	3.6	10.5						1.7		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W08		3.1	3.1	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		3.7	3.7	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						157.9	156.7	156.7	0.0	0.0	0.0	1.81	0.0	1.66	0.1	8.2						
Third	R6	W10-L	Bedroom	11.4	8.5	2.8	24.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						107.3	104.2	104.2	0.0	0.0	1.1	1.07	0.9	0.91	0.2	15.7						
Third	R8	W12-L	Bedroom	11.2	9.1	2.2	19.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						107.3	104.4	104.3	0.1	0.1	1.1	1.06	0.9	0.94	0.1	12.0						
Third	R9	W13	Living Room	3.2	1.6	1.6	49.2						0.1		0.1				2	0	1	0	0.5	0.0
		W14-L		3.7	3.7	0.0	0.0						0.0		0.0				2	0	2	0	1.0	0.0
		W14-U											0.0		0.0									
		W15		35.2	32.7	2.6	7.3	157.9	156.6	156.6	0.0	0.0	1.8	1.88	1.7	1.74	0.1	7.3	N/F	N/F	N/F	N/F	N/F	N/F
Third	R10	W16	Living Room	35.1	32.8	2.2	6.4						1.8		1.7				N/F	N/F	N/F	N/F	N/F	N/F
		W17		3.2	3.2	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W18-L		3.8	3.8	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						157.9	156.8	156.8	0.0	0.0	0.0	1.87	0.0	1.77	0.1	5.4						
Third	R11	W19-L	Bedroom	10.8	9.3	1.5	14.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						107.3	104.3	104.3	0.0	0.0	1.0	1.04	0.9	0.95	0.1	8.4						
Third	R13	W21-L	Bedroom	10.6	9.6	1.0	9.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W21-U						107.3	104.6	104.6	0.0	0.0	1.0	1.03	1.0	0.97	0.1	5.4						
Third	R14	W22	Living Room	3.2	1.8	1.4	43.7						0.1		0.1				2	0	1	0	0.5	0.0
		W23-L		3.7	3.7	0.0	0.0						0.0		0.0				2	0	2	0	1.0	0.0
		W23-U											0.0		0.0									
		W24		32.9	31.5	1.4	4.3	157.9	156.7	156.6	0.1	0.1	1.7	1.77	1.6	1.69	0.1	4.6	N/F	N/F	N/F	N/F	N/F	N/F
Third	R15	W25-L	Living Room	12.6	12.1	0.5	3.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W25-U											0.8		0.7									
		W26		10.6	9.6	1.0	9.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W27-L		13.4	13.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W27-U						175.8	172.8	172.7	0.0	0.0	0.0	0.93	0.0	0.90	0.0	2.4						
Third	R16	W28	Bedroom	36.8	35.7	1.1	2.9	129.1	128.3	128.3	0.0	0.0	2.4	2.38	2.3	2.31	0.1	2.8	N/F	N/F	N/F	N/F	N/F	N/F
31 Vineyard Path																								
First	R1	W01-L	Unknown	23.4	14.0	9.4	40.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W01-U						153.6	143.2	72.7	70.5	49.2	1.1	1.15	0.8	0.83	0.3	27.3						
First	R2	W02-L	Unknown	36.5	24.3	12.2	33.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						135.8	134.7	66.9	67.8	50.3	1.8	1.89	1.3	1.37	0.5	27.5						
First	R3	W03-L	Unknown	36.6	24.3	12.3	33.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						135.8	134.8	67.2	67.6	50.1	1.8	1.90	1.3	1.37	0.5	27.8						
First	R4	W04-L	Unknown	31.6	20.5	11.1	35.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											1.6		1.2									
		W05-L		32.2	29.9	2.4	7.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						124.3	123.3	122.9	0.4	0.3	1.7	3.35	1.6	2.82	0.5	15.8						
First	R5	W06-L	Unknown	30.4	28.4	2.1	6.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						124.3	113.1	113.0	0.1	0.0	1.6	1.61	1.5	1.53	0.1	4.9						
First	R6	W07-L	Unknown	30.8	29.1	1.7	5.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						148.8	132.1	132.1	0.0	0.0	1.9	2.00	1.8	1.92	0.1	4.1						
First	R7	W08-L	Unknown	31.5	30.1	1.4	4.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						148.8	138.2	138.1	0.0	0.0	1.9	2.03	1.8	1.96	0.1	3.4						
First	R8	W09-L	Unknown	32.3	31.6	0.7	2.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											1.0		1.0									
		W10-L		34.2	33.4	0.8	2.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						262.0	259.7	259.6	0.1	0.0	1.0	2.01	1.0	1.98	0.0	1.7						
Second	R1	W01-L	Unknown	25.5	16.3	9.1	35.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						153.6	144.1	81.2	62.9	43.7	1.1	1.12	0.8	0.84	0.3	24.7						
Second	R2	W02-L	Unknown	38.6	26.6	12.1	31.2						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						135.8	134.6	72.9	61.7	45.8	1.7	1.84	1.2	1.36	0.5	26.5						
Second	R3	W03-L	Unknown	38.7	26.6	12.1	31.3						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						135.8	134.8	73.5	61.4	45.5	1.7	1.84	1.2	1.35	0.5	26.6						
Second	R4	W04-L	Unknown	33.1	22.6	10.5	31.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											1.5		1.2									
		W05-L		35.3	33.1	2.2	6.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						124.3	123.3	123.0	0.4	0.3	1.6	3.27	1.6	2.80	0.5	14.3						
Second	R5	W06-L	Unknown	33.7	31.9	1.9	5.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						124.3	122.6	122.5	0.0	0.0	1.6	1.61	1.5	1.55	0.1	4.2						
Second	R6	W07-L	Unknown	34.8	33.2	1.6	4.5						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						148.8	147.7	147.7	0.0	0.0	1.9	2.05	1.8	1.97	0.1	3.6						
Second	R7	W08-L	Unknown	35.4	34.1	1.3	3.6						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W08-U						148.8	147.5	147.5	0.0	0.0	1.9	2.07	1.8	2.01	0.1	3.0						
Second	R8	W09-L	Unknown	35.4	34.7	0.7	1.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											1.0		0.9									
		W10-L		36.9	36.1	0.8	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						262.0	259.7	259.7	0.0	0.0	1.0	2.00	1.0	1.97	0.0	1.6						
Third	R1	W01-L	Unknown	31.8	24.2	7.6	23.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						153.6	151.3	110.1	41.2	27.2	1.3	1.29	1.0	1.06	0.2	18.1						
Third	R2	W02-L	Unknown	38.8	28.7	10.1	26.0						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						135.8	134.5	89.3	45.2	33.6	1.7	1.84	1.3	1.42	0.4	22.4						
Third	R3	W03-L	Unknown	38.8	28.7	10.1	26.1						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						135.8	134.8	89.8	45.1	33.4	1.7	1.84	1.3	1.42	0.4	22.5						
Third	R4	W04-L	Unknown	34.3	25.7	8.6	25.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											1.5		1.2									
		W05-L		36.0	34.3	1.7	4.7						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						124.3	123.6	123.6	0.0	0.0	1.6	3.21	1.5	2.83	0.4	11.8						
Third	R5	W06-L	Unknown	34.7	33.2	1.5	4.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						124.3	122.5	122.5	0.1	0.0	1.5	1.56	1.5	1.51	0.1	3.3						
Third	R6	W07-L	Unknown	37.5	36.3	1.2	3.3						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						148.8	147.9	147.9	0.0	0.0	2.0	2.16	1.9	2.10	0.1	2.9						
Third	R7	W08-L	Unknown	37.7	36.6	1.0	2.7						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						148.8	147.5	147.5	0.0	0.0	2.0	2.17	1.9	2.12	0.1	2.4						
Third	R8	W09-L	Unknown	35.3	34.7	0.6	1.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											0.9		0.9									
		W10-L		36.5	35.8	0.6	1.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						262.0	259.6	259.6	0.0	0.0	0.9	1.88	0.9	1.86	0.0	1.3						
Vineyard Heights																								
Third	R4	W08-L	Unknown	20.7	17.5	3.2	15.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.6		0.5									
		W09-L		35.7	28.6	7.1	19.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											1.5		1.3									
		W10-L		39.1	31.4	7.7	19.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U											1.6		1.3									
		W11-L		35.5	31.2	4.2	12.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											1.5		1.4									
		W12-L		20.6	19.5	1.2	5.6						0.0		0.0				15	2	15	2	1.0	1.0
		W12-U						157.8	155.6	155.6	0.0	0.0	0.6	6.09	0.5	5.28	0.8	13.4						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Third	R5	W13-L	Unknown	37.1	30.0	7.1	19.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						127.7	114.8	97.0	17.7	15.5	0.7	0.71	0.6	0.59	0.1	16.3						
Third	R6	W14-L	Unknown	34.4	28.3	6.1	17.7						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						258.7	258.5	258.5	0.0	0.0	5.7	5.91	4.9	5.10	0.8	13.8						
Third	R7	W15-L	Unknown	36.5	30.5	6.0	16.5						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U						304.9	304.6	304.6	0.0	0.0	6.0	6.27	5.2	5.41	0.9	13.7						
Third	R8	W16-L	Unknown	36.6	30.9	5.7	15.7						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						235.6	235.5	235.5	0.0	0.0	5.5	5.67	4.7	4.93	0.7	13.2						
Third	R9	W17-L	Unknown	36.6	31.1	5.5	15.1						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U						181.5	181.5	181.5	0.0	0.0	5.5	5.65	4.7	4.93	0.7	12.8						
Third	R10	W18-L	Unknown	35.9	30.6	5.3	14.7						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						266.3	265.9	265.9	0.0	0.0	5.8	5.99	5.0	5.25	0.7	12.3						
Fourth	R1	W01-L	Unknown	31.8	31.0	0.9	2.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.5		0.5									
		W02-L		31.8	30.9	0.9	2.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						230.7	218.6	218.6	0.0	0.0	0.5	1.02	0.5	1.00	0.0	1.9						
Fourth	R2	W03	Unknown	25.5	24.5	1.0	3.8	92.4	90.3	90.3	0.0	0.0	1.0	1.02	1.0	1.00	0.0	2.4	N/F	N/F	N/F	N/F	N/F	N/F
Fourth	R3	W04	Unknown	32.5	31.4	1.0	3.2						0.9		0.9				N/F	N/F	N/F	N/F	N/F	N/F
		W05		33.2	32.2	1.1	3.2	147.6	145.9	145.9	0.0	0.0	0.9	1.87	0.9	1.82	0.0	2.3	N/F	N/F	N/F	N/F	N/F	N/F
Fourth	R4	W06-L	Unknown	30.2	29.0	1.2	4.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											0.7		0.6									
		W07-L		30.6	29.3	1.3	4.2						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						138.1	136.6	136.6	0.0	0.0	0.7	1.44	0.6	1.40	0.0	2.8						
Fourth	R5	W08	Unknown	36.6	35.3	1.3	3.6	140.0	136.4	136.4	0.0	0.0	1.1	1.05	1.0	1.02	0.0	3.0	N/F	N/F	N/F	N/F	N/F	N/F
Fourth	R6	W09	Unknown	38.7	37.2	1.4	3.7						1.1		1.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10		38.8	37.3	1.5	3.9	145.9	145.0	145.0	0.0	0.0	1.1	2.16	1.0	2.09	0.1	3.4	N/F	N/F	N/F	N/F	N/F	N/F
Fourth	R7	W11	Unknown	38.3	36.6	1.7	4.4						1.1		1.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12		36.6	34.8	1.8	4.9	143.2	142.4	142.3	0.0	0.0	1.0	2.11	1.0	2.03	0.1	4.0	N/F	N/F	N/F	N/F	N/F	N/F
Fourth	R8	W13-L	Unknown	31.8	29.8	2.1	6.5						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.5		0.5									
		W14-L		31.7	29.5	2.2	6.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											0.5		0.5									
		W15-L		37.9	31.8	6.1	16.2						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U						195.9	193.3	193.3	0.0	0.0	1.8	3.07	1.5	2.74	0.3	10.7						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Fourth	R9	W16-L	Unknown	20.9	18.5	2.3	11.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U											0.6		0.6									
		W17-L		35.8	30.6	5.2	14.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											1.7		1.5									
		W18-L		39.3	33.3	6.0	15.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U											1.8		1.6									
		W19-L		35.9	32.3	3.6	10.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U											1.7		1.5									
		W20-L		20.8	19.8	1.1	5.0						0.0		0.0				15	2	15	2	1.0	1.0
		W20-U						157.8	155.6	155.6	0.0	0.0	0.6	6.86	0.6	6.14	0.7	10.5						
Fourth	R10	W21	Unknown	37.3	31.8	5.5	14.7						0.9		0.8				N/F	N/F	N/F	N/F	N/F	N/F
		W22		39.3	38.3	1.0	2.5	127.7	125.9	125.9	0.0	0.0	1.0	1.89	1.0	1.75	0.1	7.3	59	20	59	20	1.0	1.0
Fourth	R11	W23	Unknown	38.4	37.6	0.8	2.0	211.9	188.4	188.4	0.0	0.0	0.4	0.45	0.4	0.44	0.0	1.8	54	18	54	18	1.0	1.0
Fourth	R12	W24	Unknown	39.1	38.2	0.8	2.1						0.8		0.8				55	18	55	18	1.0	1.0
		W25		38.9	38.1	0.8	2.1	207.9	202.1	202.1	0.0	0.0	0.8	1.68	0.8	1.65	0.0	1.7	53	18	53	18	1.0	1.0
Fourth	R13	W26	Unknown	37.4	36.6	0.8	2.1	121.4	118.8	118.8	0.0	0.0	1.2	1.16	1.1	1.15	0.0	1.6	46	14	46	14	1.0	1.0
Fourth	R14	W27-L	Unknown	31.7	30.9	0.8	2.4						0.1		0.1				48	20	48	20	1.0	1.0
		W27-U											0.6		0.6									
		W28-L		31.7	30.9	0.8	2.4						0.1		0.1				57	20	57	20	1.0	1.0
		W28-U						153.6	150.9	150.9	0.0	0.0	0.6	1.35	0.6	1.33	0.0	1.5						
Fourth	R15	W29	Unknown	37.3	36.6	0.7	1.9	109.5	107.6	107.6	0.0	0.0	1.2	1.24	1.2	1.22	0.0	1.4	59	20	59	20	1.0	1.0
Fourth	R16	W30	Unknown	38.8	38.1	0.7	1.8	114.8	112.7	112.7	0.0	0.0	1.3	1.25	1.2	1.23	0.0	1.4	59	20	59	20	1.0	1.0
Fifth	R1	W01-L	Unknown	32.0	31.5	0.6	1.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.5		0.5									
		W02-L		32.0	31.4	0.6	1.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						230.7	218.6	218.6	0.0	0.0	0.5	1.02	0.5	1.01	0.0	1.2						
Fifth	R2	W03	Unknown	25.8	25.2	0.6	2.4	92.4	90.5	90.5	0.0	0.0	1.0	1.02	1.0	1.01	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
Fifth	R3	W04	Unknown	32.9	32.3	0.6	1.9						0.9		0.9				N/F	N/F	N/F	N/F	N/F	N/F
		W05		33.7	33.1	0.7	2.0	147.6	146.5	146.5	0.0	0.0	1.0	1.88	0.9	1.86	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
Fifth	R4	W06-L	Unknown	30.7	29.9	0.8	2.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											0.7		0.6									
		W07-L		31.0	30.1	0.8	2.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						138.1	136.7	136.7	0.0	0.0	0.7	1.45	0.7	1.43	0.0	1.7						
Fifth	R5	W08	Unknown	36.8	36.0	0.8	2.2	140.0	136.4	136.4	0.0	0.0	1.1	1.05	1.0	1.03	0.0	1.8	N/F	N/F	N/F	N/F	N/F	N/F
Fifth	R6	W09	Unknown	39.0	38.1	0.9	2.3						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W10		39.1	38.1	0.9	2.4	145.9	145.0	145.0	0.0	0.0	1.1	2.16	1.1	2.12	0.0	2.1	N/F	N/F	N/F	N/F	N/F	N/F
Fifth	R7	W11	Unknown	38.5	37.4	1.1	2.7						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F
		W12		36.8	35.7	1.1	3.0	143.2	142.4	142.4	0.0	0.0	1.0	2.11	1.0	2.06	0.1	2.4	N/F	N/F	N/F	N/F	N/F	N/F
Fifth	R8	W13-L	Unknown	32.0	30.7	1.3	4.0						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.5		0.5									
		W14-L		31.9	30.6	1.3	4.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											0.5		0.5									
		W15-L		38.0	33.6	4.4	11.6						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U						195.9	193.1	193.1	0.0	0.0	1.8	3.08	1.6	2.84	0.2	7.6						
Fifth	R9	W16-L	Unknown	20.9	19.5	1.5	6.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U											0.6		0.6									
		W17-L		36.0	32.4	3.6	9.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											1.7		1.5									
		W18-L		39.4	35.0	4.4	11.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U											1.8		1.6									
		W19-L		36.0	33.2	2.8	7.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U											1.7		1.6									
		W20-L		20.9	20.1	0.9	4.2						0.0		0.0				15	2	15	2	1.0	1.0
		W20-U						157.8	155.6	155.6	0.0	0.0	0.6	6.82	0.6	6.29	0.5	7.7						
Fifth	R10	W21	Unknown	37.4	33.3	4.1	10.9						0.9		0.8				N/F	N/F	N/F	N/F	N/F	N/F
		W22		39.4	38.6	0.8	2.1	127.7	125.9	125.9	0.0	0.0	1.0	1.85	1.0	1.75	0.1	5.6	59	20	59	20	1.0	1.0
Fifth	R11	W23	Unknown	38.5	37.9	0.6	1.6	211.9	188.5	188.5	0.0	0.0	0.4	0.45	0.4	0.44	0.0	1.5	54	18	54	18	1.0	1.0
Fifth	R12	W24	Unknown	39.2	38.6	0.7	1.8						0.8		0.8				56	18	56	18	1.0	1.0
		W25		39.1	38.4	0.7	1.7	207.9	202.1	202.1	0.0	0.0	0.8	1.66	0.8	1.63	0.0	1.4	56	18	56	18	1.0	1.0
Fifth	R13	W26	Unknown	37.6	36.9	0.6	1.7	121.4	118.8	118.8	0.0	0.0	1.1	1.14	1.1	1.13	0.0	1.3	46	14	46	14	1.0	1.0
Fifth	R14	W27-L	Unknown	31.9	31.2	0.6	2.0						0.1		0.1				48	20	48	20	1.0	1.0
		W27-U											0.6		0.6									
		W28-L		31.9	31.3	0.6	2.0						0.1		0.1				57	20	57	20	1.0	1.0
		W28-U						153.6	150.9	150.9	0.0	0.0	0.6	1.33	0.6	1.32	0.0	1.2						
Fifth	R15	W29	Unknown	37.5	36.9	0.6	1.5	109.5	107.6	107.6	0.0	0.0	1.2	1.21	1.2	1.20	0.0	1.2	59	20	59	20	1.0	1.0
Fifth	R16	W30	Unknown	39.0	38.4	0.6	1.5	114.8	112.7	112.7	0.0	0.0	1.2	1.23	1.2	1.21	0.0	1.2	59	20	59	20	1.0	1.0
Sixth	R1	W01-L	Unknown	39.6	39.3	0.3	0.7						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.6		0.6									
		W02-L		39.6	39.3	0.3	0.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						230.7	218.6	218.6	0.0	0.0	0.6	1.32	0.6	1.31	0.0	0.6						
Sixth	R2	W03	Unknown	27.0	26.7	0.3	1.2	92.4	91.6	91.6	0.0	0.0	1.1	1.05	1.0	1.04	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Sixth	R3	W04	Unknown	34.8	34.5	0.4	1.0						1.0		1.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05		35.5	35.2	0.4	1.0	147.6	147.0	147.0	0.0	0.0	1.0	1.96	1.0	1.94	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
Sixth	R4	W06-L	Unknown	31.2	30.8	0.4	1.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											0.7		0.7									
		W07-L		31.4	30.9	0.4	1.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						138.1	136.9	136.9	0.0	0.0	0.7	1.45	0.7	1.44	0.0	0.9						
Sixth	R5	W08	Unknown	37.4	37.0	0.4	1.1	140.0	137.1	137.1	0.0	0.0	1.1	1.06	1.1	1.05	0.0	1.0	N/F	N/F	N/F	N/F	N/F	N/F
Sixth	R6	W09	Unknown	39.3	38.8	0.5	1.2						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F
		W10		39.4	38.9	0.5	1.3	145.9	145.0	145.0	0.0	0.0	1.1	2.17	1.1	2.14	0.0	1.1	N/F	N/F	N/F	N/F	N/F	N/F
Sixth	R7	W11	Unknown	39.0	38.4	0.5	1.4						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F
		W12		37.4	36.9	0.6	1.5	143.2	142.4	142.4	0.0	0.0	1.0	2.13	1.0	2.10	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
Sixth	R8	W13-L	Unknown	32.0	31.3	0.7	2.2						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.5		0.5									
		W14-L		31.9	31.1	0.7	2.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											0.5		0.5									
		W15-L		38.0	35.1	3.0	7.9						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U						195.9	193.1	193.1	0.0	0.0	1.8	3.08	1.6	2.92	0.2	5.1						
Sixth	R9	W16-L	Unknown	21.1	20.3	0.8	3.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U											0.6		0.6									
		W17-L		36.2	34.0	2.2	6.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											1.7		1.6									
		W18-L		39.4	36.4	3.0	7.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U											1.8		1.7									
		W19-L		36.3	34.2	2.1	5.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U											1.7		1.6									
		W20-L		21.1	20.4	0.7	3.3						0.0		0.0				15	2	15	2	1.0	1.0
		W20-U						157.8	155.6	155.6	0.0	0.0	0.6	6.91	0.6	6.54	0.4	5.3						
Sixth	R10	W21	Unknown	37.5	34.6	2.9	7.6						0.9		0.8				N/F	N/F	N/F	N/F	N/F	N/F
		W22		39.5	38.8	0.6	1.6	127.7	125.9	125.9	0.0	0.0	1.0	1.90	1.0	1.82	0.1	4.1	59	20	59	20	1.0	1.0
Sixth	R11	W23	Unknown	38.6	38.1	0.5	1.2	211.9	188.3	188.3	0.0	0.0	0.5	0.45	0.4	0.44	0.0	1.1	54	18	54	18	1.0	1.0
Sixth	R12	W24	Unknown	39.4	38.9	0.5	1.4						0.8		0.8				58	19	58	19	1.0	1.0
		W25		39.3	38.8	0.5	1.3	207.9	202.1	202.1	0.0	0.0	0.8	1.69	0.8	1.67	0.0	1.2	58	19	58	19	1.0	1.0
Sixth	R13	W26	Unknown	38.2	37.6	0.5	1.4	121.4	118.8	118.8	0.0	0.0	1.2	1.18	1.2	1.17	0.0	1.1	51	14	51	14	1.0	1.0
Sixth	R14	W27-L	Unknown	31.8	31.3	0.5	1.6						0.1		0.1				48	20	48	20	1.0	1.0
		W27-U											0.6		0.6									
		W28-L		31.9	31.4	0.5	1.6						0.1		0.1				57	20	57	20	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W28-U						153.6	150.8	150.8	0.0	0.0	0.6	1.36	0.6	1.34	0.0	1.0						
Sixth	R15	W29	Unknown	38.1	37.6	0.5	1.2	109.5	107.6	107.6	0.0	0.0	1.3	1.25	1.2	1.24	0.0	1.0	59	20	59	20	1.0	1.0
Sixth	R16	W30	Unknown	39.3	38.8	0.4	1.1	114.8	112.7	112.7	0.0	0.0	1.3	1.26	1.2	1.24	0.0	1.0	59	20	59	20	1.0	1.0
Seventh	R1	W01	Unknown	39.6	39.5	0.2	0.4						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02		39.6	39.5	0.2	0.4	147.5	146.7	146.7	0.0	0.0	1.1	2.15	1.1	2.14	0.0	0.4	N/F	N/F	N/F	N/F	N/F	N/F
Seventh	R2	W03-L	Unknown	39.6	39.4	0.2	0.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.9		0.9									
		W04-L		39.6	39.4	0.2	0.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						138.1	137.1	137.1	0.0	0.0	0.9	1.88	0.9	1.88	0.0	0.4						
Seventh	R3	W05	Unknown	39.6	39.4	0.2	0.5						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06		39.6	39.4	0.2	0.5	140.0	139.5	139.5	0.0	0.0	1.1	2.22	1.1	2.21	0.0	0.4	N/F	N/F	N/F	N/F	N/F	N/F
Seventh	R4	W07	Unknown	39.6	39.4	0.2	0.6	145.9	143.0	143.0	0.0	0.0	1.1	1.08	1.1	1.08	0.0	0.5	N/F	N/F	N/F	N/F	N/F	N/F
Seventh	R5	W08	Unknown	39.6	39.4	0.2	0.6						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09		39.6	39.4	0.3	0.6	143.2	142.4	142.4	0.0	0.0	1.1	2.19	1.1	2.18	0.0	0.5	N/F	N/F	N/F	N/F	N/F	N/F
Seventh	R6	W10-L	Unknown	39.6	39.3	0.3	0.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U											0.7		0.7									
		W11-L		39.6	39.3	0.3	0.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.7		0.7									
		W12-L		38.1	36.2	1.9	5.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						195.9	193.3	193.3	0.0	0.0	1.8	3.42	1.7	3.32	0.1	2.9						
Seventh	R7	W13-L	Unknown	21.8	21.5	0.3	1.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.6		0.6									
		W14-L		37.1	35.8	1.3	3.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											1.8		1.7									
		W15-L		39.5	37.6	1.9	4.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											1.8		1.8									
		W16-L		37.1	35.6	1.5	4.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U											1.8		1.7									
		W17-L		21.9	21.4	0.5	2.4						0.0		0.0				15	2	15	2	1.0	1.0
		W17-U						157.8	155.6	155.6	0.0	0.0	0.6	7.12	0.6	6.87	0.2	3.4						
Seventh	R8	W18	Unknown	37.5	35.7	1.9	4.9						0.9		0.9				N/F	N/F	N/F	N/F	N/F	N/F
		W19		39.5	39.0	0.5	1.2	127.7	125.9	125.9	0.0	0.0	1.0	1.90	1.0	1.85	0.1	2.8	59	20	59	20	1.0	1.0
Seventh	R9	W20	Unknown	38.9	38.6	0.4	1.0	211.9	192.3	192.3	0.0	0.0	0.4	0.44	0.4	0.44	0.0	0.9	57	18	57	18	1.0	1.0
Seventh	R10	W21	Unknown	39.5	39.1	0.4	1.0						0.8		0.8				59	20	59	20	1.0	1.0
		W22		39.5	39.1	0.4	1.0	207.9	202.3	202.3	0.0	0.0	0.8	1.69	0.8	1.68	0.0	0.9	59	20	59	20	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Seventh	R11	W23-L	Unknown	39.5	39.1	0.4	1.0						0.1		0.1				59	20	59	20	1.0	1.0
		W23-U											0.8		0.8									
		W24-L		39.5	39.1	0.4	1.0						0.1		0.1				59	20	59	20	1.0	1.0
		W24-U						153.6	150.8	150.8	0.0	0.0	0.8	1.75	0.8	1.74	0.0	0.8						
Eighth	R1	W01-L	Unknown	36.7	36.6	0.1	0.2						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						295.7	295.7	295.7	0.0	0.0	5.2	5.56	5.2	5.55	0.0	0.1						
Eighth	R2	W02-L	Unknown	36.7	36.6	0.1	0.2						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						295.5	295.5	295.5	0.0	0.0	5.2	5.56	5.2	5.55	0.0	0.2						
Eighth	R3	W03-L	Unknown	36.7	36.6	0.1	0.2						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											5.0		5.0									
		W04-L		30.6	29.8	0.8	2.6						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						196.0	196.0	196.0	0.0	0.0	6.1	11.78	6.0	11.66	0.1	1.1						
Eighth	R4	W05-L	Unknown	24.6	24.5	0.1	0.5						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											3.5		3.5									
		W06-L		32.0	31.8	0.1	0.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.3		1.3									
		W07-L		39.3	38.6	0.6	1.7						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											2.9		2.8									
		W08-L		39.5	38.4	1.1	2.8						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											2.8		2.7									
		W09-L		39.4	38.4	1.0	2.4						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											2.9		2.8									
		W10-L		33.2	32.8	0.3	1.1						0.1		0.1				38	6	38	6	1.0	1.0
		W10-U											1.3		1.3									
		W11-L		25.4	25.1	0.3	1.3						0.2		0.2				18	2	18	2	1.0	1.0
		W11-U						82.6	82.6	82.6	0.0	0.0	3.6	19.56	3.5	19.28	0.3	1.4						
Eighth	R5	W12-L	Unknown	28.5	27.6	0.9	3.2						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											4.5		4.4									
		W13-L		36.9	36.6	0.3	0.8						0.3		0.3				51	18	51	18	1.0	1.0
		W13-U						164.7	164.7	164.7	0.0	0.0	5.4	10.55	5.4	10.40	0.1	1.4						
Eighth	R6	W14-L	Unknown	36.9	36.6	0.3	0.8						0.4		0.4				51	18	51	18	1.0	1.0
		W14-U						295.5	295.5	295.5	0.0	0.0	5.2	5.58	5.2	5.55	0.0	0.6						
Eighth	R7	W15-L	Unknown	36.9	36.6	0.3	0.7						0.4		0.4				52	19	52	19	1.0	1.0
		W15-U						295.8	295.8	295.8	0.0	0.0	5.2	5.59	5.2	5.56	0.0	0.6						
Ninth	R1	W01	Unknown	37.2	37.2	0.0	0.0						5.9		5.9				N/F	N/F	N/F	N/F	N/F	N/F
		W02		37.2	37.1	0.1	0.3	42.3	42.3	42.3	0.0	0.0	5.9	11.76	5.9	11.74	0.0	0.2	53	20	53	20	1.0	1.0
Ninth	R2	W03	Unknown	37.2	37.2	0.0	0.0						2.7		2.7				N/F	N/F	N/F	N/F	N/F	N/F
		W04-L		38.8	38.7	0.0	0.1						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											5.2		5.2									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W05-L		39.1	38.9	0.3	0.6						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											2.7		2.7									
		W06-L		39.0	38.5	0.5	1.3						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											2.6		2.6									
		W07-L		39.1	38.6	0.5	1.3						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											2.7		2.7									
		W08-L		38.8	38.6	0.2	0.5						0.4		0.4				55	20	55	20	1.0	1.0
		W08-U											5.2		5.2									
		W09		37.2	37.0	0.1	0.4	82.6	82.6	82.6	0.0	0.0	2.7	25.24	2.7	25.11	0.1	0.5	51	18	51	18	1.0	1.0
The Tapestry																								
First	R1	W01	Unknown	27.1	23.3	3.8	14.1	141.8	131.1	105.0	26.1	19.9	1.4	1.37	1.2	1.23	0.1	10.2	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02	Unknown	26.1	22.4	3.8	14.5						0.8		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W03		26.0	22.0	4.0	15.3	141.8	136.5	121.0	15.5	11.3	0.8	1.56	0.7	1.39	0.2	10.7	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W04	Unknown	27.1	22.6	4.5	16.5						1.1		0.9				N/F	N/F	N/F	N/F	N/F	N/F
		W05		34.6	32.9	1.7	5.0	214.0	211.5	209.8	1.7	0.8	0.9	1.97	0.9	1.80	0.2	8.4	58	21	55	21	0.9	1.0
3 to 9 Lower Richmond Road																								
Ground	R3	W03	Living Room	20.3	17.6	2.7	13.1						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W04		28.8	25.0	3.8	13.1						1.7		1.5				N/F	N/F	N/F	N/F	N/F	N/F
		W05		20.6	17.7	2.9	14.0	139.9	139.0	122.7	16.4	11.8	0.3	2.32	0.3	2.11	0.2	9.2	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W06	Living Room	18.7	16.4	2.3	12.3						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W07		28.9	25.4	3.5	12.2						1.7		1.5				N/F	N/F	N/F	N/F	N/F	N/F
		W08		21.9	19.2	2.7	12.4	139.9	139.0	124.6	14.4	10.3	0.3	2.33	0.3	2.13	0.2	8.5	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R7	W13	Living Room	19.5	17.2	2.4	12.1						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W14		29.6	26.5	3.1	10.5						1.7		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W15		21.9	19.7	2.2	10.1	139.9	139.0	131.6	7.4	5.3	0.3	2.36	0.3	2.19	0.2	7.4	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R8	W16	Living Room	18.8	16.7	2.1	11.2						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W17		30.2	27.2	2.9	9.7						1.7		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W18		23.5	21.6	2.0	8.3	139.9	139.0	135.1	3.9	2.8	0.4	2.40	0.3	2.23	0.2	6.9	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02-L	Bedroom	31.5	27.5	4.0	12.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						137.0	94.1	70.0	24.1	25.6	1.3	1.26	1.1	1.14	0.1	9.9						
First	R3	W03-L	Bedroom	31.6	27.8	3.8	12.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						137.0	90.0	72.2	17.8	19.8	1.2	1.19	1.1	1.07	0.1	9.5						
First	R6	W06-L	Bedroom	32.4	28.9	3.4	10.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						137.0	103.7	88.9	14.8	14.2	1.3	1.29	1.2	1.18	0.1	8.5						
First	R7	W07-L	Bedroom	32.8	29.5	3.3	10.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W07-U						137.0	110.7	101.0	9.6	8.7	1.3	1.31	1.2	1.20	0.1	8.2						
35 Lower Richmond Road																								
Ground	R1	W01-L	Class Room	18.6	18.5	0.1	0.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.5		0.5									
		W12-L		11.7	11.3	0.4	3.3						0.0		0.0				19	7	19	7	1.0	1.0
		W12-U											0.3		0.3									
		W13		12.8	12.5	0.3	2.1						0.0		0.0				22	6	22	6	1.0	1.0
		W14		12.9	12.6	0.2	1.9						0.0		0.0				22	6	22	6	1.0	1.0
		W15-L		11.3	11.1	0.2	1.8						0.0		0.0				24	6	24	6	1.0	1.0
		W15-U						352.7	243.1	243.1	0.0	0.0	0.3	1.23	0.3	1.23	0.0	0.7						
Ground	R3	W03-L	Class Room	6.1	5.7	0.4	7.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.1		0.1									
		W04-L		12.7	12.0	0.7	5.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.3		0.3									
		W05		16.4	15.5	0.9	5.5						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W06-L		19.2	18.2	1.0	5.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											0.4		0.3									
		W07		34.9	32.8	2.1	6.0						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W08		34.8	32.7	2.1	6.1						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		27.2	26.6	0.6	2.1						0.0		0.0				39	6	39	6	1.0	1.0
		W09-U											0.4		0.4									
		W10-L		20.1	19.6	0.5	2.5						0.0		0.0				28	5	28	5	1.0	1.0
		W10-U						356.1	354.1	345.0	9.1	2.6	0.4	2.53	0.4	2.42	0.1	4.4						
Ground	R4	W11-L	Class Room	13.2	12.8	0.4	3.2						0.0		0.0				17	5	17	5	1.0	1.0
		W11-U						147.7	42.6	42.6	0.0	0.0	0.7	0.70	0.7	0.69	0.0	1.4						
First	R1	W04	Class Room	18.5	17.8	0.7	3.6						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		27.3	26.9	0.4	1.5						0.0		0.0				43	9	43	9	1.0	1.0
		W09-U											0.2		0.2									
		W10-L		25.2	24.8	0.4	1.5						0.0		0.0				41	9	41	9	1.0	1.0
		W10-U											0.2		0.2									
		W11		23.4	23.1	0.3	1.5						0.3		0.3				39	9	39	9	1.0	1.0
		W12		21.3	21.0	0.3	1.4						0.9		0.9				36	11	36	11	1.0	1.0
		W13		23.3	23.1	0.2	0.7						0.9		0.9				39	16	39	16	1.0	1.0
		W15		6.4	6.4	0.0	0.0						0.1		0.1				17	2	17	2	1.0	1.0
		W16		83.5	83.4	0.1	0.1						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W17		81.4	81.0	0.4	0.5						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W18		36.6	35.3	1.3	3.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W19		84.9	84.7	0.2	0.3						0.4		0.4				82	21	82	21	1.0	1.0
		W20		83.5	83.3	0.2	0.2						0.4		0.4				80	21	80	21	1.0	1.0
		W21		84.1	83.9	0.1	0.2	700.4	700.4	700.4	0.0	0.0	0.4	4.81	0.4	4.78	0.0	0.6	76	24	76	24	1.0	1.0
First	R2	W05-L	Class Room	20.0	19.1	0.9	4.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.2		0.2									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W06		23.8	22.6	1.1	4.7						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W07		34.8	33.1	1.8	5.0						2.8		2.6				N/F	N/F	N/F	N/F	N/F	N/F
		W08		28.7	28.3	0.4	1.5	165.2	164.0	163.9	0.0	0.0	0.5	3.97	0.5	3.82	0.1	3.8	45	11	45	11	1.0	1.0
39-41 Lower Richmond Road																								
Ground	R2	W04-L	Dining Room	28.4	27.5	0.9	3.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						138.1	134.2	134.2	0.0	0.0	1.5	1.58	1.5	1.54	0.0	2.8						
First	R1	W01	Living Room	33.0	32.0	1.0	3.0	138.1	134.9	134.9	0.0	0.0	2.3	2.26	2.2	2.21	0.1	2.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02-L	Living Room	35.6	34.3	1.3	3.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						138.1	135.0	135.0	0.0	0.0	1.8	1.86	1.7	1.80	0.1	3.2						
Second	R1	W01-L	Bedroom	33.2	32.5	0.8	2.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						138.1	134.4	134.4	0.0	0.0	1.7	1.76	1.7	1.73	0.0	1.9						
Second	R2	W02-L	Bedroom	34.2	33.2	1.0	2.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						138.1	134.9	134.9	0.0	0.0	1.6	1.69	1.6	1.65	0.0	2.4						
43 to 51 Lower Richmond Road																								
Ground	R2	W02	Unknown	36.3	35.0	1.3	3.6	121.9	118.8	118.8	0.0	0.0	1.8	1.85	1.8	1.78	0.1	3.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W04-L	Unknown	36.4	35.1	1.3	3.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						143.4	141.2	141.2	0.0	0.0	1.9	1.94	1.8	1.87	0.1	3.3						
Ground	R5	W05-L	Unknown	36.4	35.1	1.3	3.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						108.3	107.2	107.2	0.0	0.0	2.3	2.35	2.2	2.27	0.1	3.2						
Ground	R8	W08-L	Unknown	36.6	35.5	1.1	2.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						107.9	106.9	106.9	0.0	0.0	2.3	2.37	2.3	2.30	0.1	2.7						
Ground	R10	W10	Unknown	33.9	33.9	0.0	0.0	67.4	62.5	62.5	0.0	0.0	2.9	2.92	2.9	2.92	0.0	0.0	50	13	50	13	1.0	1.0
First	R1	W01	Unknown	36.8	35.7	1.1	2.9	113.8	111.7	111.7	0.0	0.0	2.0	1.95	1.9	1.90	0.1	2.7	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02	Unknown	36.8	35.8	1.0	2.7	130.9	128.5	128.5	0.0	0.0	1.8	1.78	1.7	1.74	0.0	2.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W03-L	Unknown	36.8	35.8	1.0	2.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						125.4	123.5	123.5	0.0	0.0	2.0	2.14	2.0	2.09	0.1	2.5						
First	R4	W04-L	Unknown	36.9	36.0	1.0	2.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						143.4	141.4	141.4	0.0	0.0	1.9	1.97	1.8	1.92	0.0	2.5						
First	R5	W05-L	Unknown	36.7	35.8	0.9	2.6						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						108.3	107.2	107.2	0.0	0.0	2.3	2.50	2.3	2.44	0.1	2.4						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R6	W06-L	Unknown	36.9	36.1	0.9	2.4						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						86.8	86.6	86.6	0.0	0.0	2.7	2.86	2.6	2.80	0.1	2.2						
First	R7	W07-L	Unknown	37.0	36.2	0.8	2.2						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						86.7	86.4	86.4	0.0	0.0	2.7	2.87	2.6	2.81	0.1	2.1						
First	R8	W08-L	Unknown	36.9	36.1	0.8	2.1						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						107.9	107.0	107.0	0.0	0.0	2.3	2.51	2.3	2.46	0.0	1.9						
First	R9	W09	Unknown	37.3	36.6	0.7	1.9	94.5	93.7	93.7	0.0	0.0	3.5	3.51	3.5	3.45	0.1	1.7	N/F	N/F	N/F	N/F	N/F	N/F
First	R10	W10	Unknown	36.7	36.7	0.0	0.0	67.4	63.3	63.3	0.0	0.0	4.2	4.20	4.2	4.20	0.0	0.0	54	16	54	16	1.0	1.0
First	R11	W11-L	Unknown	32.6	32.6	0.0	0.0						0.2		0.2				37	9	37	9	1.0	1.0
		W11-U						45.8	44.8	44.8	0.0	0.0	3.5	3.76	3.5	3.76	0.0	0.0						
First	R12	W12-L	Unknown	36.6	36.6	0.0	0.0						0.1		0.1				59	21	59	21	1.0	1.0
		W12-U											1.1		1.1									
		W13-L		36.6	36.6	0.0	0.0						0.1		0.1				59	22	59	22	1.0	1.0
		W13-U						45.4	43.4	43.4	0.0	0.0	1.1	2.24	1.1	2.24	0.0	0.0						
First	R13	W14-L	Unknown	36.6	36.6	0.0	0.0						0.1		0.1				62	22	62	22	1.0	1.0
		W14-U						28.1	26.0	26.0	0.0	0.0	1.5	1.58	1.5	1.58	0.0	0.0						
Second	R1	W01	Unknown	34.4	33.6	0.8	2.2	113.8	112.3	112.3	0.0	0.0	1.7	1.75	1.7	1.71	0.0	1.9	N/F	N/F	N/F	N/F	N/F	N/F
Second	R2	W02	Unknown	34.4	33.7	0.7	2.1	130.9	129.0	129.1	0.0	0.0	1.6	1.59	1.6	1.56	0.0	1.8	N/F	N/F	N/F	N/F	N/F	N/F
Second	R3	W03-L	Unknown	31.8	31.1	0.7	2.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						125.4	123.5	123.5	0.0	0.0	1.2	1.23	1.2	1.20	0.0	1.8						
Second	R4	W04-L	Unknown	31.1	30.5	0.6	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						143.4	141.2	141.2	0.0	0.0	1.1	1.10	1.1	1.09	0.0	1.7						
Second	R5	W05-L	Unknown	30.8	30.2	0.6	2.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						108.3	107.2	107.2	0.0	0.0	1.3	1.34	1.3	1.32	0.0	1.6						
Second	R6	W06-L	Unknown	31.0	30.5	0.6	1.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						86.8	86.5	86.5	0.0	0.0	1.5	1.54	1.5	1.52	0.0	1.5						
Second	R7	W07-L	Unknown	31.0	30.4	0.5	1.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						86.7	86.4	86.4	0.0	0.0	1.5	1.54	1.5	1.51	0.0	1.4						
Second	R8	W08-L	Unknown	30.5	30.0	0.5	1.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						107.9	107.0	107.0	0.0	0.0	1.3	1.33	1.3	1.31	0.0	1.3						
Second	R9	W09-L	Unknown	32.0	31.6	0.5	1.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						94.5	93.6	93.6	0.0	0.0	1.4	1.43	1.4	1.42	0.0	1.2						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Second	R10	W10-L	Unknown	32.7	32.7	0.0	0.0						0.1		0.1				49	18	49	18	1.0	1.0
		W10-U						67.4	63.4	63.4	0.0	0.0	1.7	1.75	1.7	1.75	0.0	0.0						
Second	R11	W11-L	Unknown	33.1	33.1	0.0	0.0						0.1		0.1				52	20	52	20	1.0	1.0
		W11-U						45.8	44.8	44.8	0.0	0.0	2.3	2.36	2.3	2.36	0.0	0.0						
Second	R12	W12-L	Unknown	28.5	28.5	0.0	0.0						0.1		0.1				43	17	43	17	1.0	1.0
		W12-U											0.3		0.3									
		W13-L		28.4	28.4	0.0	0.0						0.1		0.1				43	17	43	17	1.0	1.0
		W13-U						45.4	43.2	43.2	0.0	0.0	0.3	0.81	0.3	0.81	0.0	0.0						
Second	R13	W14-L	Unknown	28.4	28.4	0.0	0.0						0.1		0.1				44	18	44	18	1.0	1.0
		W14-U						28.1	25.8	25.8	0.0	0.0	0.5	0.57	0.5	0.57	0.0	0.0						
51a to 55 Lower Richmond Road																								
Ground	R1	W01	Unknown	19.9	19.6	0.3	1.5						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W02		9.6	9.2	0.3	3.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03		19.8	19.4	0.4	2.0	60.6	58.0	58.0	0.0	0.0	0.7	1.46	0.7	1.44	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W04	Unknown	35.9	35.3	0.6	1.7	97.3	96.0	96.0	0.0	0.0	3.0	3.04	3.0	2.99	0.0	1.5	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W05	Unknown	36.5	36.1	0.4	1.1	229.8	226.3	226.3	0.0	0.0	1.8	1.84	1.8	1.82	0.0	1.1	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W06	Unknown	32.0	31.6	0.4	1.2	89.0	85.2	85.2	0.0	0.0	1.5	1.46	1.4	1.45	0.0	0.9	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W07	Unknown	32.4	31.9	0.5	1.4	37.1	35.2	35.2	0.0	0.0	2.6	2.60	2.6	2.57	0.0	1.2	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R6	W08	Unknown	2.1	2.1	0.0	0.0						0.1		0.1								1.0	1.0
		W09		4.9	4.9	0.0	0.0	53.4	23.7	23.7	0.0	0.0	0.4	0.49	0.4	0.49	0.0	0.0	23	12	23	12	1.0	1.0
First	R1	W01-L	Unknown	33.9	33.6	0.3	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						44.6	43.1	43.1	0.0	0.0	1.1	1.14	1.1	1.13	0.0	0.8						
First	R2	W02-L	Unknown	35.4	34.9	0.5	1.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						106.0	105.0	105.0	0.0	0.0	2.9	2.89	2.8	2.85	0.0	1.2						
First	R3	W03-L	Unknown	37.6	37.2	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						229.8	227.2	227.2	0.0	0.0	1.8	1.84	1.8	1.82	0.0	1.1						
First	R4	W04-L	Unknown	33.2	32.9	0.3	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						89.0	86.2	86.2	0.0	0.0	1.4	1.41	1.4	1.40	0.0	0.7						
First	R5	W05-L	Unknown	33.8	33.4	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						37.1	35.9	35.9	0.0	0.0	2.5	2.51	2.5	2.48	0.0	1.0						
57-59 Lower Richmond Road																								

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R1	W01-L	Living Room	37.0	36.6	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						142.6	141.3	141.3	0.0	0.0	3.7	3.72	3.7	3.68	0.0	1.0						
Ground	R4	W05-L	Living Room	12.5	12.0	0.4	3.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.4		0.4									
		W06-L		37.2	36.9	0.4	1.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											4.0		4.0									
		W07-L		20.8	20.8	0.0	0.0						0.0		0.0				13	0	13	0	1.0	0.0
		W07-U						143.6	143.3	143.3	0.0	0.0	0.5	5.01	0.5	4.97	0.0	0.9						
First	R1	W01-L	Bedroom	37.1	36.7	0.4	0.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						108.7	105.6	105.6	0.0	0.0	1.4	1.44	1.4	1.43	0.0	0.9						
First	R2	W02-L	Bedroom	37.2	36.8	0.4	0.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						66.9	66.2	66.2	0.0	0.0	2.0	2.09	2.0	2.07	0.0	0.9						
First	R3	W03-L	Bedroom	37.2	36.9	0.3	0.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						68.4	67.6	67.6	0.0	0.0	2.0	2.06	2.0	2.05	0.0	0.8						
First	R4	W04-L	Bedroom	37.2	36.9	0.3	0.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						105.0	102.3	102.3	0.0	0.0	1.4	1.51	1.4	1.50	0.0	0.8						
61-63 Lower Richmond Road																								
Ground	R2	W02	Unknown	35.4	35.1	0.4	1.0	304.7	300.8	300.8	0.0	0.0	1.3	1.33	1.3	1.32	0.0	0.9	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W03	Unknown	35.4	35.1	0.3	0.9	298.9	293.5	293.5	0.0	0.0	1.3	1.32	1.3	1.31	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01-L	Unknown	29.4	29.1	0.3	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						53.2	50.7	50.7	0.0	0.0	1.3	1.31	1.3	1.30	0.0	0.9						
First	R2	W02-L	Unknown	37.5	37.2	0.3	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						150.9	145.0	145.0	0.0	0.0	1.3	1.28	1.2	1.27	0.0	0.9						
First	R3	W03-L	Unknown	37.5	37.2	0.3	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						150.9	145.3	145.3	0.0	0.0	1.3	1.28	1.2	1.27	0.0	0.9						
First	R4	W04-L	Unknown	29.9	29.8	0.2	0.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						53.2	50.7	50.7	0.0	0.0	1.3	1.33	1.3	1.32	0.0	0.5						
67 Lower Richmond Road																								
Ground	R2	W03	Dining Room	33.0	32.7	0.3	0.8						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F
		W04		21.2	21.0	0.2	0.9	168.3	160.1	160.1	0.0	0.0	0.4	1.50	0.4	1.49	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W05	Living Room	30.2	30.2	0.0	0.0						0.1		0.1				49	14	49	14	1.0	1.0
		W06-L		16.6	16.6	0.0	0.0						0.0		0.0				43	9	43	9	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W06-U											0.2		0.2									
		W07-L		11.5	11.5	0.0	0.0						0.0		0.0				29		29		1.0	1.0
		W07-U											0.2		0.2									
		W08-L		25.5	25.5	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						367.3	319.3	319.3	0.0	0.0	1.1	1.67	1.1	1.67	0.0	0.0						
Ground	R4	W09-L	Kitchen	19.1	19.1	0.0	0.0						0.1		0.1				42	10	42	10	1.0	1.0
		W09-U											0.6		0.6									
		W10-L		29.0	28.9	0.1	0.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						104.0	102.0	102.0	0.0	0.0	1.8	2.50	1.8	2.49	0.0	0.2						
Ground	R5	W11	Unknown	11.9	11.9	0.0	0.0						0.4		0.4				11	0	11	0	1.0	0.0
		W12-L		22.4	22.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											1.3		1.3									
		W13		32.4	32.4	0.0	0.0	97.8	97.8	97.8	0.0	0.0	1.3	3.09	1.3	3.09	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01-L	Bedroom	37.5	37.2	0.3	0.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											1.1		1.1									
		W02-L		37.5	37.2	0.3	0.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						153.2	152.3	152.3	0.0	0.0	1.2	2.32	1.1	2.31	0.0	0.7						
First	R2	W03-L	Bedroom	31.0	31.0	0.0	0.0						0.0		0.0				77	18	77	18	1.0	1.0
		W03-U											0.7		0.7									
		W04-L		35.1	35.1	0.0	0.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.7		0.7									
		W05-L		33.0	33.0	0.0	0.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						219.1	218.4	218.4	0.0	0.0	0.7	2.08	0.7	2.08	0.0	0.0						
Second	R1	W01-L	Unknown	34.8	34.5	0.3	0.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						89.2	0.0	0.0	0.0	0.0	0.0	0.03	0.0	0.03	0.0	0.5						
Lady Elizabeth House																								
Ground	R1	W01-L	LD	34.2	34.2	0.0	0.0						0.0		0.0				47	12	47	12	1.0	1.0
		W01-U						153.0	151.5	151.5	0.0	0.0	2.2	2.21	2.2	2.21	0.0	0.0						
Ground	R2	W02	LD	23.0	22.7	0.3	1.1	39.3	36.6	36.6	0.0	0.0	0.6	0.58	0.6	0.57	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W03	Kitchen	36.4	36.1	0.3	0.7	55.0	52.7	52.7	0.0	0.0	1.6	1.64	1.6	1.63	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W06	Kitchen	30.3	30.0	0.3	0.9	57.8	54.2	54.2	0.0	0.0	1.4	1.35	1.3	1.35	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R6	W07	LD	37.2	36.9	0.3	0.7	195.0	188.4	188.4	0.0	0.0	1.8	1.84	1.8	1.83	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R7	W08	Bedroom	30.4	30.1	0.3	0.9	133.2	130.3	130.3	0.0	0.0	1.1	1.13	1.1	1.12	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R8	W09-L	LD	30.8	30.6	0.2	0.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						194.4	191.1	191.1	0.0	0.0	1.3	1.34	1.3	1.33	0.0	0.4						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R9	W10	Bedroom	27.7	27.6	0.1	0.4	132.5	130.0	130.0	0.0	0.0	1.1	1.06	1.1	1.06	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R10	W11	LD	18.2	18.1	0.2	0.9						0.8		0.8				N/F	N/F	N/F	N/F	N/F	N/F
		W12		17.7	17.7	0.0	0.0	37.0	26.5	26.5	0.0	0.0	0.8	1.52	0.8	1.52	0.0	0.3	37	13	37	13	1.0	1.0
Ground	R11	W13-L	Living Room	29.1	28.9	0.2	0.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											1.0		1.0									
		W14-L		29.8	29.6	0.2	0.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											1.0		1.0									
		W15-L		27.3	27.2	0.1	0.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.9		0.9									
		W16-L		31.3	31.3	0.0	0.0						0.1		0.1				54	20	54	20	1.0	1.0
		W16-U											1.0		1.0									
		W17-L		28.0	28.0	0.0	0.0						0.1		0.1				59	17	59	17	1.0	1.0
		W17-U						386.2	386.2	386.2	0.0	0.0	0.9	5.18	0.9	5.17	0.0	0.2						
Ground	R12	W18	Bedroom	29.1	29.1	0.0	0.0	132.9	130.4	130.4	0.0	0.0	1.1	1.10	1.1	1.10	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R13	W19-L	LD	31.9	31.9	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						194.6	192.7	192.7	0.0	0.0	1.3	1.38	1.3	1.38	0.0	0.0						
Ground	R14	W20-L	LD	31.9	31.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U						194.6	191.7	191.7	0.0	0.0	1.3	1.28	1.3	1.28	0.0	0.0						
Ground	R15	W21	Bedroom	34.5	34.5	0.0	0.0	132.6	129.8	129.8	0.0	0.0	1.3	1.26	1.3	1.26	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R16	W22	Bedroom	35.2	35.1	0.0	0.0	131.6	129.2	129.2	0.0	0.0	1.3	1.29	1.3	1.29	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R17	W23	LD	34.7	34.7	0.0	0.0	195.3	181.3	181.3	0.0	0.0	0.9	0.94	0.9	0.94	0.0	0.0	85	27	85	27	1.0	1.0
First	R1	W01-L	LD	37.2	36.9	0.3	0.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						195.7	189.4	189.4	0.0	0.0	2.0	1.97	2.0	1.96	0.0	0.7						
First	R2	W02	Kitchen	37.2	37.0	0.3	0.7	55.0	52.7	52.7	0.0	0.0	1.7	1.69	1.7	1.68	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W04	Kitchen	36.3	36.0	0.3	0.8	57.8	55.0	55.0	0.0	0.0	1.6	1.59	1.6	1.58	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
First	R5	W05	LD	36.7	36.4	0.3	0.8						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W06-L		36.0	35.7	0.3	0.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.5		1.4									
		W07		35.9	35.6	0.3	0.9	195.0	193.7	193.7	0.0	0.0	0.5	2.54	0.5	2.52	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R6	W08	Bedroom	32.5	32.2	0.3	0.9	133.2	130.3	130.3	0.0	0.0	1.2	1.19	1.2	1.18	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R7	W09-L	LD	36.2	36.0	0.2	0.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						194.4	192.4	192.4	0.0	0.0	1.4	1.52	1.4	1.51	0.0	0.5						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R8	W10	Bedroom	36.8	36.6	0.1	0.4	132.5	130.1	130.1	0.0	0.0	1.3	1.33	1.3	1.33	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R10	W12	Bedroom	37.2	37.1	0.1	0.2	132.9	130.4	130.4	0.0	0.0	1.3	1.34	1.3	1.34	0.0	0.2	N/F	N/F	N/F	N/F	N/F	N/F
First	R11	W13-L	LD	36.9	36.8	0.1	0.2						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						194.6	192.7	192.7	0.0	0.0	1.4	1.54	1.4	1.54	0.0	0.2						
First	R12	W14-L	LD	34.3	34.2	0.0	0.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						194.6	191.8	191.8	0.0	0.0	1.3	1.36	1.3	1.36	0.0	0.1						
First	R13	W15	Bedroom	36.7	36.5	0.1	0.4	132.6	129.7	129.7	0.0	0.0	1.3	1.34	1.3	1.33	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R14	W16	Bedroom	37.1	36.9	0.1	0.3	131.6	129.2	129.2	0.0	0.0	1.4	1.36	1.4	1.35	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R15	W17	LD	37.1	37.0	0.1	0.4						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W18-L		36.9	36.8	0.1	0.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U											1.5		1.5									
		W19		37.2	37.0	0.1	0.4	195.3	194.5	194.5	0.0	0.0	0.5	2.58	0.5	2.57	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
Second	R1	W01	LD	35.6	35.6	0.0	0.0						0.6		0.6				46	16	46	16	1.0	1.0
		W02		35.9	35.7	0.3	0.7	349.6	338.4	338.4	0.0	0.0	0.6	1.17	0.6	1.16	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
Second	R3	W05	Kitchen	38.4	38.2	0.3	0.7	57.8	55.1	55.1	0.0	0.0	1.7	1.66	1.7	1.65	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
Second	R4	W06-L	LD	38.5	38.2	0.3	0.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						195.0	183.9	183.9	0.0	0.0	1.5	1.61	1.5	1.59	0.0	0.7						
Second	R5	W07	Bedroom	29.1	28.7	0.3	1.1	133.2	126.8	126.8	0.0	0.0	1.0	1.02	1.0	1.01	0.0	0.9	N/F	N/F	N/F	N/F	N/F	N/F
Second	R6	W08-L	LD	38.3	38.1	0.2	0.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						194.4	192.1	192.1	0.0	0.0	1.5	1.60	1.5	1.59	0.0	0.7						
Second	R7	W09	Bedroom	34.2	33.9	0.3	0.8	132.5	127.6	127.6	0.0	0.0	1.2	1.15	1.1	1.15	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
Second	R9	W11	Bedroom	34.3	34.0	0.3	0.8	132.9	129.4	129.4	0.0	0.0	1.2	1.16	1.1	1.15	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
Second	R10	W12-L	LD	38.4	38.2	0.3	0.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						194.6	192.7	192.7	0.0	0.0	1.5	1.60	1.5	1.59	0.0	0.7						
Second	R11	W13-L	LD	32.9	32.7	0.2	0.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						194.6	191.7	191.7	0.0	0.0	1.2	1.23	1.2	1.22	0.0	0.5						
Second	R12	W14	Bedroom	31.8	31.5	0.3	0.9	132.6	126.4	126.4	0.0	0.0	1.1	1.09	1.1	1.09	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
Second	R13	W15	Bedroom	32.0	31.7	0.3	0.9	131.6	125.2	125.2	0.0	0.0	1.1	1.10	1.1	1.09	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F

2 to 10 Waldeck Road

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R1	W01-L	eception Roor	26.5	25.2	1.4	5.1						0.2		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						184.4	182.8	182.8	0.0	0.0	1.9	2.06	1.8	1.98	0.1	4.2						
Ground	R4	W04	Bedroom	20.4	20.4	0.0	0.0						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W05		23.6	23.6	0.0	0.0	114.0	110.4	110.4	0.0	0.0	0.7	1.39	0.7	1.39	0.0	0.0	42	15	42	15	1.0	1.0
Ground	R5	W06	Bedroom	21.4	21.4	0.0	0.0						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W07		24.7	24.7	0.0	0.0	122.6	117.1	117.1	0.0	0.0	0.7	1.41	0.7	1.41	0.0	0.0	38	12	38	12	1.0	1.0
Ground	R6	W08	Unknown	22.2	22.2	0.0	0.0	57.3	35.4	35.4	0.0	0.0	0.9	0.92	0.9	0.92	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R7	W09	Unknown	23.9	23.9	0.0	0.0	40.2	29.7	29.7	0.0	0.0	1.3	1.32	1.3	1.32	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R8	W10	Unknown	29.1	29.1	0.0	0.0	40.2	29.4	29.4	0.0	0.0	1.5	1.52	1.5	1.52	0.0	0.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01-L	Bedroom	36.5	34.9	1.6	4.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.9		0.8									
		W02-L		36.3	34.7	1.6	4.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						174.5	171.8	171.8	0.0	0.0	0.9	1.85	0.8	1.77	0.1	4.0						
First	R3	W04-L	LKD	25.2	25.2	0.0	-0.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.3		0.3									
		W05-L		28.7	28.7	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.9		0.9									
		W06-L		29.4	29.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											0.9		0.9									
		W07-L		21.2	21.1	0.0	0.2						0.0		0.0				43	19	43	19	1.0	1.0
		W07-U											0.7		0.7									
		W08-L		27.9	27.8	0.0	0.1						0.0		0.0				48	18	48	18	1.0	1.0
		W08-U						380.8	380.8	380.8	0.0	0.0	0.9	3.74	0.9	3.73	0.0	0.1						
First	R4	W09-L	LKD	29.8	29.7	0.0	0.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											1.1		1.1									
		W10-L		28.7	28.7	0.0	0.0						0.0		0.0				38	10	38	10	1.0	1.0
		W10-U											1.1		1.1									
		W11-L		33.8	33.8	0.0	0.0						0.0		0.0				56	21	56	21	1.0	1.0
		W11-U						272.5	272.2	272.2	0.0	0.0	1.5	3.69	1.5	3.69	0.0	0.0						
First	R6	W13-L	LKD	30.4	30.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											1.3		1.3									
		W14-L		34.6	34.6	0.0	0.0						0.0		0.0				57	21	57	21	1.0	1.0
		W14-U											1.5		1.5									
		W15-L		35.1	35.1	0.0	0.0						0.0		0.0				57	21	57	21	1.0	1.0
		W15-U						296.9	296.7	296.7	0.0	0.0	1.5	4.29	1.5	4.29	0.0	0.0						
First	R8	W17-L	LKD	32.7	32.6	0.1	0.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											1.4		1.4									
		W18-L		35.4	35.4	0.0	0.0						0.0		0.0				56	20	56	20	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W18-U											1.5		1.5									
		W19-L		35.6	35.6	0.0	0.0						0.0		0.0				57	20	57	20	1.0	1.0
		W19-U						291.1	290.8	290.8	0.0	0.0	1.5	4.45	1.5	4.45	0.0	0.1						
Second	R1	W01-L	Bedroom	37.4	36.1	1.3	3.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						191.5	182.5	182.7	-0.3	-0.1	0.9	1.02	0.9	0.99	0.0	3.0						
3 to 9 Waldeck Road																								
Ground	R1	W01	Unknown	17.7	17.7	0.0	0.0	20.6	16.6	16.6	0.0	0.0	0.7	0.67	0.7	0.67	0.0	0.0	29	8	29	8	1.0	1.0
Ground	R2	W02	Unknown	17.1	17.1	0.0	0.0	94.9	40.1	40.1	0.0	0.0	1.0	1.03	1.0	1.03	0.0	0.0	31	9	31	9	1.0	1.0
Ground	R4	W05	Unknown	18.9	18.9	0.0	0.1	20.6	16.3	16.3	0.0	0.0	0.7	0.67	0.7	0.67	0.0	0.0	27	8	27	8	1.0	1.0
Ground	R5	W06	Unknown	19.3	19.3	0.0	0.2	20.6	16.2	16.2	0.0	0.0	0.7	0.67	0.7	0.67	0.0	0.0	29	10	29	10	1.0	1.0
Ground	R6	W07	Unknown	21.4	21.3	0.0	0.1	59.6	14.6	14.6	0.0	0.0	0.4	0.36	0.4	0.36	0.0	0.0	38	14	38	14	1.0	1.0
Ground	R7	W08	Unknown	29.2	29.0	0.2	0.8	86.7	86.1	86.1	0.0	0.0	1.4	1.37	1.4	1.36	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R8	W09	Unknown	28.0	27.8	0.2	0.8	86.7	81.8	81.8	0.0	0.0	1.3	1.33	1.3	1.32	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R9	W10	Unknown	31.4	31.3	0.2	0.5	86.7	86.1	86.1	0.0	0.0	1.4	1.44	1.4	1.44	0.0	0.4	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R10	W11	Unknown	32.3	32.1	0.2	0.5	79.1	78.8	78.8	0.0	0.0	1.5	1.55	1.5	1.54	0.0	0.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01-L	Unknown	2.5	2.5	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.1		0.1									
		W02-L		22.4	22.4	0.0	0.0						0.0		0.0				46	13	46	13	1.0	1.0
		W02-U											1.3		1.3									
		W03-L		15.4	15.4	0.0	0.0						0.0		0.0				37	12	37	12	1.0	1.0
		W03-U						97.5	80.8	80.8	0.0	0.0	0.4	1.84	0.4	1.84	0.0	0.0						
First	R2	W04	Unknown	23.7	23.7	0.0	0.0	34.0	32.0	32.0	0.0	0.0	1.0	0.96	1.0	0.96	0.0	0.0	38	12	38	12	1.0	1.0
First	R3	W05-L	Unknown	12.9	12.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.3		0.3									
		W06-L		27.2	27.2	0.0	0.0						0.0		0.0				48	13	48	13	1.0	1.0
		W06-U											1.5		1.5									
		W07-L		15.3	15.3	0.0	0.0						0.0		0.0				37	12	37	12	1.0	1.0
		W07-U						94.9	64.5	64.5	0.0	0.0	0.4	2.27	0.4	2.27	0.0	0.0						
First	R4	W08	Unknown	24.5	24.5	0.0	0.0	34.0	32.0	32.0	0.0	0.0	1.0	0.98	1.0	0.98	0.0	0.0	38	11	38	11	1.0	1.0
First	R5	W09-L	Unknown	14.9	14.8	0.1	0.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											0.4		0.4									
		W10-L		27.4	27.3	0.0	0.1						0.0		0.0				48	13	48	13	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W10-U											1.5		1.5									
		W11-L		15.4	15.4	0.0	0.0						0.0		0.0				37	12	37	12	1.0	1.0
		W11-U						94.9	60.0	60.0	0.0	0.0	0.4	2.31	0.4	2.30	0.0	0.1						
First	R6	W12	Unknown	24.5	24.5	0.0	0.0	34.0	32.0	32.0	0.0	0.0	1.0	0.98	1.0	0.98	0.0	0.0	39	12	39	12	1.0	1.0
First	R7	W13-L	Unknown	15.2	15.1	0.1	0.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.4		0.4									
		W14-L		27.6	27.5	0.0	0.1						0.0		0.0				49	14	49	14	1.0	1.0
		W14-U											1.5		1.5									
		W15-L		16.8	16.8	0.0	0.0						0.0		0.0				41	16	41	16	1.0	1.0
		W15-U						94.9	58.6	58.6	0.0	0.0	0.4	2.34	0.4	2.34	0.0	0.1						
First	R8	W16	Unknown	25.3	25.3	0.0	0.0	59.6	55.5	55.5	0.0	0.0	0.7	0.66	0.7	0.66	0.0	0.0	42	15	42	15	1.0	1.0
First	R9	W17	Unknown	33.5	32.9	0.6	1.8	101.1	100.3	100.3	0.0	0.0	1.3	1.35	1.3	1.33	0.0	1.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R10	W18	Unknown	33.4	32.8	0.6	1.7	86.7	86.3	86.3	0.0	0.0	1.5	1.47	1.5	1.45	0.0	1.5	N/F	N/F	N/F	N/F	N/F	N/F
First	R11	W19	Unknown	33.5	32.9	0.6	1.7	101.1	100.3	100.3	0.0	0.0	1.3	1.35	1.3	1.33	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R12	W20	Unknown	33.6	33.1	0.5	1.6	86.7	86.2	86.1	0.0	0.0	1.5	1.48	1.5	1.46	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R13	W21	Unknown	33.7	33.1	0.5	1.5	101.1	100.1	100.1	0.0	0.0	1.4	1.35	1.3	1.33	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R14	W22	Unknown	33.7	33.2	0.5	1.5	86.7	86.2	86.2	0.0	0.0	1.5	1.48	1.5	1.46	0.0	1.2	N/F	N/F	N/F	N/F	N/F	N/F
First	R15	W23	Unknown	33.7	33.2	0.5	1.5	101.1	100.0	100.0	0.0	0.0	1.4	1.35	1.3	1.34	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R16	W24	Unknown	33.9	33.4	0.5	1.5	79.1	78.9	78.9	0.0	0.0	1.6	1.57	1.5	1.55	0.0	1.2	N/F	N/F	N/F	N/F	N/F	N/F
Second	R1	W01	Unknown	37.5	36.7	0.8	2.2	97.6	97.1	97.1	0.0	0.0	2.7	2.70	2.6	2.64	0.1	2.1	N/F	N/F	N/F	N/F	N/F	N/F
Second	R2	W02	Unknown	37.6	36.9	0.7	1.9	97.6	97.1	97.1	0.0	0.0	2.7	2.71	2.7	2.66	0.1	1.9	N/F	N/F	N/F	N/F	N/F	N/F
Second	R3	W03	Unknown	37.7	37.1	0.7	1.8	97.6	97.1	97.1	0.0	0.0	2.7	2.71	2.7	2.67	0.0	1.8	N/F	N/F	N/F	N/F	N/F	N/F
Second	R4	W04	Unknown	37.8	37.2	0.7	1.7	97.6	97.1	97.1	0.0	0.0	2.7	2.72	2.7	2.67	0.0	1.7	N/F	N/F	N/F	N/F	N/F	N/F
1 to 5 Varsity Row																								
Ground	R2	W04-L	Kitchen	34.4	34.4	0.0	0.1						0.0		0.0				75	22	75	22	1.0	1.0
		W04-U											1.2		1.2									
		W05-L		33.9	33.8	0.0	0.1						0.0		0.0				71	21	71	21	1.0	1.0
		W05-U						135.6	134.4	134.4	0.0	0.0	1.2	2.35	1.2	2.34	0.0	0.1						
Ground	R3	W06-L	Kitchen	23.2	23.0	0.2	0.8						0.0		0.0				53	17	53	17	1.0	1.0
		W06-U											1.1		1.1									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W07		53.1	53.1	0.1	0.1	98.2	86.4	86.4	0.0	0.0	1.0	2.10	1.0	2.09	0.0	0.3	74	24	73	23	1.0	1.0
Ground	R4	W08-L	Kitchen	28.2	28.1	0.1	0.2						0.0		0.0				54	14	54	14	1.0	1.0
		W08-U						146.2	129.7	129.7	0.0	0.0	0.9	0.94	0.9	0.94	0.0	0.1						
Ground	R5	W09-L	Kitchen	24.9	24.4	0.4	1.8						0.0		0.0				48	18	48	18	1.0	1.0
		W09-U						138.1	123.6	123.6	0.0	0.0	0.9	0.91	0.9	0.90	0.0	1.3						
Ground	R6	W10-L	Kitchen	27.0	26.6	0.4	1.6						0.0		0.0				50	14	50	14	1.0	1.0
		W10-U											0.5		0.5									
		W11-L		29.6	29.5	0.1	0.4						0.0		0.0				52	15	52	15	1.0	1.0
		W11-U											0.6		0.6									
		W12-L		32.1	31.5	0.7	2.1						0.0		0.0				71	20	71	20	1.0	1.0
		W12-U											1.0		1.0									
		W13-L		29.0	28.1	1.0	3.3						0.0		0.0				65	23	65	23	1.0	1.0
		W13-U						299.1	297.8	297.8	0.0	0.0	0.6	2.83	0.6	2.79	0.0	1.4						
First	R1	W01-L	Bedroom	39.6	39.6	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						107.4	98.6	98.6	0.0	0.0	0.9	1.05	0.9	1.05	0.0	0.0						
First	R2	W02-L	Bedroom	35.9	35.8	0.1	0.3						0.1		0.1				79	26	79	26	1.0	1.0
		W02-U						125.0	121.9	121.9	0.0	0.0	0.8	0.83	0.7	0.83	0.0	0.2						
First	R4	W04-L	Bedroom	29.7	29.5	0.2	0.7						0.0		0.0				66	26	66	26	1.0	1.0
		W04-U						75.8	64.8	64.8	0.0	0.0	1.5	1.58	1.5	1.57	0.0	0.6						
First	R6	W06-L	Bedroom	34.7	34.1	0.6	1.7						0.0		0.0				71	24	71	24	1.0	1.0
		W06-U						75.8	69.2	69.2	0.0	0.0	1.8	1.79	1.7	1.76	0.0	1.6						
First	R9	W09-L	Bedroom	34.4	33.4	1.0	3.0						0.0		0.0				69	22	69	22	1.0	1.0
		W09-U						84.5	82.6	82.6	0.0	0.0	1.7	1.73	1.6	1.68	0.0	2.6						
First	R11	W11	Bedroom	34.2	33.9	0.3	1.0						1.2		1.2				56	18	56	18	1.0	1.0
		W12		36.4	35.2	1.1	3.1						1.9		1.8				78	25	78	25	1.0	1.0
		W13		34.5	33.2	1.3	3.7	162.2	162.2	162.2	0.0	0.0	1.2	4.25	1.1	4.15	0.1	2.3	73	25	73	25	1.0	1.0
Second	R1	W01-L	eception Roor	34.0	34.0	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.7		0.7									
		W02-L		38.7	38.7	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.8		0.8									
		W03-L		39.6	39.6	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.4		0.4									
		W04-L		39.6	39.6	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						264.1	264.0	264.0	0.0	0.0	0.4	2.44	0.4	2.44	0.0	0.0						
Second	R2	W05-L	Bedroom	39.6	39.6	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											1.0		1.0									
		W06-L		37.4	37.3	0.1	0.2						0.0		0.0				81	28	81	28	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W06-U						73.4	73.0	73.0	0.0	0.0	1.0	2.13	1.0	2.13	0.0	0.1						
Second	R4	W08-L	Bedroom	34.4	34.1	0.2	0.7						0.0		0.0				74	28	74	28	1.0	1.0
		W08-U						75.8	59.4	59.0	0.4	0.7	1.5	1.52	1.5	1.51	0.0	0.6						
Second	R6	W10-L	Bedroom	37.2	36.6	0.6	1.6						0.0		0.0				80	28	80	28	1.0	1.0
		W10-U						65.9	58.6	58.5	0.1	0.1	1.8	1.80	1.7	1.77	0.0	1.5						
Second	R9	W13-L	Bedroom	37.3	36.4	0.9	2.4						0.0		0.0				78	25	78	25	1.0	1.0
		W13-U						79.3	73.8	73.7	0.1	0.1	1.6	1.61	1.5	1.57	0.0	2.3						
Second	R10	W14	Bedroom	49.5	48.7	0.8	1.6						0.7		0.7				76	26	76	26	1.0	1.0
		W15		38.1	37.3	0.8	2.0	193.8	173.8	173.8	0.0	0.0	0.8	1.48	0.8	1.45	0.0	1.7	68	23	68	23	1.0	1.0
Second	R12	W18	Bedroom	38.5	37.8	0.7	1.8						1.5		1.5				67	22	67	22	1.0	1.0
		W19		39.6	39.6	0.0	0.0	91.3	91.3	91.3	0.0	0.0	1.6	3.07	1.6	3.04	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
6-7 Varsity Row																								
Ground	R1	W01-L	Kitchen	32.2	31.0	1.2	3.6						0.0		0.0				69	20	69	20	1.0	1.0
		W01-U						128.9	124.1	124.1	0.0	0.0	0.7	0.76	0.7	0.74	0.0	3.0						
Ground	R2	W02-L	Kitchen	25.3	25.1	0.2	0.8						0.0		0.0				45	11	45	11	1.0	1.0
		W02-U						128.9	104.0	98.8	5.2	5.0	0.6	0.65	0.6	0.64	0.0	0.6						
First	R1	W01-L	Bedroom	35.7	34.3	1.3	3.7						0.1		0.1				77	25	77	25	1.0	1.0
		W01-U											0.8		0.7									
		W02-L		35.8	34.4	1.4	3.9						0.1		0.1				75	24	75	24	1.0	1.0
		W02-U						126.6	124.5	124.5	0.0	0.0	0.8	1.77	0.7	1.71	0.1	3.4						
First	R4	W05-L	Bedroom	35.5	34.0	1.4	4.1						0.1		0.1				76	24	76	24	1.0	1.0
		W05-U											0.8		0.7									
		W06-L		35.2	33.7	1.4	4.1						0.1		0.1				74	22	74	22	1.0	1.0
		W06-U						126.6	124.6	124.6	0.0	0.0	0.8	1.75	0.7	1.69	0.1	3.5						
Second	R1	W01-L	Bedroom	37.3	36.2	1.2	3.1						0.1		0.1				78	26	78	26	1.0	1.0
		W01-U											1.1		1.1									
		W02-L		37.4	36.2	1.2	3.2						0.1		0.1				77	25	77	25	1.0	1.0
		W02-U						75.8	75.4	75.4	0.0	0.0	1.1	2.33	1.0	2.26	0.1	2.9						
Second	R4	W05-L	Bedroom	37.4	36.1	1.3	3.4						0.1		0.1				79	26	79	26	1.0	1.0
		W05-U											1.1		1.0									
		W06-L		37.3	36.0	1.3	3.4						0.1		0.1				79	26	79	26	1.0	1.0
		W06-U						76.3	75.8	75.8	0.0	0.0	1.1	2.32	1.0	2.24	0.1	3.2						
2 to 6 Williams Lane																								
Ground	R1	W01	LKD	32.3	24.5	7.8	24.1						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W02-L		30.4	30.4	0.0	0.0						0.1		0.1				36		36		1.0	1.0
		W02-U						378.2	377.0	373.3	3.7	1.0	1.4	2.03	1.4	1.94	0.1	4.2						
Ground	R3	W06	Living Room	32.9	24.4	8.5	25.8	108.6	106.8	56.8	50.0	46.8	1.2	1.19	0.9	0.95	0.2	20.4	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R6	W13	LKD	33.0	24.3	8.7	26.2						0.4		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W14-L		28.8	28.8	0.0	0.0						0.1		0.1				40	10	40	10	1.0	1.0
		W14-U						372.6	371.9	361.8	10.0	2.7	1.4	2.01	1.4	1.92	0.1	4.5						
First	R1	W01-L	Bedroom	34.5	27.4	7.1	20.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											1.4		1.2									
		W02-L		30.9	24.2	6.8	21.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						122.5	121.1	121.1	0.0	0.0	1.3	2.85	1.1	2.38	0.5	16.4						
First	R2	W03-L	Bedroom	35.4	27.7	7.7	21.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											1.2		1.0									
		W04-L		35.4	27.7	7.8	21.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						152.9	151.0	132.6	18.4	12.2	1.1	2.48	0.9	2.04	0.4	17.9						
First	R3	W05-L	Bedroom	35.5	27.7	7.8	22.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											1.4		1.1									
		W06-L		35.6	27.7	7.8	22.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						122.5	121.4	121.4	0.0	0.0	1.4	3.00	1.1	2.46	0.5	18.0						
Second	R1	W01-L	Bedroom	36.5	30.9	5.6	15.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											1.1		1.0									
		W02-L		33.0	27.6	5.4	16.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						116.5	115.0	115.0	0.0	0.0	1.0	2.28	0.9	1.98	0.3	12.9						
Second	R2	W03-L	Bedroom	37.1	30.9	6.2	16.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											1.1		0.9									
		W04-L		37.2	30.9	6.2	16.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						116.5	115.3	115.3	0.0	0.0	1.1	2.30	0.9	1.97	0.3	14.3						
Second	R3	W05-L	Bedroom	37.2	31.0	6.2	16.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											1.1		0.9									
		W06-L		37.2	31.0	6.2	16.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						116.5	115.1	115.1	0.0	0.0	1.1	2.40	0.9	2.06	0.3	14.3						
8-10 Williams Lane																								
Ground	R2	W05-L	Kitchen	36.8	35.3	1.5	4.2						0.1		0.1				81	26	73	25	0.9	1.0
		W05-U						146.4	146.1	146.1	0.0	0.0	3.0	3.10	2.9	2.98	0.1	3.8						
Ground	R3	W06-L	Kitchen	36.3	35.3	1.1	2.9						0.1		0.1				76	25	69	24	0.9	1.0
		W06-U						146.4	146.1	146.0	0.0	0.0	3.0	3.05	2.9	2.97	0.1	2.7						
First	R2	W02-L	Bedroom	31.6	30.1	1.5	4.9						0.0		0.0				59	18	52	17	0.9	0.9

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W02-U											1.1		1.0									
		W03-L		37.5	36.4	1.1	2.8						0.1		0.1				82	26	75	25	0.9	1.0
		W03-U						146.5	142.3	142.3	0.0	0.0	1.4	2.53	1.3	2.47	0.1	2.7						
First	R3	W04-L	Bedroom	37.2	36.5	0.8	2.0						0.1		0.1				81	26	75	25	0.9	1.0
		W04-U											1.4		1.3									
		W05-L		28.3	28.2	0.1	0.4						0.0		0.0				50	20	49	19	1.0	1.0
		W05-U						146.5	142.2	142.2	0.0	0.0	1.0	2.46	1.0	2.43	0.0	1.1						
Second	R1	W01-L	Bedroom	38.1	37.6	0.5	1.4						0.1		0.1				82	26	81	27	1.0	1.0
		W01-U						110.8	107.3	107.3	0.0	0.0	1.4	1.48	1.4	1.46	0.0	1.0						
Second	R2	W02-L	Bedroom	38.1	37.8	0.4	1.0						0.1		0.1				83	27	83	28	1.0	1.0
		W02-U						110.8	107.2	107.2	0.0	0.0	1.4	1.46	1.4	1.45	0.0	0.7						
12 to 20 Williams Lane																								
Ground	R1	W01	Unknown	36.9	36.4	0.5	1.3	34.7	33.2	33.2	0.0	0.0	2.5	2.48	2.5	2.46	0.0	0.8	79	27	74	26	0.9	1.0
Ground	R3	W05	Unknown	36.6	36.3	0.3	0.9	34.7	33.1	33.1	0.0	0.0	2.3	2.32	2.3	2.31	0.0	0.6	76	26	73	25	1.0	1.0
Ground	R5	W09	Unknown	36.7	36.5	0.3	0.7	34.7	32.7	32.7	0.0	0.0	2.3	2.33	2.3	2.32	0.0	0.5	76	26	74	25	1.0	1.0
Ground	R7	W13	Unknown	36.8	36.5	0.3	0.7	34.7	33.3	33.3	0.0	0.0	2.4	2.35	2.3	2.34	0.0	0.4	76	25	75	25	1.0	1.0
Ground	R9	W17	Unknown	36.8	36.6	0.2	0.7	34.7	33.2	33.2	0.0	0.0	2.4	2.37	2.4	2.36	0.0	0.4	77	26	76	26	1.0	1.0
First	R1	W01-L	Bedroom	37.9	37.5	0.3	0.9						0.1		0.1				83	27	80	26	1.0	1.0
		W01-U											1.6		1.6									
		W02-L		37.9	37.6	0.3	0.8						0.1		0.1				83	27	82	27	1.0	1.0
		W02-U						113.6	112.8	112.8	0.0	0.0	1.6	3.41	1.6	3.39	0.0	0.5						
First	R2	W03-L	Bedroom	37.9	37.7	0.3	0.7						0.1		0.1				83	27	83	28	1.0	1.0
		W03-U											1.6		1.6									
		W04-L		38.0	37.7	0.3	0.7						0.1		0.1				83	27	83	28	1.0	1.0
		W04-U						113.6	112.7	112.7	0.0	0.0	1.6	3.41	1.6	3.40	0.0	0.4						
First	R3	W05-L	Bedroom	38.0	37.8	0.2	0.6						0.1		0.1				83	27	83	28	1.0	1.0
		W05-U											1.6		1.6									
		W06-L		38.1	37.8	0.2	0.6						0.1		0.1				83	27	83	28	1.0	1.0
		W06-U						113.6	112.8	112.8	0.0	0.0	1.6	3.42	1.6	3.41	0.0	0.4						
First	R4	W07-L	Bedroom	38.1	37.9	0.2	0.6						0.1		0.1				83	27	83	28	1.0	1.0
		W07-U											1.6		1.6									
		W08-L		38.1	37.9	0.2	0.6						0.1		0.1				83	27	84	28	1.0	1.0
		W08-U						113.6	112.8	112.8	0.0	0.0	1.6	3.43	1.6	3.42	0.0	0.4						
First	R5	W09-L	Bedroom	38.1	37.9	0.2	0.6						0.1		0.1				84	28	84	28	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W09-U											1.6		1.6									
		W10-L		38.2	38.0	0.2	0.6						0.1		0.1				83	27	83	27	1.0	1.0
		W10-U						113.6	112.8	112.8	0.0	0.0	1.6	3.40	1.6	3.39	0.0	0.4						
First	R6	W11	Unknown	11.2	11.2	0.0	-0.2	133.2	15.7	15.7	0.0	0.0	0.4	0.42	0.4	0.42	0.0	-0.4	N/F	N/F	N/F	N/F	N/F	N/F
Second	R1	W01-L	Bedroom	37.6	37.4	0.2	0.5						0.1		0.1				83	27	84	28	1.0	1.0
		W01-U						154.4	152.9	152.7	0.2	0.1	1.0	1.05	1.0	1.05	0.0	0.2						
Second	R2	W02-L	Bedroom	37.7	37.5	0.1	0.4						0.1		0.1				83	27	84	28	1.0	1.0
		W02-U						154.4	153.7	153.6	0.1	0.0	1.0	1.04	1.0	1.04	0.0	0.2						
Second	R3	W03-L	Bedroom	37.8	37.6	0.1	0.4						0.1		0.1				83	27	84	28	1.0	1.0
		W03-U						154.4	153.5	153.4	0.0	0.0	1.0	1.02	1.0	1.02	0.0	0.2						
Second	R4	W04-L	Bedroom	37.8	37.6	0.2	0.4						0.1		0.1				83	27	84	28	1.0	1.0
		W04-U						154.4	153.1	153.0	0.1	0.1	1.0	1.02	1.0	1.02	0.0	0.2						
Second	R5	W05-L	Bedroom	37.8	37.7	0.1	0.4						0.1		0.1				83	28	83	28	1.0	1.0
		W05-U						154.4	153.1	153.1	0.0	0.0	1.0	1.03	1.0	1.02	0.0	0.3						
22 to 26 Williams Lane																								
Ground	R1	W01	Unknown	24.7	24.7	0.0	0.0	33.6	27.8	27.8	0.0	0.0	1.8	1.77	1.8	1.77	0.0	0.0	50	22	50	22	1.0	1.0
Ground	R4	W08	Unknown	33.3	33.1	0.2	0.6	33.6	31.1	31.1	0.0	0.0	2.3	2.32	2.3	2.31	0.0	0.5	71	26	71	26	1.0	1.0
Ground	R6	W12	Unknown	34.9	35.0	0.0	-0.1	34.7	32.1	32.1	0.0	0.0	2.2	2.23	2.2	2.23	0.0	-0.1	76	24	76	24	1.0	1.0
First	R1	W01-L	Bedroom	30.7	30.7	0.0	0.1						0.1		0.1				64	25	64	25	1.0	1.0
		W01-U						108.1	103.4	103.4	0.0	0.0	1.5	1.66	1.5	1.66	0.0	0.1						
First	R2	W02-L	Bedroom	36.6	36.3	0.2	0.6						0.1		0.1				74	27	74	27	1.0	1.0
		W02-U						108.1	103.1	103.1	0.0	0.0	1.7	1.87	1.7	1.86	0.0	0.5						
First	R3	W03-L	Bedroom	37.1	37.0	0.1	0.4						0.1		0.1				79	27	79	27	1.0	1.0
		W03-U											1.5		1.5									
		W04-L		37.7	37.6	0.1	0.3						0.1		0.1				79	27	79	27	1.0	1.0
		W04-U						113.6	112.6	112.6	0.0	0.0	1.6	3.35	1.6	3.34	0.0	0.3						
Second	R1	W01-L	Bedroom	35.4	35.4	0.0	0.1						0.1		0.1				71	25	71	25	1.0	1.0
		W01-U						72.1	67.9	67.9	0.0	0.0	1.7	1.85	1.7	1.85	0.0	0.1						
Second	R2	W02-L	Bedroom	38.5	38.3	0.1	0.3						0.2		0.2				83	28	83	28	1.0	1.0
		W02-U						72.1	67.8	67.8	0.0	0.0	1.8	1.97	1.8	1.97	0.0	0.3						
Second	R3	W03-L	Bedroom	36.8	36.7	0.1	0.2						0.0		0.0				79	28	79	28	1.0	1.0
		W03-U						209.2	192.0	192.0	0.0	0.0	0.6	0.64	0.6	0.64	0.0	0.2						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
1 to 3 Watney Road																								
Ground	R1	W01	Unknown	34.5	34.2	0.3	0.9	143.8	141.7	141.7	0.0	0.0	1.8	1.78	1.8	1.76	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W02-L	Unknown	25.9	25.8	0.1	0.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.5		0.5									
		W03-L		36.0	35.9	0.1	0.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						56.0	54.5	54.5	0.0	0.0	0.6	1.06	0.6	1.06	0.0	0.3						
Ground	R3	W04-L	Unknown	36.0	35.9	0.1	0.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.6		0.6									
		W05-L		20.4	20.4	0.0	0.0						0.0		0.0				7	0	7	0	1.0	0.0
		W05-U						56.0	53.5	53.5	0.0	0.0	0.4	0.99	0.4	0.99	0.0	0.1						
Ground	R4	W06	Unknown	31.3	31.2	0.1	0.2	128.9	128.0	128.0	0.0	0.0	1.8	1.77	1.8	1.77	0.0	0.2	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W07	Unknown	33.1	33.0	0.1	0.3	117.2	116.7	116.7	0.0	0.0	2.0	1.97	2.0	1.97	0.0	0.2	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01	Unknown	36.5	36.2	0.3	0.8						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W02		34.4	34.1	0.3	0.9	83.1	82.7	82.7	0.0	0.0	0.7	1.39	0.7	1.38	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W03	Unknown	34.3	34.0	0.3	0.9	108.7	107.4	107.4	0.0	0.0	1.8	1.81	1.8	1.80	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W04	Unknown	34.3	33.9	0.3	0.9	74.9	72.6	72.6	0.0	0.0	0.7	0.70	0.7	0.69	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W05	Unknown	34.2	33.9	0.3	0.9	107.8	107.7	107.7	0.0	0.0	2.0	1.97	2.0	1.95	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R5	W06	Unknown	34.1	33.8	0.3	0.9	117.2	116.9	116.9	0.0	0.0	1.9	1.89	1.9	1.88	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R6	W07	Unknown	34.2	33.9	0.3	0.9						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W08		19.7	19.7	0.0	0.0	74.9	74.7	74.7	0.0	0.0	0.5	1.18	0.5	1.18	0.0	0.4	20	6	20	6	1.0	1.0
4-5 Watney Road																								
Ground	R1	W01	Unknown	6.6	6.6	0.1	0.9						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W02		33.0	32.7	0.3	0.8	117.3	116.9	116.9	0.0	0.0	2.0	2.12	1.9	2.11	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W03-L	Unknown	24.2	23.9	0.3	1.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.4		0.4									
		W04-L		34.7	34.4	0.3	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						69.5	66.0	66.0	0.0	0.0	0.5	0.89	0.5	0.89	0.0	0.7						
Ground	R3	W05-L	Unknown	34.4	34.1	0.3	0.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.5		0.5									
		W06-L		27.0	27.0	0.0	0.0						0.0		0.0				16	1	16	1	1.0	1.0
		W06-U						69.5	67.7	67.7	0.0	0.0	0.4	0.92	0.4	0.92	0.0	0.3						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R4	W07	Unknown	32.2	32.2	0.0	0.1	117.3	116.0	116.0	0.0	0.0	1.9	1.92	1.9	1.92	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01	Unknown	22.5	22.4	0.1	0.5						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W02		34.6	34.3	0.3	0.9	74.9	74.6	74.6	0.0	0.0	0.9	1.42	0.9	1.41	0.0	0.5	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W03	Unknown	34.5	34.2	0.3	0.8	107.8	107.8	107.8	0.0	0.0	2.2	2.20	2.2	2.18	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W04	Unknown	34.5	34.2	0.3	0.8	117.3	117.0	117.0	0.0	0.0	2.1	2.09	2.1	2.08	0.0	0.7	N/F	N/F	N/F	N/F	N/F	N/F
11-13 Watney Road																								
Ground	R1	W01	Unknown	34.9	34.6	0.2	0.6	94.0	83.6	83.6	0.0	0.0	0.4	0.45	0.4	0.44	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W02	Unknown	35.1	34.9	0.2	0.5	94.8	94.7	94.7	0.0	0.0	2.2	2.19	2.2	2.18	0.0	0.5	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W03-L	Unknown	36.8	36.5	0.3	0.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											1.4		1.4									
		W04		36.9	36.6	0.4	1.1						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		27.7	27.5	0.3	0.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						213.2	213.2	213.2	0.0	0.0	1.1	2.87	1.1	2.84	0.0	0.9						
First	R1	W01	Unknown	34.9	34.6	0.4	1.0	94.0	91.4	91.4	0.0	0.0	0.8	0.78	0.8	0.77	0.0	0.9	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02-L	Unknown	35.3	34.9	0.4	1.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						108.9	108.6	108.6	0.0	0.0	1.6	1.69	1.6	1.67	0.0	0.9						
First	R3	W03-L	Unknown	35.4	35.0	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						108.8	108.3	108.3	0.0	0.0	1.7	1.76	1.7	1.74	0.0	1.0						
First	R4	W04-L	Unknown	35.2	34.8	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						93.7	91.9	91.9	0.0	0.0	1.0	1.02	1.0	1.01	0.0	1.0						
15 to 21 Watney Road																								
Ground	R1	W01	Unknown	33.6	33.3	0.3	0.8						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W02		37.0	36.7	0.4	1.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W03-L		34.7	34.5	0.2	0.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						87.0	86.4	86.4	0.0	0.0	0.6	1.54	0.6	1.53	0.0	0.7						
Ground	R2	W04	Unknown	36.8	36.6	0.2	0.5	74.3	74.1	74.1	0.0	0.0	2.0	1.96	2.0	1.95	0.0	0.5	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W05	Unknown	35.0	34.8	0.1	0.4	74.3	74.1	74.1	0.0	0.0	2.0	1.98	2.0	1.97	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W06	Unknown	31.0	30.6	0.4	1.5						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W07		37.2	36.7	0.5	1.2						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W08		34.3	33.9	0.4	1.1	87.0	86.3	86.3	0.0	0.0	0.6	1.53	0.6	1.51	0.0	1.1	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W09	Unknown	36.6	36.2	0.5	1.3	74.3	74.1	74.1	0.0	0.0	2.0	1.96	1.9	1.94	0.0	1.2	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R6	W10	Unknown	37.2	36.7	0.5	1.3	74.3	73.1	73.1	0.0	0.0	1.9	1.93	1.9	1.90	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R7	W11	Unknown	37.4	36.9	0.5	1.3						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W12		36.8	36.3	0.4	1.2						0.6		0.6				N/F	N/F	N/F	N/F	N/F	N/F
		W13		37.3	36.8	0.5	1.4	87.0	86.1	86.1	0.0	0.0	1.0	1.77	1.0	1.74	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01-L	Unknown	35.2	34.8	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						115.6	112.4	112.4	0.0	0.0	0.9	0.92	0.9	0.91	0.0	1.0						
First	R2	W02-L	Unknown	35.3	34.9	0.4	1.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						45.9	44.8	44.8	0.0	0.0	1.7	1.72	1.7	1.70	0.0	1.0						
First	R3	W03-L	Unknown	35.3	34.9	0.4	1.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						115.6	112.2	112.2	0.0	0.0	0.9	0.92	0.9	0.91	0.0	1.1						
First	R4	W04-L	Unknown	35.3	34.9	0.4	1.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						45.9	44.3	44.3	0.0	0.0	1.7	1.68	1.6	1.66	0.0	1.1						
First	R5	W05-L	Unknown	35.3	34.9	0.5	1.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						115.6	112.3	112.3	0.0	0.0	0.9	0.93	0.9	0.92	0.0	1.1						
First	R6	W06-L	Unknown	35.3	34.9	0.5	1.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						45.9	44.3	44.3	0.0	0.0	1.7	1.68	1.6	1.66	0.0	1.2						
First	R7	W07-L	Unknown	35.3	34.9	0.5	1.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						115.6	112.2	112.2	0.0	0.0	0.9	0.92	0.9	0.90	0.0	1.2						
First	R8	W08-L	Unknown	35.3	34.9	0.5	1.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						45.9	44.5	44.5	0.0	0.0	1.7	1.73	1.7	1.71	0.0	1.2						
23 to 29 Watney Road																								
Ground	R1	W01	Unknown	37.3	36.7	0.5	1.4						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W02		37.4	36.9	0.5	1.4	91.0	83.1	83.1	0.0	0.0	0.2	0.92	0.2	0.91	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W03	Unknown	36.1	35.8	0.3	0.7	74.0	72.7	72.7	0.0	0.0	1.9	1.93	1.9	1.91	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W04	Unknown	37.6	37.0	0.6	1.5						1.1		1.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		37.5	37.0	0.6	1.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.5		0.5									
		W06		77.7	77.6	0.1	0.1	132.5	132.5	132.5	0.0	0.0	17.8	19.48	17.8	19.44	0.0	0.2	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W07	Unknown	28.0	27.5	0.5	1.8	64.9	63.0	63.0	0.0	0.0	0.7	0.73	0.7	0.72	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W08	Unknown	33.6	33.3	0.3	1.0						0.8		0.8				N/F	N/F	N/F	N/F	N/F	N/F
		W09		36.5	36.0	0.5	1.4	54.9	54.2	54.2	0.0	0.0	0.3	1.08	0.3	1.07	0.0	1.0	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R6	W10	Unknown	35.6	35.3	0.3	0.7						1.8		1.8				N/F	N/F	N/F	N/F	N/F	N/F
		W11		34.0	33.8	0.2	0.7	84.9	83.5	83.5	0.0	0.0	0.6	2.41	0.6	2.39	0.0	0.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R7	W12-L	Living Room	23.8	23.7	0.0	0.1						0.1		0.1				54	17	54	17	1.0	1.0
		W12-U											1.9		1.9									
		W13-L		35.0	34.6	0.4	1.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											1.2		1.2									
		W14-L		32.4	32.0	0.4	1.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											0.4		0.4									
		W15-L		32.1	31.8	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.4		0.4									
		W16-L		34.3	33.8	0.5	1.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U											1.2		1.2									
		W17		24.6	24.2	0.4	1.5						0.3		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W18		74.3	74.3	0.0	0.0						3.1		3.1				61	17	61	17	1.0	1.0
		W19		89.8	89.6	0.2	0.2						7.9		7.9				N/F	N/F	N/F	N/F	N/F	N/F
		W20		77.0	76.9	0.2	0.2						3.3		3.3				N/F	N/F	N/F	N/F	N/F	N/F
		W21		52.5	52.5	0.0	0.0	146.2	146.2	146.2	0.0	0.0	5.2	25.18	5.2	25.12	0.1	0.2	52	13	52	13	1.0	1.0
First	R1	W01	Unknown	36.1	35.6	0.5	1.4	115.6	112.9	112.9	0.0	0.0	1.2	1.15	1.1	1.14	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02	Unknown	36.1	35.5	0.5	1.4	45.9	44.8	44.8	0.0	0.0	2.1	2.15	2.1	2.12	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W03	Unknown	36.1	35.5	0.5	1.5	115.6	112.4	112.4	0.0	0.0	1.0	1.02	1.0	1.01	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W04	Unknown	36.0	35.5	0.5	1.5	45.9	44.8	44.8	0.0	0.0	1.9	1.86	1.8	1.84	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R5	W05	Unknown	36.0	35.5	0.6	1.6	115.6	112.0	112.0	0.0	0.0	1.0	1.03	1.0	1.02	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R6	W06	Unknown	36.0	35.5	0.6	1.6	45.9	45.0	45.0	0.0	0.0	1.9	1.87	1.8	1.84	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R7	W07	Bedroom	36.0	35.4	0.6	1.6	112.2	108.3	108.3	0.0	0.0	1.0	1.03	1.0	1.01	0.0	1.5	N/F	N/F	N/F	N/F	N/F	N/F
First	R8	W08	Unknown	36.0	35.4	0.6	1.6	45.9	44.4	44.4	0.0	0.0	1.9	1.92	1.9	1.89	0.0	1.5	N/F	N/F	N/F	N/F	N/F	N/F
31 to 37 Watney Road																								
Ground	R1	W01	Unknown	36.5	35.8	0.6	1.7						1.0		1.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02		37.3	36.7	0.6	1.7	76.6	71.4	71.4	0.0	0.0	0.4	1.37	0.4	1.35	0.0	1.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W03	Unknown	35.9	35.7	0.2	0.6						2.0		2.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04		37.0	36.4	0.6	1.8	91.4	89.4	89.4	0.0	0.0	0.6	2.59	0.5	2.57	0.0	0.9	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W05	Unknown	37.0	36.3	0.7	1.8	97.4	96.5	96.5	0.0	0.0	3.3	3.25	3.2	3.20	0.1	1.8	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W06	Unknown	37.3	36.7	0.7	1.8	58.7	38.9	38.9	0.0	0.0	0.3	0.31	0.3	0.30	0.0	2.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W07-L	Unknown	37.4	36.7	0.7	1.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W07-U											1.0		0.9									
		W08-L		23.1	22.8	0.4	1.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.3		0.3									
		W09		20.2	19.8	0.4	1.8						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10		30.3	29.6	0.6	2.1						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W11		36.5	35.7	0.7	2.0	183.9	180.8	180.8	0.0	0.0	0.3	2.60	0.3	2.56	0.0	1.7	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R6	W12	Unknown	37.1	36.4	0.7	1.8	89.2	87.0	87.0	0.0	0.0	1.9	1.92	1.9	1.88	0.0	1.7	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R7	W13	Unknown	37.3	36.6	0.7	1.9						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W14		36.9	36.4	0.5	1.5						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W15		37.2	36.5	0.7	1.9	78.8	77.6	77.6	0.0	0.0	1.0	1.94	1.0	1.91	0.0	1.7	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01-L	Unknown	36.0	35.4	0.6	1.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						93.4	90.9	90.9	0.0	0.0	1.1	1.10	1.1	1.08	0.0	1.5						
First	R2	W02-L	Unknown	36.0	35.4	0.6	1.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						74.3	73.0	73.0	0.0	0.0	1.3	1.26	1.2	1.24	0.0	1.6						
First	R3	W03-L	Unknown	36.0	35.4	0.6	1.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						93.4	91.0	91.0	0.0	0.0	1.1	1.10	1.1	1.08	0.0	1.6						
First	R4	W04-L	Unknown	36.0	35.3	0.6	1.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						74.3	73.2	73.2	0.0	0.0	1.4	1.37	1.3	1.35	0.0	1.7						
First	R5	W05-L	Unknown	36.0	35.3	0.7	1.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						74.3	72.9	72.9	0.0	0.0	1.2	1.24	1.2	1.22	0.0	1.7						
First	R6	W06-L	Unknown	35.8	35.1	0.7	1.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						93.4	90.3	90.3	0.0	0.0	1.1	1.13	1.1	1.11	0.0	1.7						
First	R7	W07-L	Unknown	35.8	35.1	0.7	1.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						74.3	72.7	72.7	0.0	0.0	1.2	1.24	1.2	1.22	0.0	1.7						
First	R8	W08-L	Unknown	35.8	35.1	0.7	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						93.4	90.8	90.8	0.0	0.0	1.1	1.11	1.1	1.09	0.0	1.8						
39 to 45 Watney Road																								
Ground	R1	W01	Unknown	37.2	36.4	0.7	2.0						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W02		37.2	36.5	0.8	2.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03		37.0	36.4	0.6	1.7	80.3	78.2	78.2	0.0	0.0	0.6	1.26	0.6	1.24	0.0	1.9	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W04	Unknown	37.0	36.4	0.7	1.8	87.8	84.9	84.9	0.0	0.0	1.5	1.50	1.5	1.47	0.0	1.8	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W05	Unknown	37.1	36.3	0.8	2.0						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W06		37.0	36.2	0.8	2.0	97.4	95.2	95.2	0.0	0.0	2.1	2.57	2.0	2.52	0.1	2.0	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R4	W07	Unknown	37.1	36.3	0.8	2.1						0.6		0.6				N/F	N/F	N/F	N/F	N/F	N/F
		W08		36.8	36.1	0.7	2.0	24.8	23.8	23.8	0.0	0.0	1.3	1.90	1.3	1.87	0.0	2.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W09	Unknown	36.9	36.2	0.8	2.1						1.3		1.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10		36.7	36.1	0.6	1.8	71.7	71.1	71.1	0.0	0.0	1.2	2.52	1.2	2.48	0.0	1.8	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R6	W11	Unknown	36.9	36.2	0.7	2.0						0.7		0.7				N/F	N/F	N/F	N/F	N/F	N/F
		W12-L		33.1	32.9	0.2	0.6						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						22.3	22.1	22.1	0.0	0.0	2.1	3.05	2.1	3.02	0.0	0.8						
Ground	R7	W13	Unknown	36.2	35.6	0.5	1.5						1.9		1.9				N/F	N/F	N/F	N/F	N/F	N/F
		W14		36.5	35.8	0.7	2.0	101.5	98.8	98.8	0.0	0.0	0.5	2.40	0.5	2.36	0.0	1.5	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R8	W15	Unknown	35.7	35.0	0.7	2.0	89.2	86.3	86.3	0.0	0.0	1.4	1.41	1.4	1.38	0.0	1.9	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R9	W16	Unknown	34.7	34.0	0.7	2.1						0.9		0.9				N/F	N/F	N/F	N/F	N/F	N/F
		W17		33.2	32.5	0.7	2.2	78.8	77.8	77.8	0.0	0.0	1.2	2.06	1.2	2.02	0.0	1.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01-L	Unknown	35.7	35.0	0.7	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						93.4	90.9	90.9	0.0	0.0	1.1	1.12	1.1	1.10	0.0	1.8						
First	R2	W02-L	Unknown	35.6	34.9	0.7	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						74.3	73.2	73.2	0.0	0.0	1.3	1.30	1.3	1.28	0.0	1.8						
First	R3	W03-L	Unknown	35.6	34.9	0.7	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						93.4	90.3	90.3	0.0	0.0	1.0	1.01	1.0	0.99	0.0	1.8						
First	R4	W04-L	Unknown	35.6	34.8	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						74.3	73.3	73.3	0.0	0.0	1.3	1.33	1.3	1.31	0.0	1.8						
First	R5	W05-L	Unknown	35.5	34.8	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						74.3	73.0	73.0	0.0	0.0	1.2	1.19	1.2	1.17	0.0	1.8						
First	R6	W06-L	Unknown	35.4	34.7	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						93.4	90.8	90.8	0.0	0.0	1.1	1.14	1.1	1.12	0.0	1.8						
First	R7	W07-L	Unknown	35.1	34.4	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						74.3	73.6	73.6	0.0	0.0	1.5	1.49	1.5	1.47	0.0	1.8						
First	R8	W08-L	Unknown	34.4	33.6	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						93.4	90.9	90.9	0.0	0.0	1.1	1.09	1.1	1.07	0.0	1.8						
47-49 Watney Road																								
Ground	R1	W01	Unknown	36.5	35.8	0.7	2.0						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W02		36.5	35.8	0.7	1.9						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W03		36.5	35.8	0.7	1.9	246.7	219.8	219.8	0.0	0.0	0.3	1.07	0.3	1.05	0.0	1.8	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R2	W04	Unknown	36.3	35.6	0.7	1.8						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W05		36.2	35.6	0.6	1.7						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W06		36.2	35.6	0.6	1.7	246.7	215.6	215.6	0.0	0.0	0.3	0.99	0.3	0.98	0.0	1.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01-L	Unknown	34.1	33.3	0.7	2.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						103.7	102.2	102.2	0.0	0.0	1.2	1.20	1.2	1.18	0.0	1.9						
First	R2	W02-L	Unknown	33.9	33.2	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						138.5	136.6	136.6	0.0	0.0	1.5	1.55	1.5	1.52	0.0	1.8						
First	R3	W03-L	Unknown	33.8	33.2	0.7	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						138.5	136.9	136.9	0.0	0.0	1.5	1.51	1.5	1.48	0.0	1.7						
First	R4	W04-L	Unknown	33.8	33.1	0.6	1.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						103.7	102.4	102.4	0.0	0.0	1.3	1.26	1.2	1.24	0.0	1.6						
51-53 Watney Road																								
Ground	R1	W01	Unknown	35.7	35.2	0.5	1.4						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W02		35.7	35.2	0.5	1.4						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W03		35.6	35.1	0.5	1.3	246.7	220.0	220.0	0.0	0.0	0.3	1.05	0.3	1.04	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W04	Unknown	35.3	34.9	0.4	1.2						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W05		35.2	34.8	0.4	1.1						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W06		35.2	34.8	0.4	1.1	246.7	218.2	218.2	0.0	0.0	0.3	0.98	0.3	0.97	0.0	1.0	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01	Unknown	33.3	32.8	0.5	1.7	103.7	101.2	101.2	0.0	0.0	1.2	1.23	1.2	1.22	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02	Unknown	33.1	32.6	0.5	1.5	138.5	135.3	135.3	0.0	0.0	1.5	1.51	1.5	1.49	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W03	Unknown	32.9	32.5	0.4	1.3	138.5	135.2	135.2	0.0	0.0	1.5	1.53	1.5	1.51	0.0	1.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W04	Unknown	32.8	32.4	0.3	1.0	103.7	101.2	101.2	0.0	0.0	1.2	1.20	1.2	1.19	0.0	0.9	N/F	N/F	N/F	N/F	N/F	N/F
55-57 Watney Road																								
Ground	R1	W01	Unknown	34.3	34.2	0.2	0.5						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W02		34.2	34.1	0.1	0.4						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W03		34.2	34.0	0.1	0.4	246.7	217.1	217.1	0.0	0.0	0.3	1.02	0.3	1.01	0.0	0.4	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W04	Unknown	33.9	33.8	0.1	0.4						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W05		33.8	33.6	0.1	0.4						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W06		33.8	33.6	0.2	0.5	246.7	215.4	215.4	0.0	0.0	0.3	0.95	0.3	0.94	0.0	0.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01	Unknown	32.6	32.4	0.2	0.6	103.7	101.1	101.1	0.0	0.0	1.2	1.20	1.2	1.19	0.0	0.5	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02	Unknown	32.3	32.1	0.2	0.6	138.5	134.8	134.8	0.0	0.0	1.5	1.50	1.5	1.49	0.0	0.5	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R3	W03	Unknown	32.1	31.9	0.2	0.7	138.5	135.2	135.2	0.0	0.0	1.5	1.48	1.5	1.47	0.0	0.5	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W04	Unknown	32.1	31.7	0.3	1.0	103.7	101.0	101.0	0.0	0.0	1.1	1.15	1.1	1.14	0.0	0.8	N/F	N/F	N/F	N/F	N/F	N/F
59-61 Watney Road																								
Ground	R1	W01	Unknown	33.2	32.8	0.4	1.4						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W02		33.1	32.7	0.4	1.3						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W03		33.1	32.7	0.4	1.3	248.2	220.3	220.3	0.0	0.0	0.3	0.99	0.3	0.97	0.0	1.2	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W04	Unknown	32.9	32.5	0.4	1.3						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W05		32.9	32.4	0.4	1.2						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W06		32.9	32.5	0.4	1.2	248.2	219.4	219.4	0.0	0.0	0.3	0.92	0.3	0.91	0.0	1.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01	Unknown	31.3	30.8	0.5	1.7	104.3	102.0	102.0	0.0	0.0	1.1	1.07	1.1	1.06	0.0	1.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02	Unknown	31.2	30.7	0.5	1.6	139.3	136.2	136.2	0.0	0.0	1.3	1.35	1.3	1.33	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W03	Unknown	31.0	30.5	0.5	1.5	139.3	136.4	136.4	0.0	0.0	1.4	1.37	1.4	1.35	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W04	Unknown	30.9	30.4	0.5	1.5	104.3	102.0	102.0	0.0	0.0	1.1	1.10	1.1	1.08	0.0	1.3	N/F	N/F	N/F	N/F	N/F	N/F
63 - 65 Watney Road																								
Ground	R1	W01	Unknown	31.7	31.6	0.1	0.3						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W02		31.7	31.6	0.1	0.3						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W03		31.7	31.6	0.1	0.3	246.7	213.6	213.6	0.0	0.0	0.3	0.96	0.3	0.96	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R2	W04	Unknown	31.7	31.7	0.1	0.2						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W05		31.7	31.6	0.0	0.1						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W06		31.7	31.7	0.0	0.1	246.7	212.9	212.0	0.8	0.4	0.3	0.91	0.3	0.90	0.0	0.2	N/F	N/F	N/F	N/F	N/F	N/F
First	R1	W01	Unknown	30.3	30.2	0.2	0.5	103.7	101.3	101.3	0.0	0.0	1.1	1.06	1.1	1.06	0.0	0.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R2	W02	Unknown	30.3	30.2	0.1	0.3	138.5	135.7	135.7	0.0	0.0	1.3	1.34	1.3	1.34	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W03	Unknown	30.3	30.2	0.1	0.3	138.5	135.7	135.7	0.0	0.0	1.4	1.37	1.4	1.36	0.0	0.2	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W04	Unknown	30.2	30.1	0.1	0.2	103.7	101.5	101.5	0.0	0.0	1.1	1.09	1.1	1.09	0.0	0.2	N/F	N/F	N/F	N/F	N/F	N/F
Parliament Mews																								
Ground	R1	W02-L	Living Room	31.2	30.8	0.4	1.2						0.1		0.0				59	17	59	17	1.0	1.0
		W02-U											0.3		0.3									
		W03-L		39.1	39.1	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.4		0.4									
		W04-L		37.7	37.7	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						293.8	287.2	287.2	0.0	0.0	0.4	1.38	0.4	1.37	0.0	0.2						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R2	W01-L	Kitchen	3.2	3.2	0.0	0.0						0.0		0.0				16	4	16	4	1.0	1.0
		W01-U						77.4	18.6	18.4	0.2	1.2	0.2	0.25	0.2	0.25	0.0	0.3						
Ground	R3	W05-L	Unknown	19.9	19.3	0.6	3.2						0.1		0.1				50	13	48	11	1.0	0.8
		W05-U						125.4	34.3	32.7	1.6	4.8	0.4	0.48	0.4	0.47	0.0	2.0						
Ground	R4	W06	KD	35.9	25.2	10.6	29.6						0.5		0.4				80	28	63	13	0.8	0.5
		W07-L		34.6	24.7	10.0	28.8						0.1		0.1				77	25	61	12	0.8	0.5
		W07-U						210.7	202.2	164.1	38.1	18.8	0.7	1.30	0.5	0.98	0.3	24.2						
Ground	R5	W08	KD	35.9	25.0	10.9	30.5						0.8		0.6				79	27	61	10	0.8	0.4
		W09-L		34.7	24.5	10.2	29.3						0.1		0.1				77	25	59	9	0.8	0.4
		W09-U						210.7	201.7	151.4	50.3	24.9	1.0	1.84	0.7	1.39	0.5	24.7						
Ground	R6	W10-L	KD	34.6	24.7	10.0	28.7						0.1		0.1				77	25	62	11	0.8	0.4
		W10-U											1.0		0.7									
		W11		35.9	25.5	10.4	28.9	210.7	200.8	154.8	46.0	22.9	0.8	1.84	0.6	1.40	0.4	23.9	79	27	63	11	0.8	0.4
Ground	R7	W12	KD	35.9	25.9	10.0	27.9						0.8		0.6				79	27	63	11	0.8	0.4
		W13-L		34.6	25.8	8.8	25.5						0.1		0.1				76	25	62	11	0.8	0.4
		W13-U						210.7	202.1	166.4	35.7	17.7	1.0	1.84	0.8	1.43	0.4	22.1						
Ground	R8	W14-L	KD	34.4	26.2	8.2	23.9						0.1		0.1				75	25	61	11	0.8	0.4
		W14-U											1.0		0.8									
		W15		33.5	25.3	8.2	24.4	210.7	200.7	162.6	38.1	19.0	0.7	1.80	0.6	1.44	0.4	19.9	71	26	58	13	0.8	0.5
Ground	R9	W16-L	Test	33.9	26.9	7.0	20.6						0.4		0.3				75	25	61	11	0.8	0.4
		W16-U											5.4		4.4									
		W17		64.7	62.2	2.5	3.8	171.9	171.9	164.2	7.7	4.5	10.2	15.90	9.8	14.54	1.4	8.5	80	26	69	15	0.9	0.6
Ground	R10	W18-L	Test	33.9	27.5	6.3	18.7						0.2		0.2				75	25	64	14	0.9	0.6
		W18-U											2.7		2.3									
		W19		65.3	63.1	2.2	3.4	182.9	182.9	155.2	27.7	15.1	5.2	8.10	5.1	7.48	0.6	7.8	80	26	70	16	0.9	0.6
Ground	R11	W20-L	Unknown	19.1	19.0	0.1	0.3						0.0		0.0				48	18	48	18	1.0	1.0
		W20-U						47.6	32.0	32.0	0.0	0.0	1.7	1.77	1.7	1.76	0.0	0.2						
First	R1	W02-L	Unknown	34.1	33.8	0.3	1.0						0.1		0.1				65	20	65	20	1.0	1.0
		W02-U											0.6		0.6									
		W03-L		39.2	39.2	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						178.7	175.2	175.0	0.2	0.1	0.6	1.36	0.6	1.36	0.0	0.3						
First	R2	W01-L	Unknown	5.6	5.6	0.1	1.2						0.0		0.0				22	6	22	6	1.0	1.0
		W01-U						73.0	22.2	22.1	0.2	0.9	0.4	0.40	0.3	0.40	0.0	1.2						
First	R3	W04-L	Unknown	34.6	33.6	1.0	2.9						0.0		0.0				66	21	66	21	1.0	1.0
		W04-U						131.1	116.8	116.8	0.1	0.1	0.7	0.70	0.7	0.68	0.0	2.1						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R4	W05-L	Unknown	34.8	33.5	1.2	3.6						0.1		0.1				65	22	64	21	1.0	1.0
		W05-U						131.1	121.0	121.0	0.0	0.0	0.7	0.76	0.7	0.74	0.0	2.7						
First	R5	W06-L	Bedroom	37.0	28.0	9.0	24.3						0.0		0.0				80	28	65	14	0.8	0.5
		W06-U						80.9	79.1	66.0	13.1	16.6	1.1	1.09	0.9	0.86	0.2	20.7						
First	R6	W07-L	Living Room	36.9	27.6	9.3	25.3						0.1		0.0				80	28	65	14	0.8	0.5
		W07-U											0.4		0.3									
		W08-L		18.8	18.8	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.4		0.4									
		W09-L		20.6	20.6	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						295.0	293.1	271.9	21.2	7.2	0.4	1.27	0.4	1.18	0.1	7.7						
First	R7	W10-L	Bedroom	37.1	27.8	9.2	24.9						0.0		0.0				80	28	66	15	0.8	0.5
		W10-U						80.9	78.7	51.5	27.3	34.6	1.1	1.09	0.9	0.86	0.2	21.2						
First	R8	W11-L	Living Room	37.0	27.5	9.5	25.6						0.1		0.0				80	28	64	13	0.8	0.5
		W11-U											0.4		0.3									
		W12-L		23.7	23.7	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											0.4		0.4									
		W13-L		28.9	28.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						295.0	295.0	293.8	1.2	0.4	0.5	1.44	0.5	1.34	0.1	6.9						
First	R9	W14-L	Living Room	37.0	27.7	9.3	25.1						0.1		0.0				80	28	65	14	0.8	0.5
		W14-U											0.4		0.3									
		W15-L		29.3	29.3	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.5		0.5									
		W16-L		23.5	23.5	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						295.0	295.0	292.7	2.4	0.8	0.4	1.44	0.4	1.34	0.1	6.8						
First	R10	W17-L	Bedroom	37.1	28.4	8.7	23.5						0.0		0.0				80	28	67	15	0.8	0.5
		W17-U						80.9	78.1	45.8	32.3	41.4	1.1	1.09	0.9	0.87	0.2	20.1						
First	R11	W18-L	Bedroom	37.1	28.6	8.4	22.8						0.0		0.0				80	28	67	15	0.8	0.5
		W18-U						80.9	79.0	44.9	34.0	43.1	1.1	1.09	0.9	0.88	0.2	19.5						
First	R12	W19-L	Living Room	37.0	28.7	8.3	22.4						0.1		0.0				80	28	69	17	0.9	0.6
		W19-U											0.4		0.3									
		W20-L		23.1	23.1	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U											0.4		0.4									
		W21-L		29.1	29.1	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W21-U						295.0	295.0	293.8	1.2	0.4	0.5	1.44	0.5	1.35	0.1	6.1						
First	R13	W22-L	Living Room	36.9	29.2	7.8	21.0						0.1		0.0				80	28	69	17	0.9	0.6
		W22-U											0.4		0.3									
		W23-L		28.9	28.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W23-U											0.5		0.5									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W24-L		24.1	24.1	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W24-U						295.0	295.0	292.7	2.4	0.8	0.4	1.44	0.4	1.36	0.1	5.7						
First	R14	W25-L	Bedroom	37.0	30.1	6.9	18.6						0.0		0.0				80	28	70	18	0.9	0.6
		W25-U						80.9	78.0	60.3	17.8	22.7	1.1	1.09	0.9	0.91	0.2	16.1						
First	R15	W26-L	Living Room	36.8	30.5	6.4	17.2						0.1		0.0				79	27	69	17	0.9	0.6
		W26-U											0.4		0.4									
		W27-L		18.7	18.7	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W27-U											0.4		0.4									
		W28-L		18.2	18.2	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W28-U						295.0	293.6	283.9	9.7	3.3	0.4	1.25	0.4	1.18	0.1	5.4						
First	R16	W29-L	Bedroom	36.9	31.6	5.4	14.5						0.0		0.0				79	27	71	19	0.9	0.7
		W29-U						80.9	78.2	71.6	6.7	8.5	1.1	1.09	0.9	0.95	0.1	12.7						
First	R17	W30-L	Living Room	26.3	26.0	0.2	0.8						0.1		0.1				50	9	49	8	1.0	0.9
		W30-U											0.6		0.6									
		W31-L		20.9	20.7	0.3	1.2						0.1		0.1				46	12	45	11	1.0	0.9
		W31-U						157.6	156.5	156.5	0.0	0.0	0.5	1.24	0.5	1.23	0.0	0.7						
First	R18	W32-L	Study	17.6	17.6	0.0	0.2						0.0		0.0				45	13	44	12	1.0	0.9
		W32-U											0.6		0.6									
		W33-L		33.8	33.5	0.3	0.8						0.1		0.1				60	15	59	14	1.0	0.9
		W33-U						86.1	84.9	84.9	0.0	0.0	1.0	1.81	1.0	1.81	0.0	0.4						
First	R19	W34-L	Study	34.3	34.1	0.2	0.6						0.1		0.1				62	17	62	17	1.0	1.0
		W34-U											1.0		1.0									
		W35-L		16.7	16.7	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W35-U						86.1	83.9	83.9	0.0	0.0	0.6	1.81	0.6	1.80	0.0	0.4						
First	R20	W36-L	Living Room	22.2	22.1	0.1	0.6						0.1		0.1				29	4	29	4	1.0	1.0
		W36-U											0.5		0.5									
		W37-L		25.0	24.8	0.2	0.8						0.1		0.1				37	8	37	8	1.0	1.0
		W37-U						157.6	156.0	156.0	0.0	0.0	0.6	1.24	0.6	1.23	0.0	0.5						
First	R21	W38-L	KD	25.0	24.8	0.2	0.9						0.1		0.1				51	18	51	18	1.0	1.0
		W38-U											0.4		0.4									
		W39-L		24.5	24.5	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W39-U											0.4		0.4									
		W40-L		33.0	33.0	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W40-U						223.9	222.8	222.6	0.2	0.1	0.5	1.51	0.5	1.51	0.0	0.2						
First	R22	W41-L	Living Room	24.2	24.0	0.2	0.7						0.1		0.1				57	20	57	20	1.0	1.0
		W41-U											0.4		0.4									
		W42-L		35.3	35.1	0.2	0.5						0.1		0.1				66	21	66	21	1.0	1.0
		W42-U											0.5		0.5									
		W43-L		35.8	35.6	0.2	0.4						0.1		0.1				66	21	66	21	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W43-U											0.6		0.5									
		W44-L		39.6	39.6	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W44-U						229.9	229.6	229.6	0.0	0.0	0.6	2.43	0.6	2.42	0.0	0.4						
Second	R1	W01-L	Unknown	38.9	38.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.7		0.7									
		W02-L		37.0	36.5	0.5	1.2						0.1		0.1				66	21	66	21	1.0	1.0
		W02-U						139.9	130.9	130.9	0.0	0.0	0.6	1.47	0.6	1.46	0.0	0.5						
Second	R2	W03-L	Unknown	20.0	19.8	0.2	1.0						0.0		0.0				47	12	47	12	1.0	1.0
		W03-U						73.0	50.4	50.3	0.1	0.2	0.7	0.77	0.7	0.76	0.0	0.7						
Second	R3	W04-L	Unknown	23.8	23.7	0.1	0.5						0.0		0.0				30	4	30	4	1.0	1.0
		W04-U						67.2	46.6	46.6	0.0	0.0	0.9	0.90	0.9	0.90	0.0	0.4						
Second	R4	W05-L	Unknown	36.9	35.9	1.0	2.7						0.0		0.0				68	23	67	22	1.0	1.0
		W05-U						116.7	106.5	106.5	0.0	0.0	0.8	0.86	0.8	0.84	0.0	2.2						
Second	R5	W06-L	Unknown	37.0	35.9	1.2	3.1						0.1		0.1				68	23	67	22	1.0	1.0
		W06-U						84.0	79.5	79.5	0.0	0.0	1.0	1.05	1.0	1.02	0.0	2.6						
Second	R6	W07-L	Unknown	35.7	34.0	1.7	4.7						0.0		0.0				77	25	76	24	1.0	1.0
		W07-U											0.5		0.5									
		W08-L		35.1	33.8	1.2	3.5						0.0		0.0				77	25	75	23	1.0	0.9
		W08-U											0.5		0.5									
		W09-L		34.1	34.1	0.1	0.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											0.5		0.5									
		W10-L		27.8	27.7	0.1	0.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						204.3	202.8	202.7	0.1	0.1	0.4	2.18	0.4	2.13	0.0	2.1						
Second	R8	W12-L	Bedroom	37.8	31.0	6.8	18.0						0.1		0.1				80	28	71	19	0.9	0.7
		W12-U						90.8	83.9	73.4	10.5	12.5	0.8	0.93	0.7	0.79	0.1	15.6						
Second	R10	W14-L	Bedroom	37.8	31.0	6.8	18.1						0.1		0.1				80	28	71	19	0.9	0.7
		W14-U						90.8	84.0	72.3	11.8	14.0	0.9	0.94	0.7	0.79	0.1	15.7						
Second	R11	W15-L	Bedroom	37.8	31.1	6.7	17.8						0.1		0.1				79	27	71	19	0.9	0.7
		W15-U						90.8	84.1	72.4	11.7	13.9	0.9	0.94	0.7	0.79	0.1	15.4						
Second	R14	W18-L	Bedroom	37.9	31.9	5.9	15.6						0.1		0.1				80	28	73	21	0.9	0.8
		W18-U						90.8	83.8	76.6	7.2	8.6	0.9	0.94	0.7	0.81	0.1	13.7						
Second	R15	W19-L	Bedroom	37.8	32.3	5.6	14.7						0.1		0.1				79	27	72	20	0.9	0.7
		W19-U						90.8	83.9	73.3	10.6	12.7	0.9	0.94	0.7	0.82	0.1	12.9						
Second	R17	W21-L	Bedroom	37.8	33.3	4.6	12.1						0.1		0.1				80	28	73	21	0.9	0.8
		W21-U						90.8	83.7	75.9	7.8	9.3	0.9	0.94	0.8	0.84	0.1	10.6						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Second	R19	W23-L	Bedroom	32.8	32.6	0.3	0.8						0.0		0.0				57	19	56	18	1.0	0.9
		W23-U											0.5		0.5									
		W24-L		27.1	26.7	0.4	1.6						0.0		0.0				56	22	55	21	1.0	1.0
		W24-U											0.5		0.4									
		W25-L		26.1	25.8	0.3	1.3						0.0		0.0				62	24	62	24	1.0	1.0
		W25-U						153.4	149.4	149.4	0.0	0.0	0.5	1.52	0.4	1.51	0.0	1.1						
Second	R22	W28-L	Bedroom	23.5	23.5	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W28-U											0.4		0.4									
		W29-L		26.5	26.4	0.1	0.5						0.0		0.0				40	4	40	4	1.0	1.0
		W29-U											0.5		0.4									
		W30-L		26.4	26.1	0.3	1.2						0.0		0.0				54	15	54	15	1.0	1.0
		W30-U						153.4	149.0	149.0	0.0	0.0	0.4	1.41	0.4	1.40	0.0	0.4						
Second	R24	W32-L	Bedroom	33.4	32.5	0.9	2.8						0.0		0.0				69	23	69	23	1.0	1.0
		W32-U											0.5		0.5									
		W33-L		39.6	39.6	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W33-U						184.2	177.9	177.4	0.5	0.3	0.6	1.23	0.6	1.22	0.0	1.1						
Combe House																								
Ground	R1	W01-L	Unknown	21.3	21.0	0.3	1.2						0.0		0.0				58	11	56	10	1.0	0.9
		W01-U											0.8		0.8									
		W02-L		29.7	28.7	1.1	3.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						93.0	90.6	79.0	11.7	12.9	1.0	1.85	1.0	1.81	0.0	1.7						
Ground	R2	W03-L	Unknown	29.4	28.4	1.0	3.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.4		0.4									
		W04-L		27.7	26.8	0.9	3.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						113.4	98.6	88.4	10.2	10.3	0.9	1.32	0.9	1.29	0.0	2.4						
Ground	R3	W05-L	Unknown	19.4	18.6	0.8	4.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						75.7	54.8	47.7	7.1	12.9	0.4	0.42	0.4	0.41	0.0	2.6						
Ground	R4	W06-L	Unknown	30.9	30.3	0.6	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						112.6	89.5	82.5	7.0	7.8	1.4	1.38	1.3	1.36	0.0	1.7						
Ground	R5	W07-L	Unknown	31.0	30.5	0.5	1.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						93.1	65.7	64.4	1.3	2.0	1.0	1.04	1.0	1.03	0.0	1.3						
Ground	R6	W08-L	Unknown	31.0	30.6	0.5	1.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						91.3	64.2	63.1	1.1	1.7	1.0	1.06	1.0	1.05	0.0	1.2						
Ground	R7	W09-L	Unknown	31.1	30.6	0.5	1.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						112.3	81.6	81.2	0.4	0.5	1.4	1.38	1.3	1.36	0.0	1.2						
Ground	R8	W10-L	Unknown	20.1	20.0	0.0	0.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						75.7	51.7	51.6	0.0	0.1	0.4	0.44	0.4	0.44	0.0	0.1						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R9	W11-L	Unknown	28.4	28.1	0.3	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.8		0.8									
		W12-L		30.2	29.8	0.4	1.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						113.4	83.2	82.4	0.8	1.0	0.4	1.28	0.4	1.27	0.0	0.8						
Ground	R10	W13-L	Unknown	31.0	30.5	0.5	1.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						93.0	67.7	67.2	0.5	0.8	1.0	1.03	1.0	1.02	0.0	1.2						
Ground	R11	W14-L	Unknown	31.0	30.6	0.4	1.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						93.0	67.7	67.6	0.1	0.2	1.1	1.07	1.0	1.06	0.0	1.1						
Ground	R12	W15-L	Unknown	30.4	30.0	0.4	1.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.4		0.4									
		W16-L		28.3	27.9	0.4	1.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						113.4	83.9	83.8	0.1	0.1	0.9	1.37	0.9	1.36	0.0	1.0						
Ground	R13	W17-L	Unknown	19.8	19.4	0.4	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U						75.7	51.8	51.7	0.1	0.1	0.4	0.45	0.4	0.44	0.0	1.0						
Ground	R14	W18-L	Unknown	31.7	31.4	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						112.6	82.3	82.2	0.1	0.1	1.4	1.40	1.4	1.39	0.0	0.9						
Ground	R15	W19-L	Unknown	31.9	31.6	0.3	1.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						93.1	66.1	66.1	0.0	0.0	1.1	1.09	1.1	1.08	0.0	0.7						
Ground	R16	W20-L	Unknown	32.1	31.8	0.3	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U						91.3	66.1	66.1	0.0	0.0	1.1	1.10	1.1	1.10	0.0	0.7						
Ground	R17	W21-L	Unknown	32.3	32.1	0.3	0.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W21-U						112.3	96.1	96.1	0.0	0.0	1.4	1.39	1.4	1.38	0.0	0.7						
Ground	R18	W22-L	Unknown	21.4	21.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W22-U						75.7	59.9	59.9	0.0	0.0	0.4	0.45	0.4	0.45	0.0	0.0						
Ground	R19	W23-L	Unknown	30.1	30.0	0.1	0.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W23-U											0.9		0.9									
		W24-L		31.9	31.7	0.2	0.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W24-U						113.4	104.9	104.9	0.0	0.0	0.4	1.37	0.4	1.36	0.0	0.4						
Ground	R20	W25-L	Unknown	32.9	32.7	0.2	0.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W25-U						90.6	84.1	84.1	0.0	0.0	1.1	1.13	1.1	1.12	0.0	0.5						
First	R1	W01-L	Unknown	25.8	25.4	0.4	1.4						0.0		0.0				67	11	67	11	1.0	1.0
		W01-U											0.9		0.9									
		W02-L		32.6	31.2	1.4	4.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						93.0	92.5	86.7	5.7	6.2	1.1	2.03	1.1	1.99	0.0	2.2						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R2	W03-L	Unknown	32.2	30.8	1.4	4.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.5		0.5									
		W04-L		30.3	29.0	1.3	4.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						113.4	113.0	111.7	1.2	1.1	0.9	1.41	0.9	1.36	0.0	3.4						
First	R3	W05-L	Unknown	21.3	20.0	1.3	5.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						75.7	72.5	60.3	12.2	16.9	0.4	0.45	0.4	0.43	0.0	3.9						
First	R4	W06-L	Unknown	33.6	32.4	1.1	3.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						112.6	111.7	107.0	4.8	4.3	1.5	1.51	1.5	1.47	0.0	2.9						
First	R5	W07-L	Unknown	33.6	32.6	1.0	3.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						93.1	92.3	89.0	3.3	3.6	1.1	1.14	1.1	1.11	0.0	2.5						
First	R6	W08-L	Unknown	33.6	32.7	0.9	2.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						91.3	90.3	87.9	2.4	2.6	1.2	1.19	1.2	1.16	0.0	2.3						
First	R7	W09-L	Unknown	33.7	32.8	0.9	2.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						112.3	111.5	111.5	0.0	0.0	1.5	1.50	1.5	1.47	0.0	2.2						
First	R8	W10-L	Unknown	21.7	21.5	0.1	0.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						75.7	72.2	72.2	0.0	0.0	0.5	0.46	0.5	0.46	0.0	0.3						
First	R9	W11-L	Unknown	30.8	30.2	0.6	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.9		0.9									
		W12-L		32.7	32.0	0.7	2.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						113.4	112.8	112.6	0.1	0.1	0.5	1.35	0.5	1.33	0.0	1.6						
First	R10	W13-L	Unknown	33.5	32.7	0.7	2.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						93.0	92.3	92.1	0.2	0.2	1.1	1.09	1.1	1.07	0.0	1.9						
First	R11	W14-L	Unknown	33.5	32.8	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						93.0	92.3	92.3	0.0	0.0	1.1	1.12	1.1	1.10	0.0	1.7						
First	R12	W15-L	Unknown	32.8	32.2	0.6	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.5		0.5									
		W16-L		30.7	30.1	0.6	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						113.4	113.0	113.0	0.0	0.0	1.0	1.44	0.9	1.42	0.0	1.5						
First	R13	W17-L	Unknown	21.5	20.9	0.6	2.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U						75.7	72.9	72.9	0.0	0.0	0.5	0.47	0.5	0.46	0.0	1.6						
First	R14	W18-L	Unknown	34.1	33.6	0.5	1.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						112.6	111.7	111.7	0.0	0.0	1.5	1.52	1.5	1.50	0.0	1.4						
First	R15	W19-L	Unknown	34.2	33.7	0.5	1.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						93.1	92.1	92.1	0.0	0.0	1.2	1.18	1.2	1.16	0.0	1.2						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R16	W20-L	Unknown	34.4	33.9	0.5	1.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U						91.3	90.5	90.5	0.0	0.0	1.2	1.20	1.2	1.18	0.0	1.1						
First	R17	W21-L	Unknown	34.5	34.1	0.4	1.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W21-U						112.3	111.3	111.3	0.0	0.0	1.5	1.51	1.5	1.49	0.0	1.1						
First	R18	W22-L	Unknown	22.6	22.6	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W22-U						75.7	72.6	72.6	0.0	0.0	0.5	0.48	0.5	0.48	0.0	0.0						
First	R19	W23-L	Unknown	32.0	31.8	0.3	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W23-U											1.0		1.0									
		W24-L		33.9	33.6	0.3	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W24-U						113.4	112.9	112.9	0.0	0.0	0.5	1.46	0.5	1.45	0.0	0.7						
First	R20	W25-L	Unknown	34.8	34.5	0.3	1.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W25-U						90.6	89.9	89.9	0.0	0.0	1.2	1.21	1.2	1.20	0.0	0.8						
Second	R1	W01-L	Unknown	31.6	31.2	0.4	1.3						0.0		0.0				78	21	77	20	1.0	1.0
		W01-U											1.1		1.1									
		W02-L		35.3	33.6	1.7	4.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						93.0	92.5	92.5	0.0	0.0	1.2	2.26	1.1	2.20	0.1	2.6						
Second	R2	W03-L	Unknown	34.8	33.2	1.7	4.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.5		0.5									
		W04-L		32.9	31.3	1.6	4.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						113.4	113.0	113.0	0.0	0.0	1.0	1.50	1.0	1.44	0.1	4.0						
Second	R3	W05-L	Unknown	22.3	20.7	1.5	6.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						75.7	72.7	67.6	5.1	7.0	0.5	0.46	0.4	0.44	0.0	4.6						
Second	R4	W06-L	Unknown	35.6	34.1	1.4	4.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						112.6	111.8	110.0	1.8	1.6	1.6	1.57	1.5	1.52	0.1	3.6						
Second	R5	W07-L	Unknown	35.7	34.4	1.3	3.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						93.1	92.3	91.7	0.6	0.6	1.2	1.18	1.1	1.15	0.0	3.2						
Second	R6	W08-L	Unknown	35.7	34.5	1.2	3.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						91.3	90.2	89.9	0.4	0.4	1.2	1.20	1.2	1.17	0.0	3.0						
Second	R7	W09-L	Unknown	35.6	34.5	1.1	3.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						112.3	111.5	111.5	0.0	0.0	1.5	1.56	1.5	1.52	0.0	2.8						
Second	R8	W10-L	Unknown	22.5	22.3	0.2	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						75.7	72.8	72.8	0.0	0.0	0.5	0.48	0.5	0.48	0.0	0.5						
Second	R9	W11-L	Unknown	33.1	32.2	0.9	2.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.9		0.9									
		W12-L		35.1	34.2	0.9	2.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W12-U						113.4	112.9	112.9	0.0	0.0	0.5	1.47	0.5	1.44	0.0	2.1						
Second	R10	W13-L	Unknown	35.7	34.8	0.9	2.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						93.0	92.3	92.3	0.0	0.0	1.2	1.18	1.1	1.15	0.0	2.3						
Second	R11	W14-L	Unknown	35.7	34.8	0.8	2.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						93.0	92.3	92.3	0.0	0.0	1.2	1.22	1.2	1.19	0.0	2.1						
Second	R12	W15-L	Unknown	35.2	34.4	0.8	2.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.5		0.5									
		W16-L		33.0	32.2	0.8	2.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						113.4	113.0	113.0	0.0	0.0	1.0	1.57	1.0	1.54	0.0	1.9						
Second	R13	W17-L	Unknown	22.4	21.6	0.7	3.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U						75.7	73.0	73.0	0.0	0.0	0.5	0.49	0.5	0.48	0.0	2.1						
Second	R14	W18-L	Unknown	35.9	35.2	0.7	1.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						112.6	111.7	111.7	0.0	0.0	1.6	1.58	1.5	1.55	0.0	1.8						
Second	R15	W19-L	Unknown	36.2	35.5	0.6	1.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						93.1	92.2	92.2	0.0	0.0	1.2	1.22	1.2	1.20	0.0	1.6						
Second	R16	W20-L	Unknown	36.2	35.6	0.6	1.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U						91.3	90.5	90.5	0.0	0.0	1.2	1.24	1.2	1.22	0.0	1.5						
Second	R17	W21-L	Unknown	36.2	35.6	0.5	1.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W21-U						112.3	111.3	111.3	0.0	0.0	1.5	1.55	1.5	1.53	0.0	1.4						
Second	R18	W22-L	Unknown	23.1	23.1	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W22-U						75.7	72.7	72.7	0.0	0.0	0.5	0.49	0.5	0.49	0.0	0.0						
Second	R19	W23-L	Unknown	34.0	33.6	0.4	1.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W23-U											1.0		1.0									
		W24-L		35.8	35.4	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W24-U						113.4	113.0	113.0	0.0	0.0	0.5	1.56	0.5	1.55	0.0	1.0						
Second	R20	W25-L	Unknown	36.5	36.1	0.4	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W25-U						90.6	89.9	89.9	0.0	0.0	1.3	1.29	1.3	1.27	0.0	1.1						
1 to 10 Cromwell Place																								
Below Grour	R1	W01	Unknown	36.7	34.9	1.8	5.0	202.8	195.3	195.3	0.0	0.0	1.4	1.36	1.3	1.30	0.1	4.6	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R2	W02	Unknown	0.8	0.8	0.0	0.0	41.8	0.0	0.0	0.0	0.0	0.1	0.08	0.1	0.08	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R3	W03	Unknown	34.2	32.9	1.3	3.8	129.6	118.9	118.9	0.0	0.0	1.7	1.68	1.6	1.63	0.1	3.1	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R4	W04	Unknown	34.8	33.4	1.4	4.0	129.6	121.3	121.3	0.0	0.0	1.6	1.63	1.6	1.57	0.1	3.6	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Below Grour	R5	W05	Unknown	9.4	8.2	1.2	12.5	41.8	37.0	37.0	0.0	0.0	0.4	0.42	0.4	0.39	0.0	7.3	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R6	W06	Unknown	7.5	7.5	0.0	0.0	41.8	33.6	33.6	0.0	0.0	0.4	0.37	0.4	0.37	0.0	0.0	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R7	W07	Unknown	36.0	34.9	1.1	2.9	129.6	121.5	121.5	0.0	0.0	1.7	1.67	1.6	1.63	0.0	2.7	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R8	W08	Unknown	35.8	34.5	1.3	3.5	129.6	121.5	121.5	0.0	0.0	1.7	1.71	1.7	1.66	0.1	3.2	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R9	W09	Unknown	4.1	3.5	0.6	14.9	41.8	26.2	26.2	0.0	0.0	0.3	0.30	0.3	0.27	0.0	8.8	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R10	W10	Unknown	18.5	18.2	0.3	1.8	34.4	15.9	15.9	0.0	0.0	0.6	0.56	0.6	0.55	0.0	0.3	N/F	N/F	N/F	N/F	N/F	N/F
Below Grour	R11	W11	Bedroom	30.2	29.7	0.6	1.8	72.5	69.2	69.2	0.0	0.0	1.4	1.41	1.4	1.39	0.0	1.4	51	18	51	18	1.0	1.0
Below Grour	R12	W12	Bedroom	31.5	30.9	0.6	2.0						0.2		0.2				49	18	49	18	1.0	1.0
		W13-L		28.0	27.9	0.1	0.3						0.0		0.0				47	16	47	16	1.0	1.0
		W13-U											0.3		0.2									
		W14-L		29.2	29.0	0.3	0.9						0.0		0.0				47	16	47	16	1.0	1.0
		W14-U						144.2	127.3	127.3	0.0	0.0	0.3	0.71	0.3	0.70	0.0	0.7						
Below Grour	R13	W15	Bedroom	31.0	30.4	0.5	1.7						0.2		0.1				45	13	45	13	1.0	1.0
		W16-L		28.5	28.0	0.5	1.8						0.0		0.0				37	7	37	7	1.0	1.0
		W16-U											0.3		0.3									
		W17-L		26.4	25.9	0.5	1.9						0.0		0.0				31	4	31	4	1.0	1.0
		W17-U						144.2	128.5	128.5	0.0	0.0	0.2	0.70	0.2	0.70	0.0	0.6						
Below Grour	R14	W18	Bedroom	32.0	31.6	0.4	1.1	72.5	69.2	69.2	0.0	0.0	1.5	1.48	1.5	1.46	0.0	0.9	53	18	53	18	1.0	1.0
Below Grour	R15	W19	Bedroom	32.1	31.8	0.3	0.9	72.5	69.2	69.2	0.0	0.0	1.5	1.48	1.5	1.47	0.0	0.7	54	19	54	19	1.0	1.0
Below Grour	R16	W20	Bedroom	32.4	32.2	0.2	0.6						0.2		0.2				49	15	49	15	1.0	1.0
		W21-L		28.9	28.9	0.0	0.0						0.0		0.0				49	14	49	14	1.0	1.0
		W21-U											0.3		0.3									
		W22-L		30.1	30.1	0.0	0.0						0.0		0.0				49	14	49	14	1.0	1.0
		W22-U						144.2	128.0	128.0	0.0	0.0	0.3	0.73	0.3	0.73	0.0	0.1						
Below Grour	R17	W23	Bedroom	32.2	31.9	0.3	1.0						0.2		0.2				51	13	51	13	1.0	1.0
		W24-L		29.6	29.4	0.2	0.7						0.0		0.0				44	7	44	7	1.0	1.0
		W24-U											0.3		0.3									
		W25-L		27.7	27.4	0.3	0.9						0.0		0.0				35	4	35	4	1.0	1.0
		W25-U						144.2	128.6	128.6	0.0	0.0	0.3	0.72	0.3	0.72	0.0	0.2						
Below Grour	R18	W26	Bedroom	31.8	31.5	0.3	0.9	72.5	69.2	69.2	0.0	0.0	1.5	1.47	1.5	1.46	0.0	0.7	48	10	48	10	1.0	1.0
Ground	R1	W01-L	Unknown	37.3	35.5	1.8	4.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						202.8	199.6	199.6	0.0	0.0	2.0	1.99	1.9	1.89	0.1	4.6						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R4	W04-L	Living Room	34.9	33.6	1.3	3.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						152.5	147.7	147.7	0.0	0.0	2.2	2.21	2.1	2.14	0.1	3.3						
Ground	R5	W05-L	Living Room	36.7	35.3	1.4	3.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						154.9	151.0	151.0	0.0	0.0	2.2	2.27	2.2	2.18	0.1	3.7						
Ground	R8	W08-L	Living Room	37.4	36.0	1.3	3.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						153.7	150.9	150.9	0.0	0.0	2.3	2.32	2.2	2.24	0.1	3.4						
Ground	R9	W09-L	Living Room	37.4	36.1	1.3	3.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						153.7	150.9	150.9	0.0	0.0	2.3	2.28	2.2	2.21	0.1	3.3						
Ground	R11	W11	Unknown	26.4	25.5	0.9	3.4	34.4	30.2	30.2	0.0	0.0	0.6	0.56	0.6	0.55	0.0	2.1	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R12	W12	Unknown	26.8	25.6	1.2	4.6	124.5	117.8	117.8	0.0	0.0	0.8	0.82	0.8	0.79	0.0	3.4	37	10	35	10	0.9	1.0
Ground	R13	W13	Unknown	33.6	32.6	1.0	3.0	16.4	16.1	16.1	0.0	0.0	1.8	1.80	1.8	1.76	0.0	2.2	53	20	52	20	1.0	1.0
Ground	R14	W14	Unknown	34.0	33.3	0.8	2.3	158.1	153.2	153.2	0.0	0.0	1.6	1.58	1.6	1.55	0.0	2.0	52	19	52	19	1.0	1.0
Ground	R15	W15	Unknown	31.4	30.8	0.6	1.9	160.3	154.3	154.3	0.0	0.0	1.4	1.41	1.4	1.39	0.0	1.5	51	19	51	19	1.0	1.0
Ground	R16	W16	Unknown	33.8	33.4	0.5	1.4	16.4	16.1	16.1	0.0	0.0	1.5	1.49	1.5	1.48	0.0	0.7	49	19	49	19	1.0	1.0
Ground	R17	W17	Unknown	32.7	32.2	0.5	1.4	16.4	15.9	15.9	0.0	0.0	1.4	1.44	1.4	1.43	0.0	0.7	51	20	51	20	1.0	1.0
Ground	R18	W18	Unknown	35.0	34.6	0.5	1.3	159.2	153.7	153.7	0.0	0.0	1.6	1.61	1.6	1.59	0.0	1.2	55	20	55	20	1.0	1.0
Ground	R19	W19	Unknown	35.2	34.8	0.5	1.3	159.2	154.0	154.0	0.0	0.0	1.6	1.62	1.6	1.60	0.0	1.1	58	20	57	20	1.0	1.0
Ground	R20	W20	Unknown	34.8	34.4	0.4	1.2	16.4	16.3	16.3	0.0	0.0	1.5	1.51	1.5	1.50	0.0	0.6	55	17	55	17	1.0	1.0
First	R1	W01-L	Unknown	38.0	36.2	1.8	4.7						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						188.9	186.4	186.4	0.0	0.0	2.1	2.14	2.0	2.04	0.1	4.5						
First	R2	W02-L	Unknown	22.2	22.0	0.2	0.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						56.5	55.6	55.6	0.0	0.0	2.0	2.07	2.0	2.06	0.0	0.4						
First	R3	W03-L	Study	30.0	29.1	0.9	3.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						61.8	59.9	59.9	0.0	0.0	2.4	2.42	2.3	2.36	0.1	2.3						
First	R4	W04-L	Living Room	35.7	34.4	1.3	3.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						152.1	148.8	148.8	0.0	0.0	2.2	2.25	2.1	2.17	0.1	3.3						
First	R5	W05-L	Living Room	37.3	35.9	1.4	3.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						150.7	148.6	148.6	0.0	0.0	2.3	2.36	2.2	2.28	0.1	3.7						
First	R6	W06-L	Study	37.7	36.3	1.4	3.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W06-U						62.8	62.4	62.4	0.0	0.0	3.0	3.13	2.9	3.01	0.1	3.6						
First	R7	W07-L	Study	37.8	36.4	1.4	3.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						61.0	60.5	60.5	0.0	0.0	3.1	3.19	3.0	3.07	0.1	3.5						
First	R8	W08-L	Living Room	37.9	36.5	1.3	3.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						153.1	151.1	151.0	0.0	0.0	2.3	2.37	2.2	2.29	0.1	3.5						
First	R9	W09-L	Living Room	38.0	36.7	1.3	3.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						144.1	142.2	142.2	0.0	0.0	2.4	2.45	2.3	2.37	0.1	3.4						
First	R10	W10-L	Study	38.1	36.8	1.3	3.4						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						67.5	67.1	67.1	0.0	0.0	3.0	3.10	2.9	3.00	0.1	3.2						
First	R11	W11	Unknown	34.6	33.2	1.4	4.0	112.4	109.3	109.3	0.0	0.0	1.6	1.60	1.5	1.55	0.1	3.5	47	14	46	14	1.0	1.0
First	R12	W12	Unknown	36.2	35.2	1.1	2.9						1.5		1.5				56	20	56	20	1.0	1.0
		W13-L		36.4	35.5	0.9	2.4						0.0		0.0				56	20	55	20	1.0	1.0
		W13-U						190.5	187.8	187.8	0.0	0.0	1.3	2.87	1.3	2.80	0.1	2.5						
First	R13	W14	Unknown	37.0	36.2	0.8	2.2						0.2		0.2				57	20	56	20	1.0	1.0
		W15-L		36.4	35.7	0.8	2.1						0.0		0.0				57	20	56	20	1.0	1.0
		W15-U											0.2		0.2									
		W16-L		36.5	35.7	0.7	2.0						0.0		0.0				57	20	56	20	1.0	1.0
		W16-U											0.2		0.2									
		W17		37.0	36.3	0.7	1.9	191.2	183.7	183.7	0.0	0.0	1.2	1.88	1.2	1.85	0.0	1.6	57	20	56	20	1.0	1.0
First	R14	W18	Unknown	37.2	36.5	0.6	1.7						1.2		1.2				58	21	57	21	1.0	1.0
		W19		37.2	36.6	0.6	1.6	189.5	186.8	186.8	0.0	0.0	1.6	2.76	1.6	2.72	0.0	1.5	58	21	57	21	1.0	1.0
First	R15	W20-L	Unknown	37.3	36.9	0.5	1.3						0.0		0.0				58	21	57	21	1.0	1.0
		W20-U											1.3		1.3									
		W21		37.4	37.0	0.5	1.2	190.5	187.7	187.7	0.0	0.0	1.6	2.95	1.6	2.92	0.0	1.2	60	21	59	21	1.0	1.0
Second	R1	W01-L	Bedroom	38.5	36.7	1.8	4.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						188.9	186.3	186.3	0.0	0.0	1.6	1.66	1.6	1.59	0.1	4.5						
Second	R2	W02-L	Bedroom	21.1	21.0	0.2	0.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						54.3	53.9	53.9	0.0	0.0	1.5	1.51	1.5	1.50	0.0	0.5						
Second	R3	W03-L	Bedroom	29.3	28.4	0.9	3.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						54.3	53.9	53.9	0.0	0.0	1.9	1.87	1.8	1.82	0.0	2.3						
Second	R4	W04-L	Bedroom	34.1	32.8	1.3	3.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						162.5	158.9	158.9	0.0	0.0	1.5	1.49	1.4	1.45	0.0	3.2						
Second	R5	W05-L	Bedroom	35.2	33.8	1.4	4.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						162.5	159.7	159.7	0.0	0.0	1.5	1.53	1.5	1.48	0.1	3.5						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Second	R6	W06-L	Bedroom	35.5	34.1	1.4	3.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						54.3	54.2	54.2	0.0	0.0	2.3	2.31	2.2	2.23	0.1	3.4						
Second	R7	W07-L	Bedroom	35.6	34.2	1.4	3.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						51.5	51.4	51.4	0.0	0.0	2.4	2.38	2.3	2.30	0.1	3.4						
Second	R8	W08-L	Bedroom	35.6	34.3	1.3	3.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						162.5	160.0	159.9	0.0	0.0	1.5	1.53	1.5	1.48	0.1	3.3						
Second	R9	W09-L	Bedroom	35.7	34.4	1.3	3.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						162.5	160.1	160.1	0.1	0.0	1.5	1.53	1.5	1.47	0.1	3.3						
Second	R10	W10-L	Bedroom	36.0	34.7	1.3	3.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						54.3	54.1	54.1	0.0	0.0	2.2	2.27	2.2	2.20	0.1	3.1						
Second	R11	W11	Bedroom	36.1	34.8	1.3	3.5	112.4	110.9	110.9	0.0	0.0	1.5	1.50	1.4	1.45	0.0	3.3	50	15	49	15	1.0	1.0
Second	R12	W12	Unknown	34.6	33.5	1.1	3.1	37.5	36.9	36.9	0.0	0.0	3.0	3.04	3.0	2.95	0.1	2.7	50	17	49	17	1.0	1.0
Second	R13	W13	Bedroom	34.6	33.6	1.0	2.8	152.2	147.5	147.5	0.0	0.0	1.2	1.15	1.1	1.13	0.0	2.4	50	17	49	17	1.0	1.0
Second	R14	W14	Bedroom	34.7	33.9	0.8	2.4	150.8	146.2	146.2	0.0	0.0	1.2	1.17	1.1	1.14	0.0	2.1	50	17	49	17	1.0	1.0
Second	R15	W15	Unknown	34.8	34.0	0.8	2.2	38.1	37.5	37.5	0.0	0.0	3.0	3.02	3.0	2.97	0.1	1.9	50	17	49	17	1.0	1.0
Second	R16	W16	Unknown	34.8	34.2	0.7	2.0	37.0	36.5	36.5	0.0	0.0	3.1	3.09	3.0	3.03	0.1	1.7	50	17	50	17	1.0	1.0
Second	R17	W17	Bedroom	34.9	34.3	0.6	1.8	153.3	148.8	148.7	0.1	0.0	1.2	1.16	1.1	1.14	0.0	1.5	50	17	50	17	1.0	1.0
Second	R18	W18-L	Bedroom	35.0	34.4	0.5	1.5						0.0		0.0				50	17	50	17	1.0	1.0
		W18-U						144.2	140.3	140.3	0.0	0.0	1.2	1.16	1.1	1.15	0.0	1.3						
Second	R19	W19	Unknown	35.0	34.6	0.5	1.4	41.0	40.0	39.9	0.0	0.0	2.9	2.89	2.9	2.86	0.0	1.2	52	19	52	19	1.0	1.0
Third	R1	W01	Unknown	38.6	37.4	1.2	3.1	43.0	35.6	35.6	0.0	0.0	0.9	0.93	0.9	0.91	0.0	2.8	N/F	N/F	N/F	N/F	N/F	N/F
Third	R2	W02-L	Unknown	36.3	33.2	3.1	8.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.2		0.2									
		W03		84.0	83.1	0.9	1.1	114.9	114.9	114.9	0.0	0.0	2.4	2.71	2.4	2.67	0.0	1.5	87	27	86	27	1.0	1.0
Third	R3	W04	Unknown	87.4	86.6	0.8	0.9	67.4	61.2	61.2	0.0	0.0	3.6	3.60	3.6	3.59	0.0	0.5	86	26	85	26	1.0	1.0
Third	R4	W05	Unknown	85.3	84.7	0.6	0.8	84.4	76.4	76.4	0.0	0.0	4.8	4.75	4.7	4.73	0.0	0.5	70	20	69	20	1.0	1.0
Third	R5	W06	Unknown	84.4	83.9	0.6	0.7						2.6		2.6				87	27	86	27	1.0	1.0
		W07		86.9	86.3	0.5	0.6	109.9	97.3	97.3	0.0	0.0	2.6	5.23	2.6	5.21	0.0	0.3	87	27	87	27	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Third	R6	W08	Unknown	86.8	86.4	0.4	0.5						2.6		2.6				77	20	77	20	1.0	1.0
		W09		84.1	83.7	0.4	0.5	109.9	97.3	97.3	0.0	0.0	2.6	5.19	2.6	5.18	0.0	0.2	64	20	64	20	1.0	1.0
22 Cromwell Place																								
First	R1	W01-L	Unknown	33.8	33.5	0.4	1.1						0.0		0.0				50	16	50	16	1.0	1.0
		W01-U						232.2	219.6	219.0	0.6	0.3	0.6	0.60	0.6	0.60	0.0	0.8						
Reid Court																								
Ground	R1	W01	Unknown	34.9	22.3	12.5	36.0						1.2		0.8				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		34.3	21.9	12.4	36.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						234.0	231.6	210.8	20.8	9.0	0.8	2.02	0.6	1.44	0.6	28.7						
Ground	R2	W03	Unknown	33.5	22.7	10.9	32.4	200.4	197.9	186.8	11.0	5.6	2.1	2.09	1.6	1.56	0.5	25.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R3	W04	Unknown	34.6	26.9	7.7	22.3	195.8	193.5	186.4	7.0	3.6	2.2	2.24	1.8	1.83	0.4	18.5	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W05-L	Unknown	36.0	27.9	8.1	22.5						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.8		0.6									
		W06		36.3	28.8	7.5	20.8	219.3	217.0	215.3	1.6	0.8	1.3	2.17	1.1	1.78	0.4	18.0	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W07	Unknown	36.2	30.0	6.2	17.2						1.4		1.2				N/F	N/F	N/F	N/F	N/F	N/F
		W08-L		35.5	29.5	6.0	17.0						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						219.3	217.7	217.7	0.0	0.0	0.8	2.23	0.7	1.91	0.3	14.4						
Ground	R6	W09	Unknown	34.2	29.0	5.3	15.4	195.8	193.7	193.7	0.0	0.0	2.2	2.18	1.9	1.91	0.3	12.6	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R7	W10	Unknown	33.9	31.3	2.6	7.6	200.4	198.0	197.9	0.0	0.0	2.1	2.08	1.9	1.94	0.1	6.5	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R8	W11-L	Unknown	34.6	31.1	3.5	10.1						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.8		0.7									
		W12		34.9	31.4	3.5	10.0	232.5	230.1	230.0	0.0	0.0	1.2	2.09	1.1	1.91	0.2	8.4	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R9	W13	Unknown	32.3	28.3	4.0	12.4						1.2		1.1				56	15	49	9	0.9	0.6
		W14-L		32.7	28.6	4.1	12.5						0.0		0.0				58	16	52	10	0.9	0.6
		W14-U						234.0	231.0	231.0	0.0	0.0	0.9	2.16	0.8	1.95	0.2	9.8						
Ground	R10	W15	Unknown	33.0	29.6	3.4	10.4	200.4	197.9	197.9	0.0	0.0	2.1	2.13	1.9	1.95	0.2	8.4	63	18	58	13	0.9	0.7
Ground	R11	W16	Unknown	34.4	31.5	2.9	8.3	195.8	193.4	193.4	0.0	0.0	2.3	2.26	2.1	2.10	0.2	7.2	68	22	64	18	0.9	0.8
Ground	R12	W17-L	Unknown	35.0	31.6	3.5	9.9						0.1		0.0				67	23	62	18	0.9	0.8
		W17-U											0.8		0.8									
		W18		35.5	32.0	3.5	9.9	219.3	216.9	216.7	0.3	0.1	1.3	2.19	1.2	2.00	0.2	8.6	69	23	64	18	0.9	0.8
Ground	R13	W19	Unknown	35.6	32.3	3.3	9.3						1.3		1.2				68	23	64	19	0.9	0.8
		W20-L		35.1	31.8	3.3	9.4						0.1		0.1				69	23	64	18	0.9	0.8

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W20-U						219.3	217.1	214.3	2.7	1.3	0.8	2.22	0.8	2.04	0.2	8.1						
Ground	R14	W21	Unknown	34.2	31.3	2.9	8.4	195.8	193.8	193.6	0.2	0.1	2.3	2.28	2.1	2.12	0.2	7.1	67	22	62	17	0.9	0.8
Ground	R15	W22	Unknown	33.7	32.3	1.4	4.1	200.4	198.1	197.7	0.4	0.2	2.2	2.19	2.1	2.11	0.1	3.7	69	23	66	20	1.0	0.9
Ground	R16	W23-L	Unknown	33.0	30.8	2.2	6.5						0.0		0.0				62	22	58	18	0.9	0.8
		W23-U											0.7		0.7									
		W24		32.8	30.6	2.3	6.9	232.5	229.9	229.8	0.1	0.1	1.2	1.97	1.1	1.86	0.1	5.6	64	22	61	19	1.0	0.9
First	R1	W01	Unknown	36.2	24.0	12.2	33.6						1.2		0.9				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		36.2	24.2	12.0	33.2						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						234.0	232.0	218.1	13.9	6.0	0.9	2.24	0.7	1.63	0.6	27.2						
First	R2	W03	Unknown	36.8	25.7	11.1	30.2	132.3	130.0	117.0	13.0	10.0	1.5	1.49	1.1	1.12	0.4	25.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W04	Unknown	36.9	26.7	10.2	27.5	132.3	130.6	121.5	9.1	7.0	1.5	1.54	1.2	1.19	0.4	23.0	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W05	Unknown	36.9	27.8	9.1	24.6	132.3	130.4	125.1	5.3	4.1	1.5	1.51	1.2	1.19	0.3	20.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R5	W06	Unknown	36.9	28.8	8.1	21.9	132.3	130.6	126.9	3.6	2.8	1.6	1.56	1.3	1.27	0.3	18.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R6	W07-L	Unknown	36.6	29.4	7.2	19.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											0.9		0.7									
		W08		36.7	30.2	6.5	17.8	228.5	226.7	225.1	1.6	0.7	1.3	2.30	1.1	1.94	0.4	15.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R7	W09	Unknown	36.6	31.3	5.3	14.4						1.4		1.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10-L		36.5	31.4	5.2	14.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						228.5	226.6	226.6	0.0	0.0	0.9	2.40	0.8	2.10	0.3	12.3						
First	R8	W11	Unknown	36.8	32.3	4.6	12.4	132.3	130.5	130.5	0.0	0.0	1.5	1.52	1.4	1.35	0.2	10.9	N/F	N/F	N/F	N/F	N/F	N/F
First	R9	W12	Unknown	36.8	32.7	4.1	11.2	132.3	130.4	130.4	0.0	0.0	1.5	1.51	1.4	1.36	0.2	10.0	N/F	N/F	N/F	N/F	N/F	N/F
First	R10	W13	Unknown	36.7	33.0	3.7	10.2	132.3	130.5	130.4	0.1	0.0	1.5	1.49	1.4	1.35	0.1	9.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R11	W14	Unknown	36.6	33.2	3.4	9.2	132.3	130.5	130.4	0.0	0.0	1.5	1.51	1.4	1.38	0.1	8.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R12	W15-L	Unknown	36.0	32.8	3.1	8.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.9		0.9									
		W16		36.0	33.1	2.9	8.0	232.5	230.6	230.5	0.0	0.0	1.3	2.31	1.2	2.14	0.2	7.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R13	W17	Unknown	33.7	30.3	3.4	10.0						1.3		1.2				60	16	55	11	0.9	0.7
		W18-L		34.3	30.9	3.5	10.1						0.1		0.1				62	17	56	11	0.9	0.6
		W18-U						234.0	232.3	232.3	0.0	0.0	0.9	2.23	0.8	2.05	0.2	8.3						
First	R14	W19	Unknown	35.7	32.4	3.3	9.3	132.3	130.6	130.6	0.1	0.0	1.5	1.54	1.4	1.41	0.1	8.1	68	22	63	17	0.9	0.8

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R15	W20	Unknown	36.0	32.8	3.2	9.0	132.3	130.7	130.6	0.1	0.0	1.5	1.55	1.4	1.42	0.1	8.0	69	23	65	19	0.9	0.8
First	R16	W21	Unknown	36.2	33.0	3.1	8.7	132.3	130.9	130.8	0.1	0.0	1.5	1.54	1.4	1.42	0.1	7.7	68	22	65	19	1.0	0.9
First	R17	W22	Unknown	36.3	33.2	3.1	8.4	132.3	130.8	130.7	0.1	0.1	1.5	1.53	1.4	1.41	0.1	7.6	69	23	66	20	1.0	0.9
First	R18	W23-L	Unknown	36.0	32.9	3.1	8.5						0.1		0.1				68	23	65	20	1.0	0.9
		W23-U											0.9		0.8									
		W24		36.1	33.2	2.9	8.1	228.5	227.0	227.0	0.0	0.0	1.3	2.23	1.2	2.07	0.2	7.3	68	23	65	20	1.0	0.9
First	R19	W25	Unknown	36.1	33.4	2.8	7.6						1.3		1.2				68	23	65	20	1.0	0.9
		W26-L		36.0	33.2	2.8	7.7						0.1		0.1				67	23	64	20	1.0	0.9
		W26-U						228.5	226.9	226.9	0.0	0.0	0.9	2.30	0.8	2.15	0.2	6.8						
First	R20	W27	Unknown	36.4	33.8	2.6	7.1	132.3	130.9	130.9	0.0	0.0	1.6	1.56	1.5	1.46	0.1	6.4	70	24	68	22	1.0	0.9
First	R21	W28	Unknown	36.4	33.9	2.5	6.8	132.3	130.9	130.9	0.0	0.0	1.6	1.55	1.5	1.46	0.1	6.2	71	25	69	23	1.0	0.9
First	R22	W29	Unknown	36.3	34.0	2.3	6.4	132.3	130.7	130.7	0.0	0.0	1.5	1.54	1.4	1.45	0.1	5.9	70	25	68	23	1.0	0.9
First	R23	W30	Unknown	36.3	34.1	2.2	6.1	132.3	130.7	130.7	0.0	0.0	1.6	1.56	1.5	1.48	0.1	5.5	70	25	69	24	1.0	1.0
First	R24	W31-L	Unknown	35.8	33.7	2.1	5.9						0.1		0.1				67	23	66	22	1.0	1.0
		W31-U											0.8		0.8									
		W32		35.9	33.9	2.0	5.5	232.5	230.8	230.8	0.0	0.0	1.3	2.21	1.2	2.10	0.1	5.0	68	24	68	24	1.0	1.0
Second	R1	W01	Unknown	25.9	15.0	10.9	42.0						0.9		0.6				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		32.3	21.6	10.8	33.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						234.0	231.4	216.4	14.9	6.4	0.6	1.57	0.4	1.07	0.5	31.9						
Second	R2	W03-L	Unknown	29.7	20.1	9.7	32.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						132.3	130.2	116.2	14.0	10.8	1.1	1.13	0.8	0.83	0.3	25.9						
Second	R3	W04-L	Unknown	29.8	21.0	8.7	29.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						132.3	130.9	120.4	10.5	8.0	1.2	1.16	0.9	0.89	0.3	23.3						
Second	R4	W05-L	Unknown	29.8	22.1	7.7	26.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						132.3	130.6	123.8	6.8	5.2	1.1	1.14	0.9	0.90	0.2	20.6						
Second	R5	W06-L	Unknown	29.8	23.0	6.8	22.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						132.3	130.9	125.6	5.3	4.1	1.2	1.18	1.0	0.96	0.2	18.1						
Second	R6	W07-L	Unknown	32.6	26.6	6.0	18.5						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											0.6		0.5									
		W08		26.0	20.6	5.4	20.7	227.9	225.5	223.4	2.1	0.9	0.9	1.62	0.8	1.36	0.3	16.2	N/F	N/F	N/F	N/F	N/F	N/F
Second	R7	W09-L	Unknown	27.3	22.9	4.3	15.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											1.0		0.9									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W10-L		32.7	28.4	4.2	13.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						227.9	226.4	226.3	0.1	0.0	0.6	1.69	0.5	1.49	0.2	11.8						
Second	R8	W11-L	Unknown	29.8	26.1	3.7	12.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U						132.3	130.8	130.8	0.0	0.0	1.1	1.15	1.0	1.04	0.1	9.8						
Second	R9	W12-L	Unknown	29.8	26.5	3.3	11.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						132.3	130.7	130.7	0.0	0.0	1.1	1.14	1.0	1.04	0.1	8.8						
Second	R10	W13-L	Unknown	29.7	26.8	3.0	10.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						132.3	130.7	130.7	0.0	0.0	1.1	1.13	1.0	1.04	0.1	7.9						
Second	R11	W14-L	Unknown	29.7	27.0	2.7	9.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						132.3	130.6	130.5	0.0	0.0	1.1	1.15	1.1	1.06	0.1	7.1						
Second	R12	W15-L	Unknown	32.1	29.6	2.5	7.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.7		0.6									
		W16		25.9	23.7	2.2	8.6	232.5	230.1	229.9	0.2	0.1	0.9	1.65	0.9	1.54	0.1	6.4	N/F	N/F	N/F	N/F	N/F	N/F
Second	R13	W17	Unknown	25.1	22.4	2.7	10.8						0.9		0.8				49	20	47	18	1.0	0.9
		W18-L		31.5	28.7	2.8	8.9						0.1		0.1				61	23	59	21	1.0	0.9
		W18-U						234.0	231.0	231.0	0.0	0.0	0.7	1.64	0.6	1.51	0.1	8.1						
Second	R14	W19-L	Unknown	29.4	26.7	2.7	9.1						0.0		0.0				56	21	54	19	1.0	0.9
		W19-U						132.3	130.6	130.6	0.0	0.0	1.2	1.20	1.1	1.11	0.1	7.2						
Second	R15	W20-L	Unknown	29.5	26.9	2.6	8.8						0.0		0.0				56	21	54	19	1.0	0.9
		W20-U						132.3	130.6	130.6	0.0	0.0	1.2	1.20	1.1	1.12	0.1	7.0						
Second	R16	W21-L	Unknown	29.6	27.1	2.5	8.5						0.0		0.0				56	21	55	20	1.0	1.0
		W21-U						132.3	130.9	130.9	0.0	0.0	1.2	1.19	1.1	1.11	0.1	6.8						
Second	R17	W22-L	Unknown	29.7	27.2	2.4	8.2						0.0		0.0				56	21	54	19	1.0	0.9
		W22-U						132.3	130.8	130.8	0.0	0.0	1.2	1.19	1.1	1.11	0.1	6.6						
Second	R18	W23-L	Unknown	32.2	29.8	2.5	7.6						0.1		0.1				61	23	59	21	1.0	0.9
		W23-U											0.6		0.6									
		W24		25.8	23.4	2.3	9.0	227.9	225.0	225.0	0.0	0.0	0.9	1.64	0.8	1.53	0.1	6.9	51	22	49	20	1.0	0.9
Second	R19	W25	Unknown	26.0	23.8	2.2	8.5						0.9		0.9				51	22	50	21	1.0	1.0
		W26-L		32.3	30.1	2.2	6.9						0.1		0.1				62	24	60	22	1.0	0.9
		W26-U						227.9	225.8	225.8	0.0	0.0	0.7	1.69	0.6	1.59	0.1	6.3						
Second	R20	W27-L	Unknown	29.8	27.8	2.1	6.9						0.0		0.0				57	22	57	22	1.0	1.0
		W27-U						132.3	130.9	130.9	0.0	0.0	1.2	1.21	1.1	1.14	0.1	5.5						
Second	R21	W28-L	Unknown	29.8	27.9	2.0	6.5						0.0		0.0				57	22	57	22	1.0	1.0
		W28-U						132.3	130.9	130.9	0.0	0.0	1.2	1.21	1.1	1.14	0.1	5.3						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Second	R22	W29-L	Unknown	29.8	28.0	1.9	6.2						0.0		0.0				57	22	57	22	1.0	1.0
		W29-U						132.3	130.7	130.7	0.0	0.0	1.2	1.20	1.1	1.14	0.1	5.0						
Second	R23	W30-L	Unknown	29.8	28.1	1.8	5.9						0.0		0.0				57	22	57	22	1.0	1.0
		W30-U						132.3	130.6	130.6	0.0	0.0	1.2	1.22	1.2	1.16	0.1	4.7						
Second	R24	W31-L	Unknown	32.0	30.3	1.7	5.3						0.1		0.1				60	22	59	21	1.0	1.0
		W31-U											0.6		0.6									
		W32		26.1	24.5	1.6	6.1	232.5	229.7	229.7	0.0	0.0	0.9	1.62	0.9	1.55	0.1	4.7	51	22	51	22	1.0	1.0
Churchill Court																								
Ground	R1	W01-L	Bedroom	22.5	20.9	1.6	7.1						0.1		0.1				63	10	59	9	0.9	0.9
		W01-U											0.9		0.9									
		W02-L		15.9	10.5	5.4	34.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.2		0.1									
		W03-L		15.3	9.9	5.4	35.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.2		0.2									
		W04-L		14.1	8.8	5.3	37.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						208.7	202.0	128.9	73.1	36.2	0.2	1.65	0.1	1.38	0.3	16.2						
Ground	R2	W05-L	Bedroom	8.7	6.3	2.4	27.8						0.0		0.0				24	6	20	5	0.8	0.8
		W05-U											0.3		0.2									
		W06-L		31.6	26.5	5.1	16.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.1		0.9									
		W07-L		31.3	26.6	4.7	14.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						145.6	144.7	134.4	10.2	7.1	1.1	2.56	1.0	2.23	0.3	12.8						
Ground	R3	W08-L	Unknown	14.0	11.8	2.2	15.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.2		0.2									
		W09-L		17.1	13.9	3.2	18.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											0.4		0.3									
		W10-L		17.6	14.3	3.3	18.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						153.0	141.6	94.7	46.9	33.1	0.2	0.98	0.2	0.84	0.1	14.4						
Ground	R4	W11-L	Unknown	15.0	12.3	2.8	18.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U						153.0	126.6	93.9	32.7	25.8	0.6	0.66	0.6	0.57	0.1	13.7						
Ground	R5	W12-L	Unknown	16.9	14.9	2.0	11.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											0.2		0.2									
		W13-L		16.5	14.4	2.0	12.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.4		0.3									
		W14-L		13.8	11.9	1.9	14.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						153.0	123.2	115.4	7.7	6.3	0.2	0.90	0.2	0.81	0.1	9.9						
Ground	R6	W15-L	Bedroom	29.2	27.5	1.6	5.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											1.0		1.0									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W16-L		29.2	27.7	1.5	5.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						145.3	141.1	139.4	1.7	1.2	1.0	2.14	1.0	2.05	0.1	4.2						
Ground	R7	W17-L	Bedroom	10.7	9.9	0.8	7.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											0.2		0.2									
		W18-L		12.4	11.1	1.3	10.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U											0.3		0.3									
		W19-L		14.8	13.2	1.6	10.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						125.2	112.9	115.5	-2.5	-2.2	0.2	0.77	0.2	0.70	0.1	9.5						
Ground	R8	W20-L	LKD	25.1	25.0	0.1	0.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U											0.3		0.3									
		W21-L		31.8	31.8	0.0	0.0						0.0		0.0				34	8	34	8	1.0	1.0
		W21-U											0.3		0.3									
		W22-L		31.3	31.3	0.0	0.0						0.0		0.0				31	7	31	7	1.0	1.0
		W22-U											0.4		0.4									
		W23-L		29.5	29.5	0.0	0.0						0.0		0.0				27	5	27	5	1.0	1.0
		W23-U											0.3		0.3									
		W24-L		26.0	26.0	0.0	0.0						0.0		0.0				17	1	17	1	1.0	1.0
		W24-U						286.9	281.1	281.1	0.0	0.0	0.2	1.61	0.2	1.61	0.0	0.0						
Ground	R9	W25-L	Unknown	24.6	23.8	0.8	3.3						0.1		0.1				66	13	63	12	1.0	0.9
		W25-U						270.0	208.5	207.0	1.6	0.8	0.8	0.90	0.8	0.88	0.0	2.0						
First	R1	W01-L	Bedroom	27.3	26.1	1.2	4.4						0.1		0.1				70	13	67	12	1.0	0.9
		W01-U											1.0		1.0									
		W02-L		22.3	17.2	5.1	22.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.2		0.2									
		W03-L		20.8	15.8	5.0	24.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.3		0.2									
		W04-L		19.8	14.9	4.9	24.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						208.7	204.5	180.3	24.2	11.8	0.2	1.96	0.2	1.76	0.2	10.0						
First	R2	W05-L	Bedroom	14.1	12.3	1.9	13.3						0.0		0.0				35	8	32	7	0.9	0.9
		W05-U											0.4		0.4									
		W06-L		33.9	29.2	4.7	13.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.1		1.0									
		W07-L		33.5	29.1	4.4	13.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						145.3	144.4	144.4	0.0	0.0	1.2	2.93	1.0	2.63	0.3	10.3						
First	R3	W08-L	Unknown	16.1	13.2	2.8	17.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.2		0.2									
		W09-L		18.9	15.6	3.3	17.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											0.4		0.3									
		W10-L		21.1	17.7	3.4	16.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						153.0	149.9	114.2	35.7	23.8	0.3	1.00	0.2	0.86	0.1	14.0						
First	R4	W11-L	Unknown	29.7	26.7	3.0	10.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W11-U						153.0	149.4	125.4	24.1	16.1	1.1	1.15	1.0	1.07	0.1	7.5						
First	R5	W12-L	Unknown	20.8	18.2	2.6	12.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											0.2		0.2									
		W13-L		18.5	16.0	2.5	13.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.4		0.3									
		W14-L		15.7	13.2	2.4	15.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						153.0	149.4	132.8	16.6	11.1	0.2	0.93	0.2	0.83	0.1	11.2						
First	R6	W15-L	Bedroom	32.1	29.9	2.2	6.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											1.1		1.0									
		W16-L		32.3	30.1	2.1	6.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						145.3	144.4	144.3	0.0	0.0	1.1	2.38	1.0	2.24	0.1	5.6						
First	R7	W17-L	Bedroom	15.6	14.0	1.5	9.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											0.2		0.2									
		W18-L		17.6	15.7	1.9	10.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U											0.4		0.3									
		W19-L		20.4	18.3	2.1	10.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						125.2	118.3	118.3	0.0	0.0	0.3	1.01	0.3	0.92	0.1	9.0						
First	R8	W20-L	LKD	28.9	28.8	0.1	0.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U											0.3		0.3									
		W21-L		33.9	33.9	0.0	0.0						0.0		0.0				37	9	37	9	1.0	1.0
		W21-U											0.3		0.3									
		W22-L		33.3	33.3	0.0	0.0						0.0		0.0				34	8	34	8	1.0	1.0
		W22-U											0.4		0.4									
		W23-L		31.4	31.4	0.0	0.0						0.0		0.0				28	5	28	5	1.0	1.0
		W23-U											0.4		0.4									
		W24-L		27.7	27.7	0.0	0.0						0.0		0.0				18	1	18	1	1.0	1.0
		W24-U						286.9	283.1	283.1	0.0	0.0	0.2	1.70	0.2	1.70	0.0	0.0						
First	R9	W25-L	Unknown	29.3	28.7	0.6	2.0						0.1		0.1				73	16	71	15	1.0	0.9
		W25-U						270.0	223.3	223.0	0.3	0.2	0.9	1.02	0.9	1.01	0.0	1.3						
Second	R1	W01-L	Bedroom	33.3	32.6	0.8	2.3						0.1		0.1				81	24	81	24	1.0	1.0
		W01-U											1.2		1.2									
		W02-L		35.5	31.2	4.3	12.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.4		0.3									
		W03-L		34.6	30.4	4.2	12.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.5		0.4									
		W04-L		33.5	29.3	4.2	12.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						208.7	206.4	206.4	0.0	0.0	0.4	2.62	0.3	2.47	0.1	5.7						
Second	R2	W05-L	Bedroom	36.3	32.2	4.1	11.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											1.2		1.1									
		W06-L		36.2	32.2	4.0	11.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						145.3	144.4	144.4	0.0	0.0	1.2	2.50	1.1	2.25	0.2	9.9						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Second	R3	W07-L	Unknown	27.9	24.8	3.1	11.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											0.4		0.4									
		W08-L		32.3	29.0	3.3	10.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.7		0.6									
		W09-L		34.1	30.7	3.4	10.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						153.0	150.0	148.7	1.3	0.9	0.4	1.66	0.4	1.52	0.1	8.1						
Second	R4	W10-L	Unknown	35.5	32.4	3.2	8.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						153.0	149.6	149.6	0.0	0.0	1.2	1.28	1.1	1.18	0.1	7.8						
Second	R5	W11-L	Unknown	33.8	30.9	2.9	8.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.4		0.4									
		W12-L		32.0	29.1	2.9	9.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											0.7		0.6									
		W13-L		27.6	24.7	2.9	10.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						153.0	149.7	149.7	0.0	0.0	0.4	1.56	0.3	1.45	0.1	7.2						
Second	R6	W14-L	Bedroom	35.8	32.8	2.9	8.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											1.2		1.1									
		W15-L		35.8	32.9	2.9	8.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U						145.3	144.4	144.4	0.0	0.0	1.2	2.48	1.1	2.31	0.2	7.2						
Second	R7	W16-L	Bedroom	28.6	26.5	2.2	7.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U											0.4		0.4									
		W17-L		31.8	29.4	2.4	7.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											0.7		0.7									
		W18-L		33.5	31.0	2.5	7.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						125.2	118.9	118.9	0.0	0.0	0.5	1.80	0.5	1.69	0.1	6.2						
Second	R8	W19-L	LKD	34.1	34.0	0.1	0.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U											0.4		0.4									
		W20-L		35.9	35.9	0.0	0.0						0.0		0.0				39	9	39	9	1.0	1.0
		W20-U											0.3		0.3									
		W21-L		35.1	35.1	0.0	0.0						0.0		0.0				36	9	36	9	1.0	1.0
		W21-U											0.4		0.4									
		W22-L		33.0	33.0	0.0	0.0						0.0		0.0				30	6	30	6	1.0	1.0
		W22-U											0.4		0.4									
		W23-L		29.2	29.2	0.0	0.0						0.0		0.0				20	2	20	2	1.0	1.0
		W23-U						286.9	285.2	285.2	0.0	0.0	0.2	1.80	0.2	1.80	0.0	0.0						
Second	R9	W24-L	Unknown	34.6	34.2	0.4	1.0						0.1		0.1				81	24	81	24	1.0	1.0
		W24-U						270.0	259.4	259.3	0.1	0.0	1.1	1.17	1.1	1.16	0.0	0.7						
Third	R1	W01-L	Unknown	37.2	34.0	3.2	8.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.4		0.3									
		W02-L		37.3	34.1	3.2	8.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.6		0.6									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W03-L		37.3	34.2	3.2	8.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						178.9	175.5	175.5	0.0	0.0	0.4	1.42	0.4	1.32	0.1	7.0						
Third	R2	W04	Unknown	36.7	33.7	3.0	8.2	153.0	149.3	149.3	0.0	0.0	1.0	1.04	1.0	0.97	0.1	7.4	N/F	N/F	N/F	N/F	N/F	N/F
Third	R3	W05	Unknown	36.7	33.9	2.9	7.8	153.0	149.5	149.5	0.0	0.0	1.0	1.03	1.0	0.96	0.1	7.1	N/F	N/F	N/F	N/F	N/F	N/F
Third	R4	W06	Unknown	36.7	33.8	2.9	7.8	153.0	148.8	148.8	0.0	0.0	1.0	1.03	1.0	0.96	0.1	7.1	N/F	N/F	N/F	N/F	N/F	N/F
Third	R5	W07-L	Unknown	37.5	34.5	3.0	8.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											0.3		0.3									
		W08-L		37.5	34.5	3.0	7.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.6		0.5									
		W09-L		37.4	34.5	2.9	7.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						178.9	175.5	175.5	0.0	0.0	0.4	1.37	0.3	1.27	0.1	6.7						
17-18 Langdon Place																								
Ground	R1	W01-L	Unknown	22.4	22.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						157.5	156.4	156.4	0.0	0.0	1.1	1.09	1.1	1.09	0.0	0.0						
Ground	R2	W02-L	Unknown	23.0	23.0	0.1	0.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						157.5	156.5	156.5	0.0	0.0	1.1	1.11	1.1	1.11	0.0	0.1						
First	R1	W01-L	Unknown	37.0	36.9	0.1	0.2						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						157.5	156.3	156.3	0.0	0.0	1.2	1.33	1.2	1.33	0.0	0.2						
First	R2	W02-L	Unknown	37.0	36.8	0.2	0.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						157.5	156.5	156.5	0.0	0.0	1.2	1.33	1.2	1.32	0.0	0.6						
Tudor Lodge																								
Ground	R1	W01	Living Room	23.7	22.5	1.2	5.1						0.3		0.3				52	18	50	16	1.0	0.9
		W02-L		28.0	26.0	2.0	7.2						0.0		0.0				61	21	59	19	1.0	0.9
		W02-U						189.7	150.7	130.5	20.1	13.4	0.9	1.14	0.8	1.09	0.1	4.8						
Ground	R3	W05-L	Dining Room	32.3	29.2	3.1	9.5						0.0		0.0				71	22	66	17	0.9	0.8
		W05-U											0.9		0.8									
		W06-L		32.2	31.4	0.7	2.2						0.0		0.0				51	12	49	10	1.0	0.8
		W06-U											0.6		0.6									
		W07-L		33.5	33.0	0.5	1.4						0.1		0.1				55	13	53	11	1.0	0.8
		W07-U						200.1	199.5	199.5	0.0	0.0	1.6	3.25	1.6	3.15	0.1	3.1						
First	R1	W01-L	Bedroom	31.9	29.8	2.1	6.7						0.1		0.1				73	25	71	23	1.0	0.9
		W01-U						191.8	138.9	118.0	20.9	15.1	0.8	0.87	0.7	0.82	0.0	5.4						
First	R2	W02-L	Unknown	33.8	30.7	3.0	9.0						0.3		0.3				75	26	70	21	0.9	0.8
		W02-U						37.8	37.3	37.3	0.0	0.0	2.7	2.98	2.5	2.76	0.2	7.5						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R3	W03-L	Unknown	34.3	31.0	3.3	9.7						0.1		0.1				77	27	71	21	0.9	0.8
		W03-U											1.2		1.1									
		W04-L		34.3	33.4	0.9	2.7						0.1		0.1				59	17	57	15	1.0	0.9
		W04-U						103.7	103.1	103.1	0.0	0.0	0.6	2.03	0.6	1.91	0.1	6.2						
The Ship Thames																								
First	R1	W01-L	Unknown	34.2	28.5	5.7	16.7						0.1		0.1				74	25	62	14	0.8	0.6
		W01-U						109.0	107.3	106.5	0.9	0.8	1.3	1.43	1.2	1.23	0.2	13.8						
First	R2	W02-L	Unknown	33.1	27.2	5.9	17.7						0.1		0.1				67	20	60	13	0.9	0.7
		W02-U											1.0		0.9									
		W03-L		17.3	14.5	2.8	15.9						0.0		0.0				30	12	22	4	0.7	0.3
		W03-U						155.9	151.1	126.3	24.8	16.4	0.7	1.81	0.6	1.58	0.2	13.0						
First	R3	W04-L	Unknown	18.9	16.7	2.2	11.6						0.0		0.0				31	11	25	5	0.8	0.5
		W04-U						155.9	78.6	76.2	2.5	3.1	1.4	1.39	1.3	1.29	0.1	7.4						
First	R4	W05-L	Unknown	21.4	19.6	1.7	8.0						0.0		0.0				33	11	27	6	0.8	0.5
		W05-U											1.1		1.1									
		W06-L		24.6	23.3	1.3	5.2						0.0		0.0				38	10	33	6	0.9	0.6
		W06-U						231.8	226.2	207.5	18.7	8.3	1.2	2.39	1.2	2.29	0.1	4.2						
First	R5	W07	Unknown	28.7	26.7	1.9	6.7						1.0		1.0				61	11	59	9	1.0	0.8
		W08		18.5	17.6	0.9	4.8	265.4	261.1	261.1	0.0	0.0	0.8	1.76	0.7	1.68	0.1	4.2	35	2	34	1	1.0	0.5
Second	R1	W01	Unknown	23.9	21.9	2.0	8.3	164.7	32.8	31.5	1.2	3.7	0.5	0.52	0.5	0.49	0.0	5.7	37	12	31	6	0.8	0.5
1-2 Thames Bank Cottage																								
Ground	R1	W01	Unknown	33.5	32.6	0.9	2.8						0.9		0.9				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		26.5	24.0	2.5	9.5						0.1		0.1				59	18	53	12	0.9	0.7
		W02-U						160.2	158.8	158.7	0.0	0.0	1.6	2.63	1.5	2.48	0.1	5.5						
Ground	R2	W03	Unknown	23.5	22.1	1.4	6.0	110.6	97.5	73.0	24.6	25.2	0.6	0.56	0.5	0.54	0.0	4.6	56	16	52	12	0.9	0.8
Ground	R3	W04-L	Unknown	17.6	17.3	0.3	1.5						0.0		0.0				40		40		1.0	1.0
		W04-U						147.5	143.8	139.9	3.9	2.7	0.9	0.90	0.9	0.89	0.0	1.1						
First	R1	W01	Unknown	36.1	34.9	1.2	3.3						0.6		0.6				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		31.9	28.6	3.4	10.5						0.0		0.0				70	22	67	19	1.0	0.9
		W02-U						194.1	189.8	189.7	0.0	0.0	1.0	1.56	0.9	1.46	0.1	6.3						
First	R2	W03-L	Unknown	33.1	29.5	3.6	10.9						0.0		0.0				74	23	67	16	0.9	0.7
		W03-U						110.6	83.7	59.4	24.2	29.0	0.7	0.75	0.6	0.68	0.1	9.1						
First	R3	W04-L	Unknown	33.9	29.9	4.0	11.9						0.0		0.0				75	23	66	15	0.9	0.7

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W04-U						147.5	143.8	143.2	0.6	0.4	1.2	1.27	1.1	1.14	0.1	9.8						
Second	R1	W01-L	Unknown	38.1	36.7	1.3	3.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U						124.7	107.5	104.2	3.3	3.0	0.5	0.53	0.5	0.51	0.0	3.2						
Second	R2	W02-L	Unknown	35.5	31.3	4.2	11.8						0.0		0.0				79	25	73	19	0.9	0.8
		W02-U						110.6	106.4	106.4	0.0	0.0	1.2	1.22	1.1	1.10	0.1	10.0						
Second	R3	W03-L	Unknown	34.2	30.3	3.9	11.3						0.0		0.0				74	24	69	19	0.9	0.8
		W03-U						90.9	82.7	74.2	8.5	10.3	0.8	0.84	0.7	0.76	0.1	9.2						
Asplin Cottage																								
Ground	R1	W01-L	Unknown	28.9	27.0	2.0	6.8						0.0		0.0				54	15	47	8	0.9	0.5
		W01-U						115.6	101.9	96.8	5.1	5.0	0.9	0.88	0.8	0.83	0.1	5.7						
Ground	R2	W02	Unknown	32.0	27.6	4.4	13.6	85.8	76.2	75.8	0.4	0.5	1.1	1.11	1.0	0.98	0.1	11.0	60	18	53	11	0.9	0.6
First	R1	W01	Unknown	34.0	29.7	4.4	12.8	85.8	82.8	82.6	0.2	0.2	1.1	1.11	1.0	1.00	0.1	10.5	63	20	57	14	0.9	0.7
First	R2	W02-L	Unknown	37.1	34.5	2.6	7.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						145.9	142.5	122.1	20.4	14.3	0.6	0.62	0.5	0.58	0.0	6.4						
First	R3	W03	Unknown	36.5	33.5	3.0	8.1	114.8	111.6	111.6	0.0	0.0	0.9	0.86	0.8	0.80	0.1	7.0	N/F	N/F	N/F	N/F	N/F	N/F
Aynescombe Cottage																								
Ground	R2	W02	Living Room	30.4	26.1	4.2	14.0						0.8		0.7				54	15	43	4	0.8	0.3
		W06		36.4	32.2	4.2	11.6	214.1	213.6	212.1	1.5	0.7	1.5	2.29	1.4	2.06	0.2	10.3	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W04	Study	28.3	26.6	1.8	6.3	63.9	59.4	59.4	0.0	0.0	1.0	0.96	0.9	0.92	0.0	4.5	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R5	W05	KD	36.5	32.6	3.9	10.7	155.5	153.1	153.0	0.1	0.1	1.8	1.80	1.6	1.63	0.2	9.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W03-L	Bedroom	30.1	25.8	4.2	14.1						0.0		0.0				56	17	48	9	0.9	0.5
		W03-U											0.5		0.4									
		W04		25.1	14.2	10.9	43.5						0.1		0.0				65	25	43	5	0.7	0.2
		W05-L		25.5	18.0	7.5	29.3						0.1		0.1				52	13	38	2	0.7	0.2
		W05-U											0.7		0.5									
		W06-L		37.4	32.9	4.5	11.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											0.2		0.2									
		W07-L		37.4	33.0	4.3	11.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											0.4		0.4									
		W08-L		37.4	33.2	4.2	11.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.2		0.2									
		W09-L		28.8	28.8	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						322.3	303.5	292.3	11.2	3.7	0.7	3.01	0.7	2.68	0.3	10.8						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R4	W10	Bedroom	36.1	32.7	3.4	9.4	58.6	56.6	56.6	0.0	0.0	1.1	1.14	1.0	1.05	0.1	8.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R5	W11	Bedroom	36.1	32.8	3.2	8.9	58.8	56.8	56.8	0.0	0.0	1.1	1.13	1.0	1.05	0.1	7.7	N/F	N/F	N/F	N/F	N/F	N/F
Thames Bank House																								
Ground	R1	W01-L	Living Room	33.6	30.0	3.6	10.8						0.0		0.0				78	25	71	18	0.9	0.7
		W01-U											0.3		0.3									
		W02-L		33.4	29.8	3.6	10.8						0.0		0.0				75	24	68	17	0.9	0.7
		W02-U						418.7	347.3	229.4	117.9	34.0	0.4	0.65	0.3	0.59	0.1	8.6						
Ground	R2	W03-L	KD	33.5	29.9	3.6	10.6						0.0		0.0				77	26	71	20	0.9	0.8
		W03-U											0.9		0.9									
		W04-L		32.6	29.3	3.3	10.0						0.0		0.0				74	24	68	18	0.9	0.8
		W04-U											0.6		0.5									
		W05-L		31.9	28.9	3.0	9.5						0.0		0.0				72	24	67	19	0.9	0.8
		W05-U						271.4	269.0	255.1	13.9	5.2	0.9	2.47	0.8	2.27	0.2	8.1						
Ground	R3	W06-L	Dining Room	20.8	20.5	0.3	1.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											0.9		0.9									
		W07-L		20.6	20.4	0.2	0.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						199.8	195.5	195.4	0.0	0.0	0.9	1.87	0.9	1.86	0.0	0.6						
First	R3	W04-L	Bedroom	35.4	31.4	4.0	11.2						0.0		0.0				83	29	76	22	0.9	0.8
		W04-U											1.2		1.1									
		W05-L		35.3	31.3	4.0	11.2						0.0		0.0				82	29	75	22	0.9	0.8
		W05-U											1.2		1.1									
		W06-L		34.9	31.0	3.9	11.1						0.0		0.0				79	28	73	22	0.9	0.8
		W06-U						178.1	176.7	176.7	0.0	0.0	1.2	3.85	1.1	3.48	0.4	9.5						
First	R4	W07-L	Bedroom	29.0	28.5	0.4	1.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											1.0		0.9									
		W08-L		27.9	27.5	0.3	1.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U						220.7	215.2	215.1	0.0	0.0	0.9	1.93	0.9	1.91	0.0	1.0						
Second	R2	W02-L	Unknown	37.0	35.6	1.4	3.8						0.1		0.1				59	18	59	18	1.0	1.0
		W02-U						36.9	36.1	36.1	0.0	0.0	2.3	2.39	2.3	2.31	0.1	3.5						
Second	R3	W03-L	Bedroom	36.5	32.9	3.5	9.7						0.0		0.0				85	29	80	24	0.9	0.8
		W03-U											1.3		1.2									
		W04-L		36.5	32.9	3.6	9.7						0.0		0.0				85	29	80	24	0.9	0.8
		W04-U											1.3		1.2									
		W05-L		36.5	32.9	3.6	9.7						0.0		0.0				85	29	80	24	0.9	0.8
		W05-U						178.1	176.7	176.7	0.0	0.0	1.3	3.96	1.2	3.62	0.3	8.6						
Second	R4	W06-L	Bedroom	36.8	35.5	1.3	3.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.4		1.4									
		W07-L		36.1	34.8	1.2	3.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W07-U						164.5	159.1	159.1	0.0	0.0	1.4	2.85	1.3	2.76	0.1	3.2						
Second	R5	W08	Bedroom	31.5	29.6	1.9	5.9						0.2		0.2				69	17	67	15	1.0	0.9
		W09		36.3	35.2	1.1	3.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10		33.9	32.9	1.1	3.1						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W11		1.1	1.1	0.0	0.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W12		39.6	39.6	0.0	0.0						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W13		39.6	39.6	0.0	0.0						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W14		39.6	39.6	0.0	0.0						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W15		31.0	30.6	0.4	1.4						0.2		0.2				38	8	38	8	1.0	1.0
		W16		24.0	23.2	0.8	3.3						0.2		0.2				47	13	47	13	1.0	1.0
		W17		31.5	31.2	0.3	0.9	566.9	566.9	566.9	0.0	0.0	0.2	2.18	0.2	2.15	0.0	1.4	41	4	41	4	1.0	1.0
Old Stable																								
Ground	R1	W01	Unknown	14.5	13.5	1.0	6.7	110.8	39.3	38.7	0.6	1.4	0.4	0.40	0.4	0.38	0.0	4.6	30	11	27	8	0.9	0.7
Ground	R2	W02	Unknown	13.6	12.4	1.2	9.0	110.8	105.1	105.1	0.0	0.0	0.9	0.88	0.8	0.83	0.1	5.7	38	18	34	14	0.9	0.8
Ground	R3	W03-L	Unknown	28.0	26.8	1.2	4.4						0.2		0.2				51	16	49	14	1.0	0.9
		W03-U											2.1		2.1									
		W04		60.9	60.9	0.0	0.0						1.6		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W05		80.6	77.7	2.8	3.5	166.0	166.0	166.0	0.0	0.0	2.0	5.98	2.0	5.86	0.1	2.1	91	26	82	17	0.9	0.7
Ground	R4	W06-L	Unknown	34.4	26.7	7.7	22.5						0.1		0.1				82	26	68	16	0.8	0.6
		W06-U											1.0		0.9									
		W07-L		34.5	26.1	8.4	24.4						0.1		0.1				82	26	69	18	0.8	0.7
		W07-U											1.0		0.8									
		W08-L		36.0	30.7	5.3	14.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.9		0.8									
		W09-L		35.7	31.1	4.5	12.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											0.9		0.8									
		W10-L		35.1	31.2	3.9	11.2						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U											0.8		0.8									
		W11		92.9	91.2	1.7	1.9						0.5		0.5				95	26	85	18	0.9	0.7
		W12		97.3	95.3	2.0	2.0						0.6		0.6				95	26	84	17	0.9	0.7
		W13		95.6	94.6	1.0	1.0						0.5		0.5				83	14	79	13	1.0	0.9
		W14		95.6	94.4	1.1	1.2						0.5		0.5				82	15	78	13	1.0	0.9
		W15		97.3	95.2	2.1	2.2						0.6		0.6				92	25	85	19	0.9	0.8
		W16		93.7	91.9	1.8	1.9	461.3	461.3	461.3	0.0	0.0	0.5	8.22	0.5	7.49	0.7	8.9	91	25	84	19	0.9	0.8
Ground	R5	W17	Unknown	27.6	23.2	4.4	16.0	100.2	96.5	96.3	0.2	0.2	1.0	1.01	0.9	0.89	0.1	11.6	54	14	47	7	0.9	0.5
First	R1	W01	Unknown	15.6	14.9	0.6	4.1	110.8	39.7	39.5	0.2	0.6	0.6	0.57	0.6	0.56	0.0	2.9	28	15	26	13	0.9	0.9
First	R2	W02-L	Unknown	25.0	23.6	1.4	5.6						0.0		0.0				48	19	44	15	0.9	0.8
		W02-U											0.6		0.5									
		W03-L		26.2	24.8	1.4	5.3						0.0		0.0				50	19	46	15	0.9	0.8

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W03-U						110.8	105.4	105.4	0.0	0.0	0.6	1.21	0.6	1.17	0.0	4.0						
Second	R1	W01-L	Unknown	71.2	70.1	1.1	1.6						0.1		0.1				70	22	68	20	1.0	0.9
		W01-U											1.3		1.2									
		W02-L		77.2	73.7	3.5	4.5						0.2		0.2				93	29	86	22	0.9	0.8
		W02-U											1.1		1.0									
		W03-L		36.3	31.9	4.4	12.1						0.1		0.1				85	29	77	21	0.9	0.7
		W03-U						331.3	323.3	292.4	30.9	9.6	0.3	2.91	0.2	2.82	0.1	3.0						
Leyden House																								
Ground	R1	W01-L	Unknown	18.5	18.0	0.6	3.0						0.0		0.0				47	20	44	17	0.9	0.9
		W01-U						133.2	102.1	102.0	0.0	0.0	0.9	0.89	0.8	0.87	0.0	1.4						
Ground	R2	W02-L	Unknown	26.4	25.5	0.9	3.4						0.0		0.0				56	20	52	16	0.9	0.8
		W02-U											0.5		0.5									
		W03-L		32.4	29.3	3.1	9.6						0.0		0.0				75	25	69	19	0.9	0.8
		W03-U											0.5		0.5									
		W04-L		34.5	29.1	5.4	15.7						0.0		0.0				72	27	64	19	0.9	0.7
		W04-U											0.6		0.5									
		W05-L		28.6	25.9	2.8	9.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U						357.0	356.1	326.1	30.0	8.4	0.5	2.22	0.5	2.05	0.2	7.5						
First	R1	W01-L	Unknown	11.8	11.6	0.3	2.1						0.0		0.0				37	14	36	13	1.0	0.9
		W01-U											0.2		0.2									
		W02-L		34.0	30.9	3.1	9.1						0.0		0.0				68	24	65	21	1.0	0.9
		W02-U											1.3		1.2									
		W03-L		15.7	15.0	0.6	3.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						125.3	123.3	111.6	11.7	9.5	0.2	1.64	0.2	1.54	0.1	6.1						
First	R2	W04-L	Unknown	27.7	25.5	2.3	8.1						0.0		0.0				52	18	50	16	1.0	0.9
		W04-U						104.7	103.4	103.4	0.0	0.0	1.0	1.01	0.9	0.95	0.1	5.7						
First	R3	W05-L	Unknown	26.6	25.8	0.8	2.9						0.0		0.0				57	21	56	20	1.0	1.0
		W05-U						133.2	129.0	129.0	0.0	0.0	1.0	1.05	1.0	1.03	0.0	1.8						
First	R4	W06-L	Unknown	32.0	31.0	1.0	3.1						0.0		0.0				63	22	61	20	1.0	0.9
		W06-U											0.6		0.5									
		W07-L		34.9	32.0	2.9	8.2						0.0		0.0				80	26	76	22	1.0	0.8
		W07-U											0.6		0.6									
		W08-L		35.8	31.2	4.6	12.8						0.0		0.0				74	27	68	21	0.9	0.8
		W08-U											0.6		0.6									
		W09-L		31.9	29.6	2.4	7.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						357.0	357.0	351.6	5.3	1.5	0.6	2.48	0.5	2.32	0.2	6.5						
Second	R1	W01	Unknown	65.9	65.0	0.9	1.3	41.9	27.2	27.2	0.0	0.0	0.9	0.91	0.9	0.91	0.0	0.9	79	26	78	25	1.0	1.0
Second	R3	W02	Unknown	36.3	33.9	2.5	6.8						0.9		0.8				73	27	70	24	1.0	0.9

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W03		34.8	32.6	2.2	6.3	193.4	191.5	191.5	0.0	0.0	0.9	1.74	0.8	1.64	0.1	5.7	70	26	68	24	1.0	0.9
Second	R4	W04	Unknown	35.0	33.7	1.3	3.6						1.1		1.1				65	23	64	22	1.0	1.0
		W05		37.1	33.9	3.2	8.5						1.2		1.1				77	27	74	24	1.0	0.9
		W06		36.6	36.2	0.4	1.0	260.3	260.3	260.3	0.0	0.0	0.7	2.98	0.7	2.85	0.1	4.3	N/F	N/F	N/F	N/F	N/F	N/F
Jolly Gardeners																								
First	R1	W01	Kitchen	28.9	24.2	4.7	16.3						0.9		0.8				55	18	51	18	0.9	1.0
		W12		31.2	31.2	0.1	0.2						0.5		0.5				72	28	72	28	1.0	1.0
		W13		31.3	31.3	0.0	0.2	250.9	189.0	156.9	32.1	17.0	0.9	2.30	0.9	2.20	0.1	4.6	73	28	73	28	1.0	1.0
First	R4	W06	Bedroom	29.9	14.5	15.4	51.5						0.7		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W07		29.7	23.0	6.7	22.5	159.2	82.0	33.5	48.5	59.1	1.2	1.90	1.0	1.44	0.5	24.3	N/F	N/F	N/F	N/F	N/F	N/F
First	R5	W08	Living Room	31.5	26.4	5.1	16.1						0.5		0.5				N/F	N/F	N/F	N/F	N/F	N/F
		W09		32.6	30.7	2.0	6.0						0.6		0.5				53	21	52	21	1.0	1.0
		W10		30.8	30.8	0.1	0.2						0.5		0.5				68	27	68	27	1.0	1.0
		W11		31.6	31.5	0.1	0.2	247.8	247.2	247.2	0.0	0.0	1.0	2.64	1.0	2.55	0.1	3.3	72	28	72	28	1.0	1.0
Second	R4	W06	Bedroom	31.9	18.4	13.5	42.3						0.6		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W07		35.7	30.1	5.6	15.7	175.0	164.3	136.8	27.5	16.8	0.9	1.53	0.8	1.22	0.3	20.2	N/F	N/F	N/F	N/F	N/F	N/F

Detailed Results of the Daylight and Sunlight Analysis with balconies removed (Butler House, Rann House and Churchill Court only)

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Butler House																								
Ground	R1	W01	Bedroom	32.0	31.1	0.9	2.7						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		22.4	18.7	3.7	16.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.4		0.3									
		W03-L		20.2	17.3	2.9	14.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						144.7	129.8	127.4	2.5	1.9	0.5	1.3	0.4	1.2	0.1	7.4						
Ground	R2	W04-L	LKD	26.8	25.7	1.1	4.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.3		0.3									
		W05-L		29.5	28.4	1.1	3.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.3		0.3									
		W06-L		32.2	31.0	1.2	3.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.3		1.2									
		W07-L		36.1	26.7	9.4	26.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						304.1	303.2	298.5	4.7	1.6	2.2	4.2	1.7	3.7	0.5	12.6						
Ground	R4	W09-L	LKD	35.4	25.0	10.4	29.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											1.8		1.4									
		W10-L		26.9	23.7	3.2	11.7						0.0		0.0				35	6	34	6	1.0	1.0
		W10-U											0.9		0.9									
		W11-L		25.3	22.3	2.9	11.6						0.0		0.0				27	4	26	4	1.0	1.0
		W11-U											0.2		0.2									
		W12-L		24.1	21.3	2.8	11.8						0.0		0.0				20	1	19	1	1.0	1.0
		W12-U											0.2		0.2									
		W13		20.0	17.4	2.6	13.1	382.6	379.2	363.8	15.5	4.1	0.4	3.6	0.3	3.1	0.6	15.8	10	0	9	0	0.9	0.0
Ground	R5	W14-L	Bedroom	18.2	12.7	5.5	30.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											0.4		0.3									
		W15-L		19.9	13.8	6.1	30.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.4		0.3									
		W16		23.8	21.7	2.1	9.0	135.1	110.7	89.8	20.9	18.9	0.4	1.2	0.3	1.0	0.2	15.9	33	11	32	11	1.0	1.0
Ground	R6	W17	Bedroom	12.4	12.4	0.0	0.0						0.2		0.2				20	2	20	2	1.0	1.0
		W18		12.2	11.8	0.3	2.6	103.9	30.2	30.2	0.0	0.0	0.2	0.4	0.2	0.4	0.0	0.6	1	0	1	0	1.0	0.0
First	R1	W01	Bedroom	34.8	34.1	0.7	2.0						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		20.6	18.4	2.2	10.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						139.4	136.3	136.3	0.0	0.0	0.6	1.1	0.6	1.0	0.0	4.6						
First	R2	W03-L	Bedroom	29.4	28.6	0.8	2.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						105.1	96.1	96.1	0.0	0.0	1.0	1.0	1.0	1.0	0.0	1.9						
First	R3	W04-L	LKD	33.6	32.7	0.9	2.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.4		0.3									
		W05-L		34.1	33.1	1.0	2.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.4		0.3									
		W06-L		34.6	33.5	1.1	3.0						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W06-U											1.4		1.4									
		W07-L		37.5	28.4	9.1	24.3						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											2.2		1.7									
		W08		38.1	28.7	9.4	24.7	290.5	290.2	290.0	0.2	0.1	0.3	5.1	0.3	4.4	0.6	12.4	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W09	LKD	38.1	28.1	9.9	26.1						0.3		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10-L		37.2	26.8	10.4	28.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U											2.2		1.7									
		W11-L		29.2	26.0	3.2	11.0						0.1		0.1				39	8	38	8	1.0	1.0
		W11-U											1.2		1.1									
		W12-L		28.4	25.4	3.0	10.5						0.0		0.0				35	7	34	7	1.0	1.0
		W12-U											0.3		0.3									
		W13-L		27.7	24.8	2.9	10.4						0.0		0.0				28	5	27	5	1.0	1.0
		W13-U						290.5	284.8	284.7	0.0	0.0	0.3	4.7	0.3	3.9	0.8	16.8						
First	R5	W14-L	Bedroom	22.6	19.9	2.6	11.7						0.0		0.0				13	0	12	0	0.9	0.0
		W14-U						105.2	68.7	68.7	0.0	0.0	0.9	0.9	0.8	0.8	0.1	6.8						
First	R6	W15-L	Bedroom	20.0	14.4	5.6	27.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.7		0.5									
		W16		27.6	25.5	2.2	7.9	125.2	100.0	94.1	5.9	5.9	0.4	1.0	0.3	0.9	0.1	13.5	35	11	34	11	1.0	1.0
First	R7	W17	LKD	20.7	20.5	0.2	0.9						0.1		0.1				32	12	32	12	1.0	1.0
		W18		21.1	19.6	1.4	6.8						0.1		0.1				15	3	15	3	1.0	1.0
		W19		27.9	26.5	1.3	4.8	302.0	250.2	216.2	33.9	13.6	0.2	0.5	0.2	0.5	0.0	2.0	39	15	39	15	1.0	1.0
Second	R1	W01	Bedroom	36.5	36.0	0.5	1.5						0.4		0.4				N/F	N/F	N/F	N/F	N/F	N/F
		W02-L		22.0	20.2	1.8	8.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						139.4	138.9	138.9	0.0	0.0	0.7	1.1	0.6	1.1	0.0	3.6						
Second	R2	W03-L	Bedroom	31.3	30.7	0.6	2.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						105.1	101.0	101.0	0.0	0.0	1.1	1.1	1.1	1.1	0.0	1.4						
Second	R3	W04-L	LKD	35.5	34.8	0.7	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U											0.4		0.4									
		W05-L		35.9	35.1	0.8	2.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.4		0.4									
		W06-L		36.3	35.5	0.8	2.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.5		1.4									
		W07-L		38.4	30.3	8.1	21.1						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											2.2		1.8									
		W08		38.9	30.7	8.2	21.2	290.5	290.2	290.0	0.2	0.1	0.3	5.2	0.3	4.6	0.6	10.8	N/F	N/F	N/F	N/F	N/F	N/F
Second	R4	W09	LKD	38.9	30.2	8.8	22.5						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W10-L		38.4	28.9	9.5	24.7						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U											2.2		1.8									
		W11-L		31.1	28.2	2.9	9.4						0.1		0.1				39	8	38	8	1.0	1.0
		W11-U											1.2		1.1									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W12-L		30.5	27.8	2.7	8.9						0.0		0.0				39	8	38	8	1.0	1.0
		W12-U											0.3		0.3									
		W13-L		29.9	27.3	2.6	8.7						0.0		0.0				35	6	34	6	1.0	1.0
		W13-U						290.5	284.8	284.8	0.0	0.0	0.3	4.8	0.3	4.1	0.7	15.0						
Second	R5	W14-L	Bedroom	24.8	22.4	2.4	9.5						0.0		0.0				19	1	18	1	0.9	1.0
		W14-U						105.2	77.1	77.1	0.0	0.0	0.9	0.9	0.9	0.9	0.1	5.7						
Second	R6	W15-L	Bedroom	21.5	16.4	5.1	23.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											0.7		0.6									
		W16		30.1	28.2	2.0	6.5	125.2	100.5	100.5	0.0	0.0	0.4	1.1	0.4	0.9	0.1	11.5	42	13	42	13	1.0	1.0
Second	R7	W17	LKD	23.4	23.2	0.2	0.8						0.1		0.1				39	12	39	12	1.0	1.0
		W18		23.5	22.2	1.3	5.3						0.1		0.1				17	3	17	3	1.0	1.0
		W19		30.2	29.0	1.2	3.9						0.2		0.2				40	15	40	15	1.0	1.0
		W20-L		38.8	38.8	0.0	0.0						0.1		0.1				83	28	83	28	1.0	1.0
		W20-U											0.7		0.7									
		W21-L		38.9	38.9	0.0	0.0						0.1		0.1				83	28	83	28	1.0	1.0
		W21-U											0.6		0.6									
		W22-L		38.9	38.9	0.0	0.0						0.0		0.0				83	28	83	28	1.0	1.0
		W22-U											0.5		0.5									
		W23-L		39.0	39.0	0.0	0.0						0.1		0.1				83	28	83	28	1.0	1.0
		W23-U						302.0	301.2	301.2	0.0	0.0	0.7	3.2	0.7	3.2	0.0	0.3						
Third	R1	W01-L	Living Room	29.1	28.6	0.6	1.9						0.3		0.3				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											2.7		2.7									
		W02-L		21.6	19.8	1.8	8.2						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U						251.5	251.5	251.5	0.0	0.0	2.9	6.0	2.3	5.4	0.6	10.4						
Third	R2	W03-L	Living Room	22.2	16.6	5.6	25.3						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											2.8		2.1									
		W04-L		24.2	22.1	2.1	8.7						0.2		0.2				32	9	31	9	1.0	1.0
		W04-U						251.5	251.5	251.5	0.0	0.0	2.3	5.5	2.2	4.7	0.8	14.8						
Rann House																								
Ground	R3	W03	Bedroom	36.5	28.6	7.8	21.4	129.1	128.4	115.2	13.2	10.3	2.3	2.3	1.9	1.9	0.4	18.2	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R4	W04	Living Room	24.1	20.1	4.0	16.5						0.3		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		23.7	19.6	4.1	17.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.0		0.0									
		W06-L		27.6	21.5	6.1	22.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						175.8	173.9	163.8	10.0	5.8	1.3	1.5	1.1	1.3	0.2	14.8						
Ground	R5	W07	Living Room	33.7	28.0	5.7	16.8						1.8		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W08		12.4	12.4	0.0	0.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		12.1	12.1	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						157.9	156.6	146.1	10.4	6.7	0.0	2.0	0.0	1.8	0.2	12.1						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R6	W10-L	Bedroom	27.5	22.8	4.7	17.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						107.3	104.2	104.2	0.0	0.0	1.9	1.9	1.6	1.7	0.2	12.1						
Ground	R8	W22-L	Bedroom	27.0	23.6	3.4	12.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W22-U						107.3	104.5	100.6	3.9	3.7	1.8	1.9	1.7	1.7	0.2	8.7						
Ground	R9	W23	Living Room	13.8	10.6	3.2	23.0						0.2		0.2				3	0	1	0	0.3	0.0
		W24-L		13.6	10.2	3.4	24.7						0.0		0.0				2	0	0	0	0.0	0.0
		W24-U											0.0		0.0									
		W25		35.0	31.0	4.0	11.4	157.9	151.9	151.5	0.4	0.3	1.9	2.1	1.7	1.9	0.2	10.1	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R10	W26	Living Room	34.6	31.1	3.5	10.1						1.9		1.7				N/F	N/F	N/F	N/F	N/F	N/F
		W27		12.7	12.7	0.0	0.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W28-L		12.4	12.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W28-U						157.9	148.1	148.1	0.0	0.0	0.0	2.0	0.0	1.9	0.2	7.8						
Ground	R11	W29-L	Bedroom	26.1	23.6	2.5	9.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W29-U						107.3	104.0	104.0	0.0	0.0	1.8	1.8	1.7	1.7	0.1	6.6						
Ground	R13	W41-L	Bedroom	25.4	23.8	1.6	6.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W41-U						107.3	104.4	104.4	0.0	0.0	1.8	1.8	1.7	1.7	0.1	4.1						
Ground	R14	W42	Living Room	13.5	11.1	2.4	17.4						0.2		0.2				3	0	2	0	0.7	0.0
		W43-L		13.2	10.7	2.5	19.0						0.0		0.0				2	0	0	0	0.0	0.0
		W43-U											0.0		0.0									
		W44		31.0	28.8	2.1	6.9	157.9	141.9	140.9	0.9	0.7	1.7	1.9	1.6	1.8	0.1	6.1	N/F	N/F	N/F	N/F	N/F	N/F
Ground	R15	W45-L	Living Room	24.2	23.5	0.7	3.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W45-U											1.1		1.1									
		W46		21.7	20.3	1.5	6.7						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W47-L		21.3	19.8	1.5	7.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W47-U						175.8	140.2	137.8	2.4	1.7	0.0	1.4	0.0	1.4	0.0	2.0						
Ground	R16	W48	Bedroom	31.8	30.3	1.5	4.7	129.1	127.8	127.8	0.0	0.0	2.1	2.1	2.0	2.0	0.1	3.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R3	W03	Bedroom	37.5	30.4	7.1	18.9	129.1	128.4	126.4	2.0	1.6	2.4	2.4	2.0	2.0	0.4	16.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R4	W04	Living Room	25.1	21.5	3.6	14.3						0.3		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		24.8	21.0	3.8	15.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.0		0.0									
		W06		28.4	22.9	5.5	19.3	175.8	173.6	166.7	6.9	4.0	1.3	1.6	1.2	1.4	0.2	13.1	N/F	N/F	N/F	N/F	N/F	N/F
First	R5	W07	Living Room	34.6	29.5	5.1	14.7						1.9		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W08		13.2	13.2	0.0	0.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		12.9	12.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						157.9	156.6	150.9	5.7	3.6	0.0	2.0	0.0	1.8	0.2	10.8						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
First	R6	W10	Bedroom	28.4	24.1	4.2	14.9	107.3	104.2	104.2	0.0	0.0	2.0	2.0	1.8	1.8	0.2	10.7	N/F	N/F	N/F	N/F	N/F	N/F
First	R8	W12	Bedroom	28.1	25.0	3.1	11.0	107.3	104.5	103.9	0.6	0.5	2.0	2.0	1.8	1.8	0.2	7.8	N/F	N/F	N/F	N/F	N/F	N/F
First	R9	W13	Living Room	14.5	11.5	3.0	20.7						0.2		0.2				3	0	2	0	0.7	0.0
		W14-L		14.2	11.1	3.1	21.8						0.0		0.0				3	0	2	0	0.7	0.0
		W14-U											0.0		0.0									
		W15		36.2	32.5	3.6	10.0	157.9	156.7	156.4	0.3	0.2	1.9	2.1	1.8	1.9	0.2	9.2	N/F	N/F	N/F	N/F	N/F	N/F
First	R10	W16	Living Room	35.8	32.7	3.2	8.8						1.9		1.8				N/F	N/F	N/F	N/F	N/F	N/F
		W17		13.6	13.6	0.0	0.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W18-L		13.3	13.3	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						157.9	156.8	156.8	0.0	0.0	0.0	2.1	0.0	2.0	0.2	7.1						
First	R11	W19	Bedroom	27.3	25.0	2.3	8.4	107.3	104.3	104.3	0.0	0.0	1.9	1.9	1.8	1.8	0.1	5.9	N/F	N/F	N/F	N/F	N/F	N/F
First	R13	W21	Bedroom	26.8	25.3	1.5	5.6	107.3	104.6	104.6	0.0	0.0	1.9	1.9	1.8	1.8	0.1	3.6	N/F	N/F	N/F	N/F	N/F	N/F
First	R14	W22	Living Room	14.2	11.9	2.2	15.7						0.2		0.2				3	0	2	0	0.7	0.0
		W23-L		13.9	11.6	2.3	16.6						0.0		0.0				3	0	2	0	0.7	0.0
		W23-U											0.0		0.0									
		W24		32.4	30.5	2.0	6.0	157.9	156.7	156.4	0.2	0.1	1.8	2.0	1.7	1.8	0.1	5.5	N/F	N/F	N/F	N/F	N/F	N/F
First	R15	W25	Living Room	25.7	25.0	0.7	2.7						1.2		1.2				N/F	N/F	N/F	N/F	N/F	N/F
		W26		22.8	21.4	1.4	6.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W27-L		22.3	20.9	1.4	6.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W27-U						175.8	163.2	163.0	0.2	0.1	0.0	1.5	0.0	1.5	0.0	1.9						
First	R16	W28	Bedroom	33.7	32.3	1.4	4.1	129.1	128.2	128.2	0.0	0.0	2.2	2.2	2.1	2.1	0.1	3.5	N/F	N/F	N/F	N/F	N/F	N/F
Second	R3	W03	Bedroom	38.0	32.0	6.0	15.7	129.1	128.4	128.4	0.0	0.0	2.4	2.4	2.1	2.1	0.3	14.3	N/F	N/F	N/F	N/F	N/F	N/F
Second	R4	W04	Living Room	25.4	22.5	2.9	11.3						0.3		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		25.2	22.1	3.1	12.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.0		0.0									
		W06		28.9	24.2	4.7	16.1	175.8	173.8	171.4	2.4	1.4	1.4	1.6	1.2	1.5	0.2	11.0	N/F	N/F	N/F	N/F	N/F	N/F
Second	R5	W07	Living Room	35.2	30.9	4.3	12.3						1.9		1.7				N/F	N/F	N/F	N/F	N/F	N/F
		W08		14.5	14.5	0.0	0.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		13.9	13.9	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						157.9	156.6	155.4	1.2	0.8	0.0	2.1	0.0	1.9	0.2	9.2						
Second	R6	W10	Bedroom	29.2	25.6	3.6	12.3	107.3	104.3	104.3	0.0	0.0	2.0	2.0	1.8	1.8	0.2	9.0	N/F	N/F	N/F	N/F	N/F	N/F
Second	R8	W12	Bedroom	29.0	26.4	2.6	9.1	107.3	104.5	104.5	0.0	0.0	2.0	2.0	1.9	1.9	0.1	6.5	N/F	N/F	N/F	N/F	N/F	N/F
Second	R9	W13	Living Room	15.4	12.8	2.6	16.9						0.2		0.2				3	0	2	0	0.7	0.0
		W14-L		14.9	12.2	2.8	18.5						0.0		0.0				3	0	2	0	0.7	0.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W14-U											0.0		0.0									
		W15		37.0	33.9	3.1	8.4	157.9	156.7	156.7	0.1	0.0	2.0	2.2	1.8	2.0	0.2	7.9	N/F	N/F	N/F	N/F	N/F	N/F
Second	R10	W16	Living Room	36.7	34.0	2.7	7.4						2.0		1.8				N/F	N/F	N/F	N/F	N/F	N/F
		W17		14.8	14.8	0.0	0.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W18-L		14.2	14.2	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						157.9	156.8	156.8	0.0	0.0	0.0	2.2	0.0	2.0	0.1	6.2						
Second	R11	W19	Bedroom	28.5	26.5	2.0	6.9	107.3	104.3	104.3	0.0	0.0	2.0	2.0	1.9	1.9	0.1	5.0	N/F	N/F	N/F	N/F	N/F	N/F
Second	R13	W21	Bedroom	28.1	26.9	1.3	4.5	107.3	104.6	104.6	0.0	0.0	2.0	2.0	1.9	1.9	0.1	2.9	N/F	N/F	N/F	N/F	N/F	N/F
Second	R14	W22	Living Room	15.2	13.3	2.0	12.9						0.2		0.2				3	0	2	0	0.7	0.0
		W23-L		14.7	12.6	2.1	14.1						0.0		0.0				3	0	2	0	0.7	0.0
		W23-U											0.0		0.0									
		W24		33.6	31.9	1.7	5.1	157.9	156.7	156.5	0.2	0.1	1.8	2.0	1.7	1.9	0.1	4.8	N/F	N/F	N/F	N/F	N/F	N/F
Second	R15	W25	Living Room	27.0	26.4	0.6	2.2						1.3		1.3				N/F	N/F	N/F	N/F	N/F	N/F
		W26		24.1	22.8	1.2	5.1						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W27-L		23.6	22.4	1.3	5.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W27-U						175.8	173.5	173.5	0.0	0.0	0.0	1.6	0.0	1.5	0.0	1.6						
Second	R16	W28	Bedroom	35.5	34.2	1.3	3.6	129.1	128.3	128.3	0.0	0.0	2.3	2.3	2.2	2.2	0.1	3.2	N/F	N/F	N/F	N/F	N/F	N/F
Third	R3	W03	Bedroom	38.1	33.3	4.9	12.8	129.1	128.4	128.4	0.0	0.0	2.5	2.5	2.2	2.2	0.3	11.9	N/F	N/F	N/F	N/F	N/F	N/F
Third	R4	W04	Living Room	26.6	24.4	2.3	8.5						0.3		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W05-L		26.0	23.5	2.5	9.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											0.0		0.0									
		W06-L		30.3	26.5	3.8	12.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						175.8	173.9	173.9	0.0	0.0	1.4	1.7	1.2	1.5	0.1	8.8						
Third	R5	W07	Living Room	34.0	30.5	3.6	10.4						1.7		1.6				N/F	N/F	N/F	N/F	N/F	N/F
		W08		18.6	18.6	0.0	0.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W09-L		16.4	16.4	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						157.9	156.8	156.8	0.0	0.0	0.0	2.0	0.0	1.8	0.1	7.6						
Third	R6	W10-L	Bedroom	31.8	28.8	3.0	9.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						107.3	105.5	105.5	0.0	0.0	2.1	2.1	2.0	2.0	0.2	7.2						
Third	R8	W12-L	Bedroom	31.8	29.6	2.2	6.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U						107.3	105.4	105.4	0.0	0.0	2.1	2.1	2.0	2.0	0.1	5.2						
Third	R9	W13	Living Room	19.2	17.0	2.2	11.5						0.2		0.2				4	0	3	0	0.8	0.0
		W14-L		17.1	14.8	2.4	13.8						0.0		0.0				3	0	2	0	0.7	0.0
		W14-U											0.0		0.0									
		W15		35.3	32.7	2.6	7.3	157.9	156.7	156.6	0.0	0.0	1.8	2.0	1.7	1.9	0.1	6.4	N/F	N/F	N/F	N/F	N/F	N/F

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Third	R10	W16	Living Room	35.1	32.9	2.3	6.4						1.8		1.7				N/F	N/F	N/F	N/F	N/F	N/F
		W17		18.8	18.8	0.0	0.0						0.2		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W18-L		16.7	16.7	0.0	0.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						157.9	156.8	156.8	0.0	0.0	0.0	2.0	0.0	1.9	0.1	5.0						
Third	R11	W19-L	Bedroom	31.4	29.8	1.6	5.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						107.3	105.5	105.5	0.0	0.0	2.1	2.1	2.0	2.0	0.1	4.0						
Third	R13	W21-L	Bedroom	31.2	30.2	1.0	3.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W21-U						107.3	105.7	105.7	0.0	0.0	2.1	2.1	2.0	2.0	0.0	2.3						
Third	R14	W22	Living Room	19.1	17.4	1.7	8.8						0.2		0.2				4	0	3	0	0.8	0.0
		W23-L		17.0	15.2	1.8	10.5						0.0		0.0				3	0	2	0	0.7	0.0
		W23-U											0.0		0.0									
		W24		33.0	31.6	1.4	4.3	157.9	156.8	156.6	0.2	0.1	1.7	1.9	1.6	1.9	0.1	4.0	N/F	N/F	N/F	N/F	N/F	N/F
Third	R15	W25-L	Living Room	29.1	28.7	0.5	1.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W25-U											1.3		1.3									
		W26		25.7	24.7	1.0	4.0						0.3		0.2				N/F	N/F	N/F	N/F	N/F	N/F
		W27-L		24.9	23.8	1.1	4.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W27-U						175.8	173.6	173.6	0.0	0.0	0.0	1.6	0.0	1.6	0.0	1.3						
Third	R16	W28	Bedroom	36.8	35.7	1.1	2.9	129.1	128.3	128.3	0.0	0.0	2.4	2.4	2.3	2.3	0.1	2.8	N/F	N/F	N/F	N/F	N/F	N/F
Churchill Court																								
Ground	R1	W01-L	Bedroom	22.5	20.9	1.6	7.1						0.1		0.1				63	10	59	9	0.9	0.9
		W01-U											0.9		0.9									
		W02-L		30.7	25.0	5.6	18.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.3		0.3									
		W03-L		29.8	24.3	5.5	18.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.4		0.4									
		W04-L		28.7	23.4	5.4	18.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						208.7	202.1	155.3	46.8	23.2	0.3	2.2	0.3	2.0	0.2	9.6						
Ground	R2	W05-L	Bedroom	18.4	15.9	2.5	13.4						0.0		0.0				40	10	36	9	0.9	0.9
		W05-U											0.5		0.5									
		W06-L		31.7	26.6	5.1	16.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.1		0.9									
		W07-L		31.3	26.7	4.7	14.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						145.6	144.7	134.9	9.8	6.8	1.1	2.8	1.0	2.5	0.3	11.2						
Ground	R3	W08-L	Unknown	22.9	20.3	2.6	11.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.4		0.3									
		W09-L		26.8	23.5	3.3	12.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											0.6		0.6									
		W10-L		28.4	25.0	3.4	11.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						153.0	141.7	98.6	43.2	30.5	0.4	1.5	0.4	1.4	0.1	8.5						


Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Ground	R4	W11-L	Unknown	29.5	26.7	2.9	9.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U						153.0	127.8	101.4	26.4	20.6	1.1	1.1	1.0	1.1	0.1	7.4						
Ground	R5	W12-L	Unknown	27.6	25.3	2.3	8.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											0.4		0.4									
		W13-L		26.0	23.8	2.1	8.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.6		0.5									
		W14-L		22.4	20.4	2.0	9.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						153.0	126.9	120.0	6.9	5.5	0.3	1.4	0.3	1.3	0.1	5.8						
Ground	R6	W15-L	Bedroom	29.2	27.6	1.6	5.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											1.0		1.0									
		W16-L		29.3	27.7	1.5	5.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						145.3	141.1	139.3	1.8	1.2	1.0	2.1	1.0	2.0	0.1	4.2						
Ground	R7	W17-L	Bedroom	22.6	21.8	0.8	3.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											0.4		0.4									
		W18-L		25.4	24.1	1.3	5.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U											0.6		0.5									
		W19-L		27.1	25.5	1.6	5.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						125.2	117.8	117.8	0.0	0.0	0.4	1.5	0.4	1.4	0.1	3.8						
Ground	R8	W20-L	LKD	25.1	25.0	0.1	0.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U											0.3		0.3									
		W21-L		31.8	31.8	0.0	0.0						0.0		0.0				34	8	34	8	1.0	1.0
		W21-U											0.3		0.3									
		W22-L		31.3	31.3	0.0	0.0						0.0		0.0				31	7	31	7	1.0	1.0
		W22-U											0.4		0.4									
		W23-L		29.5	29.5	0.0	0.0						0.0		0.0				27	5	27	5	1.0	1.0
		W23-U											0.3		0.3									
		W24-L		26.0	26.0	0.0	0.0						0.0		0.0				17	1	17	1	1.0	1.0
		W24-U						286.9	281.1	281.1	0.0	0.0	0.2	1.6	0.2	1.6	0.0	0.0						
Ground	R9	W25-L	Unknown	24.6	23.8	0.8	3.3						0.1		0.1				66	13	63	12	1.0	0.9
		W25-U						270.0	208.4	206.8	1.5	0.7	0.8	0.9	0.8	0.9	0.0	2.0						
First	R1	W01-L	Bedroom	27.3	26.1	1.2	4.4						0.1		0.1				70	13	67	12	1.0	0.9
		W01-U											1.0		1.0									
		W02-L		33.1	28.0	5.1	15.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.4		0.3									
		W03-L		32.2	27.2	5.0	15.6						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.5		0.4									
		W04-L		31.0	26.1	4.9	15.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						208.7	204.6	190.0	14.6	7.1	0.4	2.4	0.3	2.2	0.2	7.7						
First	R2	W05-L	Bedroom	19.8	17.9	1.9	9.6						0.0		0.0				42	11	39	10	0.9	0.9
		W05-U											0.5		0.5									

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W06-L		33.9	29.2	4.7	13.9						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U											1.1		1.0									
		W07-L		33.7	29.3	4.4	13.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U						145.3	144.4	144.4	0.0	0.0	1.2	3.0	1.0	2.7	0.3	9.9						
First	R3	W08-L	Unknown	25.3	22.5	2.9	11.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.4		0.4									
		W09-L		29.4	26.1	3.3	11.2						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U											0.6		0.6									
		W10-L		31.1	27.7	3.4	10.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						153.0	150.0	116.9	33.1	22.1	0.4	1.5	0.4	1.4	0.1	8.3						
First	R4	W11-L	Unknown	32.2	29.2	3.0	9.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U						153.0	149.7	125.5	24.2	16.2	1.2	1.2	1.1	1.2	0.1	7.5						
First	R5	W12-L	Unknown	30.5	27.9	2.6	8.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											0.4		0.4									
		W13-L		28.9	26.3	2.5	8.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U											0.6		0.6									
		W14-L		24.9	22.4	2.5	9.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U						153.0	149.6	133.0	16.6	11.1	0.3	1.4	0.3	1.4	0.1	6.6						
First	R6	W15-L	Bedroom	32.3	30.1	2.2	6.8						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U											1.1		1.0									
		W16-L		32.3	30.2	2.1	6.6						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U						145.3	144.4	144.3	0.0	0.0	1.1	2.4	1.0	2.2	0.1	5.6						
First	R7	W17-L	Bedroom	25.4	23.9	1.5	6.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											0.4		0.4									
		W18-L		28.4	26.5	1.9	6.7						0.1		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U											0.6		0.6									
		W19-L		30.2	28.1	2.1	6.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U						125.2	118.4	118.4	0.0	0.0	0.4	1.6	0.4	1.5	0.1	5.1						
First	R8	W20-L	LKD	28.9	28.8	0.1	0.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W20-U											0.3		0.3									
		W21-L		33.9	33.9	0.0	0.0						0.0		0.0				37	9	37	9	1.0	1.0
		W21-U											0.3		0.3									
		W22-L		33.3	33.3	0.0	0.0						0.0		0.0				34	8	34	8	1.0	1.0
		W22-U											0.4		0.4									
		W23-L		31.4	31.4	0.0	0.0						0.0		0.0				28	5	28	5	1.0	1.0
		W23-U											0.4		0.4									
		W24-L		27.7	27.7	0.0	0.0						0.0		0.0				18	1	18	1	1.0	1.0
		W24-U						286.9	282.9	282.9	0.0	0.0	0.2	1.7	0.2	1.7	0.0	0.0						
First	R9	W25-L	Unknown	29.3	28.7	0.6	2.0						0.1		0.1				73	16	71	15	1.0	0.9
		W25-U						270.0	222.8	222.5	0.3	0.1	0.9	1.0	0.9	1.0	0.0	1.3						

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Second	R1	W01-L	Bedroom	33.3	32.6	0.8	2.3						0.1		0.1				81	24	81	24	1.0	1.0
		W01-U											1.2		1.2									
		W02-L		35.5	31.2	4.3	12.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.4		0.3									
		W03-L		34.7	30.4	4.2	12.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U											0.5		0.4									
		W04-L		33.5	29.3	4.2	12.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W04-U						208.7	206.4	206.4	0.0	0.0	0.4	2.6	0.3	2.5	0.2	5.8						
Second	R2	W05-L	Bedroom	36.3	32.2	4.1	11.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W05-U											1.2		1.1									
		W06-L		36.2	32.2	4.0	11.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W06-U						145.3	144.4	144.4	0.0	0.0	1.2	2.5	1.1	2.2	0.2	9.9						
Second	R3	W07-L	Unknown	27.9	24.8	3.1	11.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											0.4		0.4									
		W08-L		32.3	29.0	3.3	10.3						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.7		0.6									
		W09-L		34.1	30.7	3.4	10.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						153.0	149.9	148.6	1.3	0.9	0.4	1.7	0.4	1.5	0.1	8.2						
Second	R4	W10-L	Unknown	35.5	32.4	3.2	8.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W10-U						153.0	149.7	149.7	0.0	0.0	1.2	1.3	1.1	1.2	0.1	7.8						
Second	R5	W11-L	Unknown	33.8	30.9	3.0	8.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W11-U											0.4		0.4									
		W12-L		32.1	29.1	2.9	9.1						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W12-U											0.7		0.6									
		W13-L		27.6	24.7	2.9	10.4						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W13-U						153.0	149.5	149.5	0.0	0.0	0.4	1.6	0.3	1.5	0.1	7.4						
Second	R6	W14-L	Bedroom	35.8	32.8	2.9	8.2						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W14-U											1.2		1.1									
		W15-L		35.8	32.9	2.9	8.1						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W15-U						145.3	144.4	144.4	0.0	0.0	1.2	2.5	1.1	2.3	0.2	7.2						
Second	R7	W16-L	Bedroom	28.7	26.5	2.2	7.7						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W16-U											0.4		0.4									
		W17-L		31.9	29.4	2.4	7.7						0.1		0.1				N/F	N/F	N/F	N/F	N/F	N/F
		W17-U											0.7		0.7									
		W18-L		33.5	31.0	2.5	7.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W18-U						125.2	118.9	118.9	0.0	0.0	0.5	1.8	0.5	1.7	0.1	6.2						
Second	R8	W19-L	LKD	34.1	34.0	0.1	0.3						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W19-U											0.4		0.4									
		W20-L		35.9	35.9	0.0	0.0						0.0		0.0				39	9	39	9	1.0	1.0
		W20-U											0.3		0.3									
		W21-L		35.1	35.1	0.0	0.0						0.0		0.0				36	9	36	9	1.0	1.0

Address	Room	Window	Room Use	Existing VSC	Proposed VSC	Loss	Loss %	Room Area	Existing NSC	Proposed NSC	Loss	Loss %	Existing ADF Window	Existing ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Existing APSH Total	Existing APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
		W21-U											0.4		0.4									
		W22-L		33.0	33.0	0.0	0.0						0.0		0.0				30	6	30	6	1.0	1.0
		W22-U											0.4		0.4									
		W23-L		29.2	29.2	0.0	0.0						0.0		0.0				20	2	20	2	1.0	1.0
		W23-U						286.9	285.2	285.2	0.0	0.0	0.2	1.8	0.2	1.8	0.0	0.0						
Second	R9	W24-L	Unknown	34.6	34.2	0.4	1.0						0.1		0.1				81	24	81	24	1.0	1.0
		W24-U						270.0	259.1	259.1	0.1	0.0	1.1	1.2	1.1	1.2	0.0	0.7						
Third	R1	W01-L	Unknown	37.2	34.0	3.2	8.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W01-U											0.4		0.3									
		W02-L		37.3	34.1	3.2	8.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W02-U											0.6		0.6									
		W03-L		37.3	34.2	3.2	8.5						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W03-U						178.9	175.5	175.5	0.0	0.0	0.4	1.4	0.4	1.3	0.1	7.0						
Third	R2	W04	Unknown	36.7	33.7	3.0	8.2	153.0	149.2	149.2	0.0	0.0	1.0	1.0	1.0	1.0	0.1	7.4	N/F	N/F	N/F	N/F	N/F	N/F
Third	R3	W05	Unknown	36.7	33.9	2.9	7.8	153.0	149.4	149.4	0.0	0.0	1.0	1.0	1.0	1.0	0.1	7.1	N/F	N/F	N/F	N/F	N/F	N/F
Third	R4	W06	Unknown	36.7	33.8	2.9	7.8	153.0	148.9	148.9	0.0	0.0	1.0	1.0	1.0	1.0	0.1	7.1	N/F	N/F	N/F	N/F	N/F	N/F
Third	R5	W07-L	Unknown	37.5	34.5	3.0	8.0						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W07-U											0.3		0.3									
		W08-L		37.5	34.5	3.0	7.9						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W08-U											0.6		0.5									
		W09-L		37.4	34.5	2.9	7.8						0.0		0.0				N/F	N/F	N/F	N/F	N/F	N/F
		W09-U						178.9	175.4	175.4	0.0	0.0	0.4	1.4	0.3	1.3	0.1	6.7						

Detailed Mirror Baseline Results of the Daylight and Sunlight Analysis (Boat Race House only)



eb7 © copyright 2020

4th Floor, Holborn Tower
137-144 High Holborn
London WC1V 6PL
T: +44(0)20 7148 6290
E: info@eb7.co.uk
W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

Key:

Mirrored

NORTH

Project	The Stag Brewery SW14 7ET London
Title	Mirrored baseline Plan View

Drawn	DB	Checked	--
Date	02/05/2019	Project	2201

Rel no.	Prefix	Page no.
01	DS03	01



eb7 © copyright 2020

4th Floor, Holborn Tower
137-144 High Holborn
London WC1V 6PL
T: +44(0)20 7148 6290
E: info@eb7.co.uk
W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

Key:

Mirrored

Notes:
All heights and dimensions are in AOD

Project	The Stag Brewery SW14 7ET London
Title	Mirrored baseline 3D View

Drawn	DB	Checked	--
Date	02/05/2019	Project	2201
Rel no.	01	Prefix	DS03
Page no.	02		

Address	Room	Window	Room Use	Mirror VSC	Proposed VSC	Loss	Loss %	Room Area	Mirror NSC	Proposed NSC	Loss	Loss %	Mirror ADF Window	Mirror ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Mirror APSH Total	Mirror APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Boatrace House																								
First	R1	W01-L	LKD	0.8	0.8	0.0	0.0						0.0		0.0				N/A	N/A	N/F	N/F	N/A	N/A
		W01-U											0.1		0.1									
	R1	W02-L		1.2	1.2	0.0	0.0						0.0		0.0				N/A	N/A	N/F	N/F	N/A	N/A
		W02-U											0.1		0.1									
	R1	W03-L		33.7	33.6	0.0	0.1						0.0		0.0				82	24	82	24	1.0	1.0
		W03-U											0.4		0.4									
	R1	W04-L		33.4	33.4	0.1	0.2						0.0		0.0				81	23	81	23	1.0	1.0
		W04-U											0.4		0.4									
	R1	W05-L		33.2	33.2	0.1	0.2						0.0		0.0				81	23	81	23	1.0	1.0
		W05-U						500.2	455.5	455.5	0.0	0.0	0.4	1.5	0.4	1.5	0.0	0.0						
First	R2	W06-L	Bedroom	32.1	32.0	0.0	0.1						0.0		0.0				72	22	72	22	1.0	1.0
		W06-U						165.8	110.9	110.9	0.0	0.0	0.6	0.6	0.6	0.6	0.0	0.0						
First	R3	W07-L	Bedroom	32.4	32.3	0.0	0.1						0.0		0.0				79	23	79	23	1.0	1.0
		W07-U						158.8	111.9	111.7	0.1	0.1	0.6	0.6	0.6	0.6	0.0	0.0						
First	R4	W08	Bedroom	31.6	31.6	0.0	0.1						0.8		0.8				78	25	78	25	1.0	1.0
	R4	W09		31.6	31.6	0.0	0.0	145.3	144.3	144.3	0.0	0.0	0.8	1.6	0.8	1.6	0.0	0.0	81	25	81	25	1.0	1.0
First	R5	W10	LKD	31.6	31.6	0.0	0.1						0.6		0.6				78	24	78	24	1.0	1.0
	R5	W11		31.6	31.6	0.0	0.1						0.6		0.6				79	23	79	23	1.0	1.0
	R5	W12		31.6	31.6	0.0	0.1						0.5		0.5				77	24	77	24	1.0	1.0
	R5	W13		31.7	31.7	0.0	0.1	227.2	225.9	226.0	-0.1	0.0	0.5	2.2	0.5	2.2	0.0	0.0	80	24	80	24	1.0	1.0
First	R6	W14	Bedroom	31.7	31.7	0.0	0.2						0.5		0.5				79	25	79	25	1.0	1.0
	R6	W15		31.8	31.7	0.0	0.1						0.5		0.5				81	25	81	25	1.0	1.0
	R6	W16		27.5	23.8	3.7	13.5						0.6		0.6				N/A	N/A	N/F	N/F	N/A	N/A
	R6	W17		10.4	7.5	2.9	28.0	197.4	176.4	165.0	11.4	6.5	0.1	1.7	0.1	1.6	0.1	4.4	10	0	8	0	0.8	0.0
First	R7	W18-L	Bedroom	19.1	15.6	3.5	18.1						0.1		0.1				37	13	33	12	0.9	0.9
		W18-U						164.8	121.3	100.3	20.9	17.3	1.0	1.0	0.8	0.9	0.1	13.9						
First	R8	W19-L	LKD	16.2	14.3	1.9	11.7						0.0		0.0				29	11	25	9	0.9	0.8
		W19-U						449.7	58.6	46.3	12.3	21.0	0.4	0.4	0.3	0.4	0.0	9.7						
First	R9	W20-L	Bedroom	15.4	14.9	0.6	3.7						0.1		0.1				25	9	22	8	0.9	0.9
		W20-U						228.5	69.0	91.6	-22.6	-32.7	0.6	0.7	0.6	0.6	0.0	4.3						
First	R10	W21-L	Bedroom	17.1	17.2	-0.2	-0.9						0.1		0.1				25	8	23	8	0.9	1.0
		W21-U						184.9	72.7	84.0	-11.3	-15.5	0.8	0.8	0.8	0.8	0.0	1.1						
First	R11	W22-L	LKD	21.9	21.0	0.8	3.8						0.0		0.0				22	6	19	7	0.9	1.2
		W22-U											0.3		0.3									
	R11	W23-L		38.9	38.4	0.5	1.4						0.1		0.1				N/A	N/A	N/F	N/F	N/A	N/A
		W23-U						367.4	233.4	226.9	6.5	2.8	0.8	1.3	0.8	1.3	0.0	1.8						

Address	Room	Window	Room Use	Mirror VSC	Proposed VSC	Loss	Loss %	Room Area	Mirror NSC	Proposed NSC	Loss	Loss %	Mirror ADF Window	Mirror ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Mirror APSH Total	Mirror APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Second	R1	W01	Bedroom	29.8	29.8	0.0	0.0						1.0		1.0				N/A	N/A	N/F	N/F	N/A	N/A
	R1	W02-L		33.6	33.6	0.0	0.1						0.1		0.1				84	28	84	28	1.0	1.0
		W02-U						253.6	251.8	251.8	0.0	0.0	1.0	2.0	1.0	2.0	0.0	0.0						
Second	R2	W03-L	Bedroom	34.2	34.1	0.0	0.1						0.1		0.1				84	28	84	28	1.0	1.0
		W03-U						242.1	236.0	236.1	-0.1	0.0	1.1	1.2	1.1	1.2	0.0	0.0						
Second	R4	W05-L	Bedroom	34.4	34.2	0.2	0.5						0.2		0.2				86	29	86	29	1.0	1.0
		W05-U						134.9	132.8	132.8	0.0	0.0	1.7	1.9	1.7	1.9	0.0	0.1						
Second	R5	W06-L	LKD	34.7	34.4	0.3	1.0						0.1		0.1				86	29	82	27	1.0	0.9
		W06-U											0.9		0.9									
	R5	W07-L		24.3	19.3	5.0	20.4						0.1		0.1				40	15	35	13	0.9	0.9
		W07-U						348.2	336.7	336.2	0.5	0.1	0.6	1.6	0.5	1.5	0.1	6.5						
Second	R6	W08-L	Bedroom	22.3	17.9	4.3	19.4						0.1		0.1				33	11	28	9	0.8	0.8
		W08-U						233.4	70.3	46.2	24.1	34.3	0.7	0.8	0.6	0.7	0.1	14.1						
Second	R7	W09-L	Bedroom	21.3	17.7	3.6	17.0						0.1		0.1				30	9	24	7	0.8	0.8
		W09-U						185.3	87.9	80.4	7.5	8.5	0.8	0.9	0.7	0.8	0.1	12.5						
Second	R8	W10-L	Bedroom	22.5	19.6	2.9	12.7						0.1		0.1				29	8	23	8	0.8	1.0
		W10-U						167.4	84.8	86.7	-1.9	-2.2	0.9	1.0	0.8	0.9	0.1	9.7						
Second	R9	W11-L	LKD	38.5	38.0	0.5	1.2						0.1		0.1				N/A	N/A	N/F	N/F	N/A	N/A
		W11-U											0.8		0.8									
	R9	W12-L		38.8	38.2	0.5	1.4						0.1		0.1				N/A	N/A	N/F	N/F	N/A	N/A
		W12-U						367.5	300.2	300.2	0.0	0.0	0.8	1.7	0.8	1.7	0.0	1.0						
Third	R1	W01	Bedroom	26.4	26.4	0.0	0.0						0.8		0.8				N/A	N/A	N/F	N/F	N/A	N/A
	R1	W02-L		32.4	32.4	0.0	0.1						0.1		0.1				79	30	79	30	1.0	1.0
		W02-U						257.0	254.8	254.8	0.0	0.0	0.9	1.8	0.9	1.8	0.0	0.0						
Third	R2	W03-L	Bedroom	32.1	32.1	0.0	0.1						0.1		0.1				77	30	77	30	1.0	1.0
		W03-U						221.8	218.4	218.1	0.3	0.2	1.0	1.1	1.0	1.1	0.0	0.0						
Third	R4	W05-L	Bedroom	31.6	31.5	0.1	0.3						0.1		0.1				76	29	76	29	1.0	1.0
		W05-U						157.6	138.5	138.4	0.2	0.1	1.2	1.4	1.2	1.4	0.0	0.1						
Third	R5	W06-L	LKD	31.6	31.4	0.2	0.7						0.1		0.1				77	29	75	27	1.0	0.9
		W06-U											0.7		0.7									
	R5	W07-L		27.6	22.6	5.0	18.2						0.1		0.1				35	13	29	11	0.8	0.8
		W07-U						347.6	336.5	335.0	1.6	0.5	0.7	1.6	0.6	1.5	0.1	6.8						
Third	R6	W08-L	Bedroom	26.4	21.2	5.2	19.7						0.1		0.1				32	10	26	10	0.8	1.0
		W08-U						186.0	135.3	81.8	53.5	39.6	1.0	1.1	0.9	1.0	0.1	8.8						

Address	Room	Window	Room Use	Mirror VSC	Proposed VSC	Loss	Loss %	Room Area	Mirror NSC	Proposed NSC	Loss	Loss %	Mirror ADF Window	Mirror ADF Total	Proposed ADF Window	Proposed ADF Total	Loss	Loss %	Mirror APSH Total	Mirror APSH Winter	Proposed APSH Total	Proposed APSH Winter	Total Retained	Winter Retained
Third	R7	W09-L	Bedroom	25.0	20.1	4.9	19.5						0.1		0.1				31	10	23	8	0.7	0.8
		W09-U						178.1	148.6	99.9	48.7	32.8	0.9	1.0	0.8	0.9	0.1	9.7						
Third	R8	W10-L	Bedroom	25.6	21.2	4.4	17.1						0.1		0.1				30	9	21	6	0.7	0.7
		W10-U						171.7	123.2	102.9	20.4	16.5	1.0	1.1	0.9	1.0	0.1	9.0						
Third	R9	W11-L	LKD	33.7	33.2	0.5	1.3						0.1		0.1				N/A	N/A	N/F	N/F	N/A	N/A
		W11-U											0.7		0.6									
	R9	W12-L		33.5	33.1	0.4	1.1						0.1		0.1				N/A	N/A	N/F	N/F	N/A	N/A
		W12-U						367.2	299.6	299.7	-0.1	0.0	0.6	1.4	0.6	1.4	0.0	0.8						
Fourth	R1	W01-L	Bedroom	24.6	21.9	2.7	11.1						0.1		0.1				26	2	21	1	0.8	0.5
		W01-U						311.0	291.8	198.4	93.5	32.0	0.8	0.8	0.7	0.8	0.1	7.5						
Fourth	R2	W02-L	Bedroom	24.2	21.2	3.1	12.6						0.1		0.1				27	1	21	0	0.8	0.0
		W02-U						214.5	195.4	195.2	0.2	0.1	1.1	1.2	1.0	1.1	0.1	8.3						
Fourth	R3	W03-L	LKD	38.8	38.8	0.0	0.0						0.1		0.1				N/A	N/A	N/F	N/F	N/A	N/A
		W03-U						730.8	713.9	713.9	0.0	0.0	1.6	1.7	1.6	1.7	0.0	0.3						

Appendix 18.3

Results of the Overshadowing (Sunlight Amenity) Analysis



Fig. 1: BRE's Sun-on-Ground 21mar

YES

NO

BRE's Sun-on-ground
Area seing at least two hours of sunlight

Day: 21st March
Latitude: 51.4°N
Effective day length: 10 hours
*Min solar angle 10°
(BR209 3.3.8)

NORTH



Fig. 2: BRE's Sun-on-Ground 21mar

Zone Name	Area (m2)	Sunlit Area* Existing [%]	Proposed [%]	Loss [%]
11 Watney Road	146.5	47.4	47.4	0.0
13 Watney Road	124.2	66.1	66.1	0.0
15 Watney Road	124.7	52.4	52.4	0.0
17 Watney Road	112.0	39.7	39.7	0.0
19 Watney Road	126.2	49.2	49.2	0.0
21 Watney Road	125.5	43.2	43.2	0.0
23 Watney Road	126.7	54.8	54.8	0.0
25 Watney Road	128.8	41.7	41.7	0.0
27 Watney Road	121.1	51.6	51.6	0.0
29 Watney Road	127.0	40.2	40.2	0.0
31 Watney Road	129.7	42.8	42.8	0.0
33 Watney Road	125.2	50.9	50.9	0.0
35 Watney Road	134.1	53.9	53.9	0.0
37 Watney Road	124.4	41.0	41.0	0.0
39 Watney Road	133.3	56.7	56.7	0.0
41 Watney Road	130.7	38.6	38.6	0.0
43 Watney Road	128.2	35.2	35.2	0.0
45 Watney Road	134.6	49.9	49.9	0.0
47 Watney Road	159.5	68.5	68.5	0.0
49 Watney Road	163.0	61.8	61.8	0.0
51 Watney Road	164.7	49.6	49.6	0.0
53 Watney Road	163.4	64.4	64.4	0.0
55 Watney Road	144.8	65.7	65.7	0.0
57 Watney Road	126.3	69.1	69.1	0.0
59 Watney Road	102.1	63.2	63.2	0.0
61 Watney Road	111.6	77.4	77.4	0.0
1,2,3 Parliament Mews	91.0	69.2	69.2	0.0
4 Parliament Mews	63.5	68.1	68.1	0.0
5 Parliament Mews	65.3	68.4	68.4	0.0
6 Parliament Mews	49.5	47.0	45.6	3.0
7 Parliament Mews	50.0	46.6	43.7	6.2
8 Parliament Mews	46.5	46.0	43.5	5.4
9 Parliament Mews	45.7	43.3	41.7	3.8
10 Parliament Mews	48.1	46.4	45.5	2.0
11 Parliament Mews	46.7	22.0	22.0	0.0
Aspin Cottage	290.9	75.2	74.3	1.2
Leyden House	886.3	95.5	93.7	1.8
Reid-Court-1	99.5	99.5	100.0	-0.5
Reid-Court-2	160.5	87.3	83.5	4.3
Reid-Court-3	70.2	71.2	68.3	4.1
Reid-Court-4	54.9	100.0	100.0	0.0
Reid-Court-5	160.4	100.0	100.0	0.0
Reid-Court-6	80.2	95.4	95.4	0.0
Thames Bank House	801.4	90.3	80.5	10.9
Towpath	6,388.8	85.8	89.5	-4.3
Tudor Lodge	222.1	83.4	83.4	0.0
MortlakeGreen	14,240.6	99.8	99.8	0.0

*Sunlit Area = Area receiving at least 2hrs. of sunlight on 21st March

Table 1: Results

YES
NO

BRE's Sun-on-ground
Area seing at least two hours of sunlight

Day: 21st March
Latitude: 51.4°N
Effective day length: 10 hours
*Min solar angle 10°
(BR209 3.3.8)

NORTH




Fig. 1: BRE's Sun-on-Ground

Zone Name	Area (m2)	Sunlit Area* [%]
1	1,698.8	37.2
2	391.5	95.9
3	1,070.6	71.8
4	1,610.6	45.5
5	981.3	100.0
6	805.2	40.1
7	486.6	3.6
8	853.4	34.0
9	523.2	51.9
10	1,159.4	12.4
11	2,243.9	84.4
12	1,005.9	84.0
13	602.7	61.1
14	1,001.3	20.3
15	1,644.1	65.8
16	820.6	69.2
17	2,050.5	43.2
18	2,793.8	70.4
19	17,911.1	100.0
20	943.4	34.6

*Sunlit Area = Area receiving at least 2hrs. of sunlight on 21st March

Table 1: Results



Fig. 2: Sunlight Exposure



Fig. 3: BRE’s Sun-on-Ground

Zone Name	Area (m2)	Sunlit Area* [%]
1	1,698.8	95.3
2	391.5	100.0
3	1,070.6	97.4
4	1,610.6	96.5
5	981.3	100.0
6	805.2	99.2
7	486.6	64.2
8	853.4	93.9
9	523.2	87.5
10	1,159.4	72.5
11	2,243.9	99.9
12	1,005.9	100.0
13	602.7	99.9
14	1,001.3	97.0
15	1,644.1	99.9
16	820.6	96.8
17	2,050.5	97.3
18	2,793.8	96.3
19	17,911.1	100.0
20	943.4	96.4

*Sunlit Area = Area receiving at least 2hrs. of sunlight on 21st June

Table 2: Results




Fig. 4: Sunlight Exposure

Appendix 18.4


Transient Overshadowing Images

Existing Scenario

Proposed Scenario



8:00



Existing


Proposed

NORTH

Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)




9:00





10:00




21st March (equinox)
Hourly Shadows

Existing Scenario

Proposed Scenario






11:00





12:00





13:00

Existing

Proposed

NORTH


Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)

21st March (equinox)
Hourly Shadows

Existing Scenario


Proposed Scenario







14:00





15:00





16:00

Existing


Proposed

NORTH


Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)

21st March (equinox)
Hourly Shadows

Existing Scenario



Proposed Scenario



17:00

Existing

Proposed


NORTH

Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)

21st March (equinox)
Hourly Shadows


Existing Scenario


Proposed Scenario






6:00





7:00





8:00

Existing

Proposed

NORTH

Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)


21st June (summer solstice)

Hourly Shadows

Existing Scenario

Proposed Scenario






9:00





10:00





11:00

Existing

Proposed

NORTH

Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)


21st June (summer solstice)

Hourly Shadows

Existing Scenario

Proposed Scenario






12:00





13:00





14:00

Existing

Proposed

NORTH


Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)

21st June (summer solstice)
Hourly Shadows

Existing Scenario

Proposed Scenario







15:00





16:00





17:00

Existing

Proposed


NORTH

Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)


21st June (summer solstice)

Hourly Shadows

Existing Scenario



Proposed Scenario



18:00

Existing

Proposed


NORTH


Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)

21st June (summer solstice)
Hourly Shadows


Existing Scenario


Proposed Scenario







10:00





11:00





12:00

Existing

Proposed

NORTH


Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)


21st December (winter solstice)

Hourly Shadows


Existing Scenario


Proposed Scenario





13:00





14:00

Existing

Proposed


NORTH



Latitude: 51.4N
Min. solar altitude 10 degrees
(BR209 3.3.8)

Appendix 18.5

Light Pollution



eb7 © copyright 2020

Studio 1, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey


NORTH

Project: The Stag Brewery
SW14 7ET

Title: Existing Light Levels

Drawn	DB	Checked	--
Date	14/02/2018	Rel no.	01

Drawing no. 2201-LP01



eb7 © copyright 2020

Studio 1, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

NORTH


Project: The Stag Brewery
SW14 7ET

Title: Light Spill Grid (lux)
(Class III FA Standard)

Drawn	DB	Checked	--
Date	14/02/2018	Rel no.	01

Drawing no. 2201-LP02





eb7 © copyright 2020

Studio 1, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey


NORTH

Project: The Stag Brewery
SW14 7ET

Title: Light Spill Grid (lux)
(Class II)

Drawn	DB	Checked	--
Date	14/02/2018	Rel no.	01

Drawing no. 2201-LP03



(-73.29, -68.50, 6.00) C-----D (-79.88, 30.44, 6.00)
(-73.29, -68.50, 1.50) A-----B (-79.88, 30.44, 1.50)

G : BVP525 OUT T15 100K A-VWB/30
Z : BVP515 OUT T15 100K A-WB/30 +LO
N : BVP651 T25 DW10 BL1
b : BVP515 OUT T15 100K A-NB/30 +LO

Average	Minimum	Maximum	Min/Ave	Min/Max	Project maintenance factor	Scale
0.17	0.10	0.24	0.61	0.43	1.00	1:750

eb7 © copyright 2020

Studio 1, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

NORTH


Project: The Stag Brewery
SW14 7ET

Title: Light Spill on facades of houses to the west (lux) (Class III FA Standard)

Drawn: DB | Checked: --

Date: 14/02/2018 | Rel no.: 01

Drawing no.: 2201-LP04



(-43.90, 70.10, 6.00) C-----D (-23.54, 78.45, 6.00)
(-43.90, 70.10, 1.50) A-----B (-23.54, 78.45, 1.50)

G BVP525 OUT T15 100K A-VWB/ N BVP651 T25 DW10 BL1
Z BVP515 OUT T15 100K A-WB/3 b BVP515 OUT T15 100K A-NB/30

Average	Minimum	Maximum	Min/Ave	Min/Max	CV	Project maintenance factor	Scale
0.39	0.22	0.75	0.55	0.29	0.281	0.90	1:150

eb7 © copyright 2020

Studio 1, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

NORTH


Project: The Stag Brewery
SW14 7ET

Title: Light Spill on facades of houses to the North West (lux)
(Class III FA Standard)

Drawn: DB Checked: --

Date: 14/02/2018 Rel no.: 01

Drawing no.: 2201-LP05



(-73.29, -68.50, 6.00) C-----D (-79.88, 30.44, 6.00)
| |
(-73.29, -68.50, 1.50) A-----B (-79.88, 30.44, 1.50)

A : BVP525 OUT T15 100K A-WB/30 +LO
B : BVP525 OUT T15 100K A-NB/30 +LO
H : BVP525 OUT T15 100K A-VWB/30
O : BVP651 T25 DW10 BL1

Average	Minimum	Maximum	Min/Ave	Min/Max	Project maintenance factor	Scale
0.25	0.15	0.36	0.61	0.43	1.00	1:750

eb7 © copyright 2020

Studio 1, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

NORTH


Project: The Stag Brewery
SW14 7ET

Title: Light Spill on houses to the west
(lux)
(Class II)

Drawn: DB | Checked: --

Date: 14/02/2018 | Rel no.: 01

Drawing no.: 2201-LP06



(-43.90, 70.10, 6.00) C-----D (-23.54, 78.45, 6.00)
(-43.90, 70.10, 1.50) A-----B (-23.54, 78.45, 1.50)

A	BVP525 OUT T15 100K A-WB/3	B	BVP525 OUT T15 100K A-NB/30
H	BVP525 OUT T15 100K A-VWB/	O	BVP651 T25 DW10 BL1

Average	Minimum	Maximum	Min/Ave	Min/Max	CV	Project maintenance factor	Scale
0.58	0.32	1.13	0.55	0.29	0.281	0.90	1:150

eb7 © copyright 2020

Studio 1, 63 Webber Street
London SE1 0QW
T: +44(0)20 7148 6290
E: info@eb7.co.uk W: eb7.co.uk

Sources of information

See Sources of Information in Appendix 1

EB7 Ltd

Site Photographs
Ordnance Survey

NORTH

Project: The Stag Brewery
SW14 7ET

Title: Light Spill on facade of houses to the north west (lux)
(Class II)

Drawn: DB | Checked: --

Date: 14/02/2018 | Rel no.: 01

Drawing no.: 2201-LP07