



EXAMPLES OF DEGRADATION OF JACK ARCH BEAMS DUE TO WATER INGRESS FROM PARK LEVEL ABOVE - Please see Structural engineers report for description of required remedial works.

**NOTE:**  
REFER TO FLOWMAN CRAVEN SURVEY DRAWINGS:  
15532-010T-01 (A) - 3D Street Survey  
15532-010T-02 (B) - 3D Site Topo  
15532-010T-03 (A) - Boundary Drawing  
15532-010W-02 (A) - Railway Cutting  
15532-013E-03 - North Elevation of Listed Arches  
15532-013E-08 - South Elevation of London Road  
15532-013T-01 (B) - Planimetric Survey  
W15532-010SM - 3D Arch Survey

**FOR DETAIL OF ARCHES REFER TO:**  
KMH HERITAGE STATEMENT & ALAN BAXTER CONDITION SURVEY



Do not scale the drawing  
Do not derive dimensions from digital media

Rev	Date	Revision Notes	Drawn by	Checked	Rev	Date	Revision Notes	Drawn by	Checked	Rev	Date	Revision Notes	Drawn by	Checked					
—	—		—	—	—	—	—	—	—	—	—	—	—	—					
—	—		—	—	—	—	—	—	—	—	—	—	—	—					
—	—		—	—	—	—	—	—	—	—	—	—	—	—					
—	—		—	—	—	—	—	—	—	—	—	—	—	—					
—	—		—	—	—	—	—	—	—	—	—	—	—	—					
—	—		—	—	—	—	—	—	—	—	—	—	—	—					
—	—		—	—	—	—	—	—	—	—	—	—	—	—					
—	—		—	—	—	—	—	—	—	—	—	—	—	—	—				
—	—		—	—	—	—	—	—	—	—	—	—	—	—	—				
—	—		—	—	—	—	—	—	—	—	—	—	—	—	—				
Drawing status:			PLANNING					Job No:		3465		Drawing No:		BGY-FBA-07-XX-DR-A-00_10-7C04		Rev:		P1	
			FOR LISTED BUILDING CONSENT																
Job Title:			The Goodyard										© Drawing & Design Copyright of:						
Drawing Title:			PLOT 7C - EXISTING SECTIONS SHEET 4										<div>FAULKNERBROWNS ARCHITECTS</div> <div></div> <div>FaulknerBrowns LLP Oldson House Northumbrian Way Killingworth Newcastle upon Tyne NE12 5DW T +44 (0) 191 2683007 F +44 (0) 191 2478132</div>						
Date:		April 19		Scale:		1:50@A1		Drawn By:		JK		Checked By:							TL